

TIC-A109E-22-0027

Type:	SBS <input type="checkbox"/> Repetitive
Reference/Number:	ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815 INSPECTION OF
Title/Subject:	SBA109EP-179 REV. /
Version No:	

Linked To:	9M-BOB
Based On:	Not Applicable
Warning:	0
Warning Unit:	Select
Completed:	
Due At:	-
Status:	NOT APPLICABLE

Limitation Notes:	TIC-A109E-22-0027 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. REASON FOR ISSUANCE: THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTIONS ON HOW TO PERFORM AN INSPECTION TO DETECT CRACKS IN THE CENTER FUSELAGE AT THE INTERSECTION OF THE LATERAL PYLON (LH AND RH SIDE) WITH FLOOR SPAR.
-------------------	--