

TIC-AW139-22-0245

PART I

AD/SB ID: 10133 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 91 HARNESS INSTALLATION FORWARD ROOF AREA INSPECTION

Title/Subject: EASA AD 2022-0209-E (SB 139-731 REV/ PART 1)

AD/SB ID: 10133 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Airframe Hours	-	Hours	0	0.00 ↕	3470.47 ↕	TO BE COMPLIED	🗑
	9M-BOD	Airframe Hours	-	Hours	5	0.00 ↕	3523.75 ↕	TO BE COMPLIED	🗑

PART II

AD/SB ID: 10134 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 91 HARNESS INSTALLATION FORWARD ROOF AREA INSPECTION

Title/Subject: EASA AD 2022-0209-E (SB 139-731 REV/ PART 2)

Version No:

AD/SB ID: 10134 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Airframe Hours	-	Hours	5	0.00 ↕	3485.46 ↕	TO BE COMPLIED	🗑
	9M-BOD	Airframe Hours	-	Hours	5	0.00 ↕	3538.75 ↕	TO BE COMPLIED	🗑