

TIC-AW139-22-0184

9M-BOC

AD/SB ID: 10112 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: ATA 34 - INSTALLATION OF DF935-11 DIRECTION FINDING SYSTEM

Title/Subject: SB 139-234 REV. A

AD/SB ID: 10112 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	On Condition	-		0	-	-	OPTIONAL	

9M-BOD

AD/SB ID: 10095 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: ATA 34 - INSTALLATION OF DF935-11 DIRECTION FINDING SYSTEM

Title/Subject: SB 139-234 REV. A

AD/SB ID: 10095 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOD	On Condition	-		0	-	-	OPTIONAL	