

TIC-AW189-23-0046

JBPM/CAMO/AMP/AW189 ISSUE 3, REV 1, TEMPORARY REVISION 1

EASA D 2020-0197 (SB 189-272 Part I) status amended to not applicable as per AMP AW189 Issue 03 Rev 01 TR 01 Chapter 16.0

AD/SB ID: 7563 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOE	Not Applicable	-		0	-	-	NOT APPLICABLE
9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 7563 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 64 - TAIL ROTOR - TAIL ROTOR SERVO ACTUATOR / DUPLEX

Title/Subject: EVERY 10 FH - EASAD NO. 2020-0197 (SB189-272 PART I)

Version No:

AD/SB ID: 7474 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOE	Not Applicable	-		0	-	-	NOT APPLICABLE
9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 7474 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 64 TR FLIGHT CONTROL PERIODICAL INSPECTION FOR IMPROVED DUPLEX BEARING

Title/Subject: AD 2020-0197 / EASB NO. 189-272, NEW ISSUE PART 1

Version No: