

TIC-A109E-23-0043

ENGINE 1

ADI/SB ID: 11146 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS - INSPECTION/REPLACEMENT OF

Title/Subject: SB NO. 28373 NEW ISSUE - ENGINE 1

ADI/SB ID: 11146 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	Not Applicable	-	-	0	-	-	NOT APPLICABLE

ENGINE 2

ADI/SB ID: 11147 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS - INSPECTION/REPLACEMENT OF

Title/Subject: SB NO. 28373 NEW ISSUE - ENGINE 2

ADI/SB ID: 11147 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	Not Applicable	-	-	0	-	-	NOT APPLICABLE