

# TIC-AW139-23-0339

## ENGINE 1

AD/SB ID: 11106 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS-INSPECTION/ REPLACEMENT OF

Title/Subject: PT6C-67C SB NO.41106, NEW ISSUE - ENGINE 1

AD/SB ID: 11106 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	

## ENGINE 2

AD/SB ID: 11107 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS-INSPECTION/ REPLACEMENT OF

Title/Subject: PT6C-67C SB NO.41106, NEW ISSUE - ENGINE 2

AD/SB ID: 11107 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	