TIC-AW139-24-0084

Edit Limitation (A	2 9M-SAAS)			×	
Edit Limitatio	EAD NO.2024-0084-E, NEW ISSUE (EASB 139-783)-ATA 32 -MAIN L	Cancel	📓 Save		
Based C	x Airframe Landings V				
Warnir	y. 50				Rema
08 Warning U	t Landings V			H	0 da
Complete	t 0.00			H	
G AF Due	t 7000.00				36:1
SB State	S TO BE COMPLIED			II.	156 d
B	REFER TIC-AW139-24-0084			H	36:1
P	APPLICABLE DUE TO AIRCRAFT FITTED WITH MAIN SHOCK ABSORBER P/N 3G3210V01031.			U.	
	(PARA.1) WITHIN 100 FLIGHT HOURS (FH) AFTER THE AFFECTED PART ACCUMULATED 7000 LANDINGS AND) THEN. E	EVERY	U.	
Limitation Note	2000 LANDINGS OR 12 MONTHS WHICHEVER OCCURS FIRST.			U.	
E	CYCLES SINCE NEW:			U	187 d
E	i) LH MAIN SA = 1239 LANDING CYCLES ii) RH MAIN SA = 1239 LANDING CYCLES				216:
Acronat Cala	y Aerospace > Modifications >Edit - Personal 3 - Microsoft Edge			_	X
-			_		
	alaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&mode=edit&templates&opener_name=aircraft&templates&opener_name=aircraft&templates&opener_name=aircraft&templates&opener_name=aircraft&templates&opener_name=aircraft&templates&opener_name=aircraft&templates&opener_name				Δ»
AD/SB ID: 11271 Close 🗘 Update 🗟 Save &		e&(Close		
General Co	Tig List Aircraft List Task/Check List Linked To BOM				_
т	De: ADS V Repetitive				
Reference/Number: ATA 32 -MAIN LANDING GEAR SHOCK ABSORBER -INSPECTION 🗔 📮					
Title/Sut	ect: EAD NO.2024-0084-E, NEW ISSUE (EASB 139-783)				
Version					
Reason For Rai					
Reason FOI Rai	ng. 				
	RL:				

Figure 1: TIME LIMIT INITIAL INSPECTION ACCUMULATED 7000 LANDING

Edit Limitation (A/C: 9	IM-SAAS)		×
Edit Limitation E	ASA EAD NO.2024-0084-E, NEW ISSUE-ATA 32 -MAIN LANDING GEA	el 🗟 Se	ave
Based On:	Airframe Landings V		
Period:	2000		
Warning:	50		
Warning Unit:	Landings V		
Last Done/Fitted:	0.00		
Next Due:	0.00		
Limitation Notes:	REFER TIC-AW139-24-0084 APPLICABLE DUE TO AIRCRAFT FITTED WITH MAIN SHOCK ABSORBER P/N 3G3210V01031. (PARA.1) WITHIN 100 FLIGHT HOURS (FH) AFTER THE AFFECTED PART ACCUMULATED 7000 LANDINGS AND THEN, E 2000 LANDINGS OR 12 MONTHS WHICHEVER OCCURS FIRST. CYCLES SINCE NEW: i) LH MAIN SA = 1239 LANDING CYCLES i) PH MAIN SA = 1230 LANDING CYCLES	VERY	
Edit Limitation (A/	(C: 9M-SAAS)	×	

	Edit Limitation E/	ASA EAD NO.2024-0084-E, NEW ISSUE-ATA 32 -MAIN LANDING GEA	ancel 📓	Save		
	Based On:	Date (Months)				
	Period:	12			Re	I
-008	Warning:	3			0	
-008	Warning Unit:	Months v			(
PAF	Last Done/Fitted:				3	
(SB	Next Due:	Calculate			150	
(SB		REFER TIC-AW139-24-0084			3	
-E P		APPLICABLE DUE TO AIRCRAFT FITTED WITH MAIN SHOCK ABSORBER P/N 3G3210V01031.			0	
DTOF		(PARA.1) WITHIN 100 FLIGHT HOURS (FH) AFTER THE AFFECTED PART ACCUMULATED 7000 LANDINGS AND THEN.	EVERY	,		
R - C	Limitation Notes:	2000 LANDINGS OR 12 MONTHS WHICHEVER OCCURS FIRST.	LVLIN			
RE		CYCLES SINCE NEW:			18	7
RE		i) LH MAIN SA = 1239 LANDING CYCLES ii) RH ΜΔΤΝ SΔ = 1239 LANDING CYCLES			2	1
D	Aeronet Galaxy Ae	rospace > Modifications >Edit - Personal 3 - Microsoft Edge —	- 0		×	
ć	https://galax	xyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no8	lopener	,	A»	Ì
AD/	SB ID: 11270	Close 😏 Upd	iate 🔚 S	ave & (Close	
	General Config Lis	ist Aircraft List Task/Check List BOM				
	Туре :	ADS V Repetitive				
F	Reference/Number:	ATA 32 -MAIN LANDING GEAR SHOCK ABSORBER -INSPECTION				
	Title/Subject:	EASA EAD NO 2024-0084-E, NEW ISSUE				
	Version No:					
R	eason For Raising:					
	cusor rate	6				

Figure 2: REPETITIVE INSPECTION EVERY 2000 LANDINGS OR 12 MONTHS WHICHEVER OCCURS FIRST.