

TIC-AS350-24-0114

Edit Limitation (A/C: 9M-LKE)

Edit Limitation ASB NO. AS350-05.01.03 REV 1-ATA 65 - TIME LIMITS - MAINTEN...

Based On: Select

Warning: 0

Warning Unit: Select

Completed: -

Due At: -

Status: COMPLIED WITH

Limitation Notes:

TIC-AS350-24-0114
APPLICABLE DUE TO AIRCRAFT FITTED WITH AFFECTED P/N 350A33-2167-01.
COMPLIANCE:
- REVISION 0 OF THIS ASB HAVE BEEN COMPLIED WITH. (REFER TO W/O 2022 022 001).
- UPON RECEIVED REVISION 1 OF THIS ASB, RECORD THE MODIFICATION 0765002 ON THE LOG CARD OF THE TRH.
- UPON COMPLIANCE WITH THIS ASB, COMPLY WITH THE ALS IN FORCE FOR HELICOPTERS ON WHICH MOD 0765002 WAS IMPLEMENTED. (COMPLIED WITH - INTEGRATED IN AMP)

Aeronet Galaxy Aerospace > Modifications > Edit - Personal 3 - Microsoft Edge

https://galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&o...

AD/SB ID: 11707

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 65 - TIME LIMITS - MAINTENANCE CHECKS CHECK FOR ABSENCE OF ROTATION OF THE BEARING SPACER OF THE TAIL-ROTOR-HEAD (TRH) PITCH-CHANGE-UNIT

Title/Subject: ASB NO. AS350-05.01.03 REV 1

Version No: -

Reason For Raising: -

URL: -

Date: -- -- -- --

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
No Documents currently linked to the inspection		

Figure 1: 9M-LKE AERONET HAS BEEN UPDATED