## TIC-AS350-24-0121




Figure 1: AD 2021-0282R1 PART 1 HAS BEEN UPDATED IN AERONET

	E	dif Limitation (A/C: 9M-LKE)		,			
erati	ons Service	Edit Limitation EASA AD NO. 2021-0282R1, PART II (ASB NO. 05.01.	03)-ATA 64	Cancel	h		
		Based On:	Select 🗸				
		Warning:	0				
		Warning Unit:	Select V				
		Completed:					
		Due At:					
Do	cuments   SORs   Jo	Status:	COMPLIED WITH				
			COMPLIED WITH - REFER TO AHM W/O 2022 022 001				
		Limitation Notes:		- 1			
					d On	Period	War
	Aeronet Galaxy Aerospace > Modifications > Edit - Personal 3 - Microsoft Edge					0	×
		·					D M
							A <sup>th</sup> 1.01
AD/SB ID: 11701 ☑Close ← Update 📓 Sa						Save 8	Close O H
	General Config Lis	st Aircraft List Task/Check List Linked To BOM					D M
	Type :					3.01	
CER	Reference/Number:	ATA 64 - TAIL ROTOR - TAIL ROTOR HEAD PITCH CHA	NGE UNIT BEARING				.0 H
		SPACER - MARKING/CHECK					.01
							1.0
	Trite/Subject: EASAAD NO. 2021-0282R1, PART II (ASB NO. 05.01.03)						
	Version No:						nie
TOITS	Reason For Raising:						
ERIO	URL:						
	Date:						łou
	Tolerance:	0 % (Whole numbers only)					
	Creep Type: Document:	Creep on Completion Unit					łou
CEME	Document.	+ O Title	Filename			<	۰

Figure 2: AD 2021-0282R1 PART II HAS BEEN UPDATED IN AERONET




Figure 3: AD 2021-0282R1 PART IV HAS BEEN UPDATED IN AERONET