



	TECHNICAL INSTRUCTION COMPLIANCE			TIC REF NO	TIC/EC120B/21/0001
				DATE ISSUE	14 JAN 2021
A. TECHNICAL PUBLICATION (To Fill Up as Necessary)					
PUBLICATION TITLE	EASA - EC120B AIRWORTHINESS DIRECTIVES ATA 53 - FUSELAGE - TAIL BOOM - INSPECTION/MODIFICATION/REPAIR				
REV NO	AD NO. 2020-0015, NEW ISSUE	REV. DATE	13 JAN 2021		
APPLICABLE TO	<input checked="" type="checkbox"/> AC TYPE	<input checked="" type="checkbox"/> AC S/N:	<input type="checkbox"/> ENG. TYPE:	<input type="checkbox"/> ENG. S/N:	
	EC120B	1275 1487			
	<input type="checkbox"/> COMPONENT:		<input type="checkbox"/> EQUIPMENT:		
DISTRIBUTIONS	<input checked="" type="checkbox"/> OPERATOR	<input checked="" type="checkbox"/> AMO	<input checked="" type="checkbox"/> CAMO	<input type="checkbox"/> QUALITY	<input type="checkbox"/> OTHER:
B. TECHNICAL SERVICE (Applicability review prior to sentencing as necessary)					
<input type="checkbox"/> TIME LIMIT IMPOSED	<input checked="" type="checkbox"/> ONE TIME INSPECTION	<input type="checkbox"/> REPETITIVE INSPECTION	<input type="checkbox"/> OPTIONAL REQUIREMENT	<input type="checkbox"/> MODIFICATION REQUIRED	
<input type="checkbox"/> SPECIAL TOOLS REQUIRED	<input type="checkbox"/> INFORMATION ONLY	<input type="checkbox"/> NOT APPLICABLE	<input type="checkbox"/> OTHER:		
REMARKS:				NAME SIGNATURE & DATE	
<p>1275 - Applicable to helicopter serial number. Compliance: Within 6 months after the effective date of this AD, inspect the VHF antenna attachments to the tail boom in accordance with the instructions of paragraph 3.B of the ASB. Then before next flight require corrective action in accordance with ASB EC120-53A017 and SB EC120-53-018.</p> <p>1487 - Applicable to helicopter serial number. Compliance: Within 6 months after the effective date of this AD, inspect the VHF antenna attachments to the tail boom in accordance with the instructions of paragraph 3.B of the ASB. Then before next flight require corrective action in accordance with ASB EC120-53A017 and SB EC120-53-018.</p>				 MOHD YASIR SHAPUAN 14 JAN 2021	
C. CONTINUING AIRWORTHINESS MANAGER					
<input type="checkbox"/> MAINTENANCE SCHEDULE AMENT.	<input type="checkbox"/> PUBLICATION AMENDMENT	<input checked="" type="checkbox"/> PRE-PLANNED WORKSHEET	<input type="checkbox"/> COMPONENT SEND OFF FOR COMPLIANCE		
REMARKS:				NAME SIGNATURE & DATE	
<p>TO INCLUDE AD INSPECTION IN AERONET AND ALIGNED WITH ASB EC120-53A017. COMPLIANCE BEFORE 26 JULY 2021.</p>				 ZATY NADHIRA MOHAMED ZUHARI 15 JAN 2021	

D. MAINTENANCE PLANNER

<input checked="" type="checkbox"/>	ENTRY TO MAINT. FORECAST	<input checked="" type="checkbox"/>	PREPARE WORK PACKAGE	<input checked="" type="checkbox"/>	PLAN EMBODIMENT
<input checked="" type="checkbox"/>	SPARE ORDER	<input checked="" type="checkbox"/>	MANPOWER QUALIFICATION	<input checked="" type="checkbox"/>	TOOLING

REMARKS: 9M-HFA WP HAS BEEN ISSUED, REFER ATTACHMENT 9M-GGB AD ENTERED INTO AERONET , REFER ATTACHMENT	NAME SIGNATURE & DATE  MUHAMMAD IHSAN MASRI 15 JAN 2021
------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------

TIC COMPLIANCE CHECKLIST

COMPLIANCE		REMARKS:	NAME SIGNATURE & DATE
YES	NO		
<input checked="" type="checkbox"/>		AD COMPLIANCE CONTINUE MONITORING IN AERONET.	 ZATY NADHIRA MOHAMED ZUHARI 18 JAN 2021