

TIC-EC155-24-0141

The image shows a screenshot of the Aeronet software interface. The top window is titled "Edit Limitation (A/C: 9M-D SJ)" and contains the following fields:

- Based On: Select
- Warning: 0
- Warning Unit: Select
- Completed: -
- Due At: 0.00
- Status: NOT APPLICABLE

Below these fields, the text reads: "TIC-EC155-24-0141" and "APPLICABILITY: NOT APPLICABLE. AIRCRAFT FITTED WITH TGB WITH PART NUMBER 365A33 6005 09". The "Limitation Notes" section contains "COMPLIANCE: NOT APPLICABLE".

The bottom window is a Microsoft Edge browser displaying the URL: https://galxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&o.... The browser shows the "AD/SB ID: 11677" and a navigation menu with options: General, Config List, Aircraft List, Task/Check List, Linked To, and BOM.

The main content area of the browser window is titled "Edit" and contains the following fields:

- Type: ADS (selected) and Repetitive (checkbox)
- Reference Number: ATA 65 TAIL ROTOR PITCH CONTROL ROD BEARING INSPECTION / REPLACEMENT
- Title/Subject: AD NO. 2021-0171 REV 1
- Version No: [Empty]
- Reason For Raising: [Empty]
- URL: [Empty]
- Date: [Calendar icon]
- Tolerance: 0% (Whole numbers only)
- Creep Type: Creep on Completion Unit
- Document: [Empty]

At the bottom of the browser window, there is a table with columns "Title" and "Filename". The table is currently empty, with the text "No Documents currently linked to the inspection" displayed below it.

Figure 1: 9M-DSJ AERONET HAS BEEN UPDATED




Figure 2: 9M-KEL AERONET HAS BEEN UPDATED




Figure 3: SB 139-672 PART II AERONET HAS BEEN UPDATED