

GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14 Helicopter Centre, Marcy Lip International Aerocopce Centre-Burtan Andra Azt Sinan Armon. 47200 Sotiang, Belongus Malaysia. les 7803 7734 7228 | Fex. 7803 7734 7826



CLIENT/OWNER: ROYAL MALAYSIA WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 9380-003 POLICE WORK/INSP/DESC: 300H/12M REPETITIVE 31809 AIRCRAFT AIRCRAFT TYPE: AW139 WORKPACK REF: REFER WORKPACK #1 ENGINE: PCE-KB2112 9M-PMD-9380 REGISTRATION: 9M-PMD AJL REF NO.: BASE/FACILITY: WMSA REFER WORKPACK REFER WORKPACK #2 ENGINE: PCE-KB2092 DATE IN: REFER WORKPACK SHEET: 1 OUT: REFER OF NG/N1 NF/N2 Reason for raising: SCHEDULED INSPECTIONS TO BE CARRY OUT I.A.W EASA AD NO.: 2021-0044 ISSUE 05 Raised by and date: Other requirements/information: CAMO: Ahmad Khalis NIL FEBRUARY 2021, ASB139-661 REV. A DATE 18 FEBRUARY 2021 OR LATER APPROVED Halimi REVISIONS 28/01/2022 Item Description Technician * Eng. CRS Date 1 EASA AD NO.: 2021-0044 PARA (2) (ASB139-661) PART II - ATA 24 OVERHEAD PANEL INSPECTION TO PERFORM A RECURRENT INSPECTION INSIDE THE OVERHEAD PANEL TO CHECK THE TAPE CONDITION AND THE ABSENCE OF CHAFING IN ACCORDANCE WITH EASA AD NO.: 2021-0044 PARA (2) (ASB139-661) PART II COMPLIANCE INSTRUCTION. 4/2/22 REFERENCE: EASA AD NO.: 2021-0044 ISSUE 05 FEBRUARY 2021, ASB139-661 REV. A DATE 18 FEBRUARY 2021 8345 REMARKS: C/OUT FOUND SATIS The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. ☐ TICK WHERE APPLICABLE