

SBS

SERVICE BULLETIN (SB'S) STATUS LIST

Aircraft Registration:	9M-PME	Serial No:	31855	Date: 09/05/2023	Page No:	103
Aircraft Hours:	1568:17	Landings:	2357.00	Engine 1: 1568:17	Engine 2:	1568:17

Types	SB Number	Subject	Last Done	Next Due		
Standard SBs	BT 139-004	UPPER DECK INSULATING COVERS P/N 3G5306P07511,	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER
		INSTALLATION OF				S/N.
						INFO IS REFERRED FROM LEONARDO
						HELICOPTERS ANNEX 2 - BOLLETTINI
						TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-003 REV A	VARIANT 4TH FLAT PANEL DISPLAY P/N 3G4630F00111	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER
		INSTALLATION OF.				S/N.
						INFO IS REFERRED FROM LEONARDO
						HELICOPTERS ANNEX 2 - BOLLETTINI
						TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-64-002 REV B	PART I: INSPECTION OF SLIDER ASSY P/N 3G6430A00131 AND OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER
		THE SPIDER & SLIDER ASSY P/N 3G6430A01931.PART II:				S/N.
		SOSTITUZIONE DELLO SLIDER BUSHING P/N 3G6430V00251.				
						INFO IS REFERRED FROM LEONARDO
						HELICOPTERS ANNEX 2 - BOLLETTINI
						TECNICI STATUS LIST DATED 08/10/2019.
SERVICE BULLET		·				
ENGINE #1						
Standard SBs	NO. 1 ENGINE ~ SB NO. 41120,	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448	-	-	-/NOT APPLICABLE	TIC-AW139-21-0248 (REV.0)
	REVISION 2	- CONVERSION OF				TIC-AW139-21-0270 (REV.1)
						CATEGORY 8 - NOT APPLICABLE DUE TO
						ENGINE S/N NOT AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41119, REVISION 4	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0249 DATED 30 JUNE 2021
						APPLICABLE DUE TO ENGINE BUILD SPEC
						AND SERIAL NUMBER AFFECTED.
						COMPLIANCE: CATEGORY 7 - YOU CAN
						DO THIS SB WHEN THE SUPPLY OF THE
						SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41112,	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) -	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021
	REVISION 1	REPLACEMENT / MODIFICATION				
						APPLICABLE DUE TO BUILD SPEC AND
						ENGINE SERIAL NUMBER AFFECTED.
						CONCURRENT REQUIREMENT: NONE.



SBS

SERVICE BULLETIN (SB'S) STATUS LIST

Aircraft Registration:	9M-PME	Serial No:	31855	Date: 09/05/2023	Page No:	124
Aircraft Hours:	1568:17	Landings:	2357.00	Engine 1: 1568:17	Engine 2:	1568:17

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41003 REV 0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER.
						INFO IS REFERRED FROM ENGINE
						TECHNICAL RECORD LOG PRATT AND
						WHITNEY CANADA ENGINE BUILD STATUS
						RECORD DATED 05.12.2018.
Standard SBs	41004 REV 0	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER.
						INFO IS REFERRED FROM ENGINE
						TECHNICAL RECORD LOG PRATT AND
						WHITNEY CANADA ENGINE BUILD STATUS
						RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41006 REV. 0 - ENG #1	AIR LIMITATION RESTRICTION LIFTED	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3.
						NOT APPLICABLE PER ENGINE S/N.
						INFO IS REFERRED FROM LEONARDO
						HELICOPTER PWC PT6C-67C SERVICE
						BULETTINS STATUS LIST DATED 08/10/2019.
ENGINE #2						00/10/2010.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41120,	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448	-	-	-/NOT APPLICABLE	TIC-AW139-21-0248 (REV.0)
	REVISION 2	- CONVERSION OF				TIC-AW139-21-0270 (REV.1)
						CATEGORY 8 - NOT APPLICABLE DUE TO
						ENGINE S/N NOT AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41119, REVISION 4	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0249 DATED 30 JUNE 2021
						APPLICABLE DUE TO ENGINE BUILD SPEC
						AND SERIAL NUMBER AFFECTED.
						COMPLIANCE: CATEGORY 7 - YOU CAN
						DO THIS SB WHEN THE SUPPLY OF THE
						SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41112, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) - REPLACEMENT / MODIFICATION	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021
						APPLICABLE DUE TO BUILD SPEC AND
						ENGINE SERIAL NUMBER AFFECTED.
						CONCURRENT REQUIREMENT: NONE.