

Aircraft Registration:	9M-PMA	Serial No:	31807	Date:	05/05/2023	Page No:	35
Aircraft Hours:	1682:21	Landings:	2695.00	Engine 1:	1682:21	Engine 2:	1682:21

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0270 DATED 11 AUGUST 2021 CATEGORY 8. NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	NO.1 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41103, REVISION 1	TURBOSHAFT ENGINE - CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-20-188 - COMPLIED BY OEM
Standard SBs	NO. 1 ENGINE ~ SB NO. 41111	TURBOSHAFT ENGINE- DIAMETRICAL GROWTH DIMENSION COMPRESSOR TURBINE DISK - CORRECTION OF	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-044. NOT APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE.
Standard SBs	SB NO 41093, NEW ISSUE	TURBOSHAFT ENGINE - ROLLER BEARING OPTION (IC)- REPLACE	-	-	-/PARTS IS FULLY USED	REFER TO TIC-AW139-20-041. APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE. SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	SB NO. 41089, REVISION 3	TURBOSHAFT ENGINE - CHECK VALVE PLATE- REPLACEMENT OF	-	-	-/FOR INFO ONLY	REFER TO TIC-AW139-20-040 APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE.
Standard SBs	SB NO. 41703, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE REPLACEMENT/	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-039 NOT APPLICABLE TO ENGINE S/N
Standard SBs	SB NO 41113R1	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSPECTION OF	-	-	-/COMPLIED WITH	TIC-AW139-19-046 APPLICABLE TO ENGINE SERIAL NUMBER. COMPLIED WITH AJL NO 01743 WP# WP-PMA-19-566-001 ON 23-AUG-19 AT 223:30FH
Standard SBs	P&W SB NO. 4116 NEW ISSUE	FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION OF	-	-	-/FOR INFO ONLY	TIC-AW139-19-031 - COMPLIANCE CAT. 9SPARE PARTS INFORMATION
Standard SBs	NO. 1 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/Category 7	TIC-AW139-19-009 CAT 7 WHEN SUPERSEDED PART IS FULLY USED
Standard SBs	NO. 1 ENGINE ~ SB NO. 41066 REVISION 5	POWER TURBINE SHAFT AND STATOR ASSEMBLIES - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-19-025 DATED 23 JUNE 2019 APPLICABLE TO ENGINE TYPE
Standard SBs	NO. 1 ENGINE ~ SB NO. 41065, REVISION 3	POWER TURBINE VANE RING - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-19-047 DATED 17 JULY 2019 NOT APLICABLE DUE TO ENGINE SERIAL NUMBER.
Standard SBs	P&WC SB NO. 41095 REV. 1	POWER TURBINE SHAFT - INSPECTION OF	-	-	-/FOR INFO ONLY	
Standard SBs	3HRL4-HOIST-ATF-01R2	EQUIPMENT/FURNISHINGS - RESCUE HOIST LUBRICATION UPDATE - PRODUCT IMPROVEMENT	-	-	-/FOR INFO ONLY	

Aircraft Registration:	9M-PMA	Serial No:	31807	Date:	05/05/2023	Page No:	37
Aircraft Hours:	1682:21	Landings:	2695.00	Engine 1:	1682:21	Engine 2:	1682:21

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41065, REVISION 3	POWER TURBINE VANE RING - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-19-047 DATED 17 JULY 2019 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41116, REVISION 1	TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION OF	-	-	-/FOR INFO ONLY	REFER TO TIC-AW139-19-076 - APPLICABLE TO ENGINE TYPE COMPLIANCE: CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	NO. 2 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/Category 7	TIC-AW139-19-009 CAT 7 WHEN SUPERSEDED PART IS FULLY USED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41112, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) - REPLACEMENT / MODIFICATION	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021 APPLICABLE DUE TO BUILD SPEC AND ENGINE SERIAL NUMBER AFFECTED. CONCURRENT REQUIREMENT: NONE.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-205 CAT 7, APPLICABILITY: NOT APPLICABLE ENGINE SN NOT AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0270 DATED 11 AUGUST 2021 CATEGORY 8. NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41111	TURBOSHAFT ENGINE - DIAMETRICAL GROWTH DIMENSION, COMPRESSOR TURBINE DISK - CORRECTION OF	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-044. NOT APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41119, REVISION 4	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0249 DATED 30 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41103, REVISION 1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-20-188 - COMPLIED BY OEM
Standard SBs	NO. 2 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0031 NOT APPLICABLE DUE TO #2 ENGINE SN (PCE-KB2069) NOT AFFECTED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41073, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/N/A (POST-MOD)	TIC-AW139-20-039 DATED 11 MARCH 2020 NOT APPLICABLE TO ENGINE SERIAL NUMBER