

Aircraft Registration:	9M-PMB	Serial No:	31726	Date:	31/03/2023	Page No:	54
Aircraft Hours:	1928:19	Landings:	3473.00	Engine 1:	1928:19	Engine 2:	1928:19

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO.1 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41110 REVISION 2	PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0239 DATED 11 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPECT AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/OPEN	TIC-AW139-19-009 CAT 7 WHEN SUPERSEDED PART IS FULLY USED
Standard SBs	NO. 1 ENGINE ~ SB NO. 41112, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) - REPLACEMENT / MODIFICATION	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021 APPLICABLE DUE TO BUILD SPEC AND ENGINE SERIAL NUMBER AFFECTED. CONCURRENT REQUIREMENT: NONE.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41119, REVISION 4	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0249 DATED 30 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0270 DATED 11 AUGUST 2021 CATEGORY 8. NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
ENGINE NO.2						
Standard SBs	NO. 2 ENGINE ~ SB NO. 41030, REVISION 1	CHECK VALVE ASSEMBLY - INSPECTION OF	-	-	-/COMPLIED WITH	
Standard SBs	NO.2 ENGINE ~ S.B. NO. 41100 REV. 2	NO.5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	ONLY APPLICABLE TO CERTAIN OPERATORS ONLY.
Standard SBs	NO. 2 ENGINE ~ S.B. 41107 REV.0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ALL ENGINE EQUIPPED WITH OLD PART NUMBER. NEW PART NUMBER WILL REPLACED THE OLD PART NUMBER WHEN NEEDED. REFER TIC-17-015 DATED 23.01.2017
Standard SBs	SB NO. 41095, REVISION 1	TURBOSHAFT ENGINE POWER TURBINE SHAFT - INSPECTION OF	-	-	-/NOT APPLICABLE	

Aircraft Registration:	9M-PMB	Serial No:	31726	Date:	31/03/2023	Page No:	66
Aircraft Hours:	1928:19	Landings:	3473.00	Engine 1:	1928:19	Engine 2:	1928:19

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSP	P&WC SB NO. 41113 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	APPLICABLE TO ENGINE SERIAL NUMBER. REFER TO TIC-AW139-19-051 DATED 25.07.2019
Standard SBs	NO. 2 ENGINE ~ SB NO. 41066 REVISION 5	POWER TURBINE SHAFT AND STATOR ASSEMBLIES - REPLACEMENT OF	-	-	-/COMPLIED WITH	
Standard SBs	NO. 2 ENGINE ~ SB NO. 41116, REVISION 1	TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION OF	-	-	-/OPEN	REFER TO TIC-AW139-19-076 - APPLICABLE TO ENGINE TYPE COMPLIANCE: CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	NO. 2 ENGINE ~ SB NO. 41073, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/Required	
Standard SBs	NO. 2 ENGINE ~ SB NO. 41100, REVISION 8	TURBOSHAFT ENGINE NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/OPTIONAL	
Standard SBs	NO. 2 ENGINE ~ SB NO. 41103, REVISION 1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/OPTIONAL	WP-PMB-20-2066 @ 1442:35 FH ON 08/10/2020 (AJL 02907)
Standard SBs	NO. 2 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-205 CAT 7, APPLICABILITY: NOT APPLICABLE ENGINE SN NOT AFFECTED.
Standard SBs	NO. 2 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0031 NOT APPLICABLE DUE TO #2 ENGINE S/N (PCE-KB1832) NOT AFFECTED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41110 REVISION 2	PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0239 DATED 11 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPECT AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/OPEN	TIC-AW139-19-009 CAT 7 WHEN SUPERSEDED PART IS FULLY USED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41112, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) - REPLACEMENT / MODIFICATION	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021 APPLICABLE DUE TO BUILD SPEC AND ENGINE SERIAL NUMBER AFFECTED. CONCURRENT REQUIREMENT: NONE.