

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	09/05/2023	Page No:	104
Aircraft Hours:	1568:17	Landings:	2357.00	Engine 1:	1568:17	Engine 2:	1568:17

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/OPTIONAL	REFERENCE: TIC-AW139-21-0241 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7: YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED
Standard SBs	NO. 1 ENGINE ~ SB NO. 41110 REVISION 2	PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0239 DATED 11 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPECT AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO.1 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 1 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0031 NOT APPLICABLE DUE TO ENGINE S/N (PCE-KB2214) NOT AFFECTED
Standard SBs	NO. 1 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-217 DATED 31 DECEMBER 2020 CATEGORY 7, APPLICABILITY: NOT APPLICABLE DUE TO AFFECTED SERIAL NUMBER ENGINE NOT FITTED ON AIRCRAFT.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41103, REVISION 1	TURBOSHAFT ENGINE - CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-20-188 DATED 02 NOVEMBER 2020 COMPLIED BY OEM.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41100, REVISION 8	TURBOSHAFT ENGINE - NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/Category 8	TIC-AW139-20-090 DATED 02 JUNE 2020 APPLICABLE DUE TO ENGINE BUILD SPECIFICATION. COMPLIANCE: CATEGORY 8
Standard SBs	NO. 1 ENGINE ~ SB NO. 41073, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-039 DATED 11 MARCH 2020 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	09/05/2023	Page No:	125
Aircraft Hours:	1568:17	Landings:	2357.00	Engine 1:	1568:17	Engine 2:	1568:17

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/OPTIONAL	REFERENCE: TIC-AW139-21-0241 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7: YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41110 REVISION 2	PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0239 DATED 11 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPECT AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 2 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0031 NOT APPLICABLE DUE TO AIRCRAFT S/N (PCE-KB2224) NOT AFFECTED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-217 CATEGORY 7, APPLICABILITY: NOT APPLICABLE DUE TO AFFECTED ENGINE SERIAL NUMBER NOT FITTED ON AIRCRAFT.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41103, REVISION 1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-20-188 DATED 02 NOVEMBER 2020 COMPLIED BY OEM.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41100, REVISION 8	TURBOSHAFT ENGINE NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/Category 8	TIC-AW139-20-090 DATED 02 JUNE 2020 APPLICABLE DUE TO ENGINE BUILD SPECIFICATION. COMPLIANCE: CATEGORY 8
Standard SBs	NO. 2 ENGINE ~ SB NO. 41073, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-039 DATED 11 MARCH 2020 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.