

Aircraft Registration:	9M-YTL	Serial No:	41358	Date:	05/05/2023	Page No:	29
Aircraft Hours:	388:55	Landings:	591.00	Engine 1:	388:55	Engine 2:	388:55

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 41113R1	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSPECTION OF			-	-/COMPLIED WITH TIC-AW139-19-046 APPLICABLE TO ENGINE SERIAL NUMBER. COMPLIANCE IS CATEGORY 3 WHICH IS AT FIRST MAINTENANCE OPPORTUNITY WITHOUT EXCEEDING 50 FLIGHT HOURS FROM RECEIPT OF THIS SERVICE BULLETIN COMPLIED WITH WP# WP-YTL-20-41113
Standard SBs	SB 41021 R1	FUEL SYSTEM - INSPECTION OF	348.67		-	-/COMPLIED WITH - LAST DONE 9M-YTL-11102 AT 348:40 ON 14/10/2022 (AJL 1561)
Standard SBs	SB 41030	CHECK VALVE ASSEMBLY - INSPECTION OF	0.00	400.00	-	-/CANCELLED CANCELLED
Standard SBs	SB139-573, NEW ISSUE	ATA 31 - KIT HUMS COMPLETION			-	-/NOT APPLICABLE TIC-AW139-19-035 - NOT APPLICABLE BY ACRFT SN AND THIS IS OPTIONAL SB
Standard SBs	P&W SB NO. 4116 NEW ISSUE	FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION OF			-	-/FOR INFO ONLY TIC-AW139-19-031 - COMPLIANCE CAT. 9SPARE PARTS INFORMATION
Standard SBs	SB 139-593 REV. A	ATA 71 - ENGINE MOUNTING RODS REPLACEMENT			-	-/NOT APPLICABLE TIC-AW13919-019 YTL & PGU AW139 NOT APPLICABLE TO COMPONENT SN.
Standard SBs	SB139-525, REVISION A	ATA 95 - INSTALLATION OF INFLATION SERVICE CHARTS			-	-/NOT APPLICABLE TIC-AW139-19-018 NOT APPLICABLE BY COMPONENT SN REV. A OF THIS SERVICE BULLETIN HAS BEEN ISSUED TO EXTEND THE EFFECTIVITY SECTION. NOT APPLICABLE TO COMPONENT PART NUMBER P/N FOR THE NEW EFFECTIVITY. REFER TO TIC-AW139-19-018 DATED 22 NOVEMBER 2019
Standard SBs	NO. 1 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET			-	-/PARTS IS FULLY USED TIC-AW139-19-009 CAT 7 WHEN SUPERSEDED PART IS FULLY USED
Standard SBs	SB139-535 REV./	ATA 23 - INSTALLATION OF KIT EXTERNAL LOUDSPEAKERS			-	-/OPTIONAL TIC-YTL-19-028 - THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION FOR INSTALLATION OF THE EXTERNAL LOUDSPEAKERS (400 W).
Standard SBs	SB139-501 REV.B	ATA 62 MAIN ROTOR BLADE ASSY UPGRADE			-	-/OPTIONAL TIC-AW139-19-001 - OPTIONAL SB

Aircraft Registration:	9M-YTL	Serial No:	41358	Date:	05/05/2023	Page No:	59
Aircraft Hours:	388:55	Landings:	591.00	Engine 1:	388:55	Engine 2:	388:55

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41049 REV. 2 (ENG#2)	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	-	-	-/NOT APPLICABLE	REF: TIC-YTL-18-013 DATE: 11.12.2018 NOT APPLICABLE BY ENGINE SN. AIRCRAFT FITTED WITH ENGINE S/N PCE-KB14443 AND PCE-KB1457
Standard SBs	NO. 2 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/PARTS IS FULLY USED	COMPLIANCE AT CATAGORY 7 - WHEN SUPERSEDED PART IS FULLY USED.
Standard SBs	41052 REV. 1 (ENG#2)	OIL TRAY, ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	REF: TIC-YTL-18-012 DATE: 11.12.2018 NOT APPLICABLE BY ENGINE SN. AIRCRAFT FITTED WITH ENGINE S/N PCE-KB1443 AND PCE-KB1457
Standard SBs	41094 REV. 3 (ENG#2)	BLEED VALVE - INSPECTION/MODIFICATION OF	0.00	5000.00	-/TO BE COMPLIED	NOT COMPLIED WITH. CATEGORY 4 TO BE COMPLY ON THE FIRST TIME THE ENGINE OR MODULE IS AT A MAINTENANCE BASE THAT CAN DO THE PROCEDURES, REGARDLESS OF THE SCHEDULED MAINTENANCE ACTION OR REASON FOR ENGINE REMOVAL. REFER TO LHM MOD RECORD BOOK SEC 7 TB (ENGINE) COMPLIANCE SUMMARY ON 29.11.2018
Standard SBs	41101 REV. 3 (ENG#2)	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING MSS CAVITY WITH RTV	239.00	-	-/COMPLIED WITH	APPLICABLE. TO BE COMPLY WITHIN 150 FLIGHT HOURS FROM RECEIPT OF REVISION 2 OF THIS SERVICE BULLETIN. DUE ON 257:23 HRS. REFER TO LHM MOD RECORD BOOK SEC 7 TB (ENGINE) COMPLIANCE SUMMARY ON 29.11.2018 LAST DONE WP-YTL-20-1911 AT 239:00 ON 01/10/2020 (AJL 1312)