

ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

| | | | | | | | |
|------------------------|---------------|------------|-------------|-----------|------------|-----------|---------|
| Aircraft Registration: | 9M-SAS | Serial No: | 6583 | Date: | 20/09/2021 | Page No: | 14 |
| Aircraft Hours: | 3380:50 | Landings: | 7774.00 | Engine 1: | 5443:01 | Engine 2: | 5411:01 |

| Types | AD Number | Subject | Last Done | Next Due | Interval/Status | Limitation Notes |
|---------------|---|---|-----------|----------|-------------------------|---|
| Standard ADs | EASA AD NO 2014-0236R1 (ASB EC155-33A013) | ATA 33 - LIGHTS - EMERGENCY LIGHTING ROTORCRAFT FLIGHT MANUAL AMENDMENT / OPERATIONAL PROCEDURE | - | - | -/NOT APPLICABLE | PARA 1, WITHIN 30 DAYS AFTER 11 NOVEMBER 2014, AMEND RFM AS PER ASB EC155-33A013. PARA 2, BEFORE FIRST FLIGHT OF THE DAY, DO FUNCTIONAL CX AS PER EC155-33A013. NOT APPLICABLE. DUE TO NOT FITTED WITH COBHAM OR AIR PRECISION EMERGENCY LIGHTING BATTERY P/N 704A46130044 (MP/N: B1250000). TIC-EC155-21-0074 |
| Types | AD Number | Subject | Last Done | Next Due | Interval | Limitation Notes |
| Component ADs | EASA AD No.: 2021-0170 // EASB NO. EC155-04A016, REV. 4 | ATA 65 TAIL ROTOR DOUBLE BEARING INSPECTION / REPLACEMENT | 0.00 | 3355.00 | - | |