

Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07/03/2023	Page No:	1
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1: 915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
ADs	•			<u> </u>		
Types	AD Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive ADs	EASA AD No.: 2022-0205 (SB 139-724	TAIL ROTOR - DAMPER BRACKET - INSPECTION	07/02/2023	07/08/2023	6	
	REV B)					
Repetitive ADs	EASA AD No.: 2022-0205 (SB 139-724	TAIL ROTOR - DAMPER BRACKET - INSPECTION	906:15	956:15	50	
	REV B)					
Repetitive ADs	EASA AD 2022-0182-E PARA 1 (SBEA	TAIL ROTOR - DUPLEX BEARINGS - INSPECTION/REPLACEMENT //	0:00	0:00	10	
	139-725 REV. A PART I)	ROTOR FLIGHT CONTROL - TAIL ROTOR ACTUATOR -				
		INSPECTION/REPLACEMENT				
Repetitive ADs	EASA AD 2015-0226R7 CORRECTION	ATA 25 - EQUIPMENT / FURNISHINGS HOIST TEST /	-	-	0	
	20 DECEMBER 2021 (SB139-	REPLACEMENT				
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE	06/12/2022	06/12/2023	12	TIC-AW139-22-0120 DATED 13 MAY 2022
	(ASB139-661 REV. B)	PART II COMPLIANCE				9M-PMF-10822 (AJL 02111) AT 578:50FH ON
						27/05/2022
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE	862:55	1162:55	300	TIC-AW139-22-0120 DATED 13 MAY 2022
	(ASB139-661 REV. B)	PART II COMPLIANCE				9M-PMF-10822 (AJL 02111) AT 578:50FH ON
						27/05/2022
Repetitive ADs	EASA AD 2020-0271 PARA (2) (ASB139	50FH - ATA 62 MAIN ROTOR SWASHPLATE BOOT INSPECTION	906:15	956:15	50	TIC-AW139-20-201 DATED 9 DECEMBER
	-654 PART II					2020
						9M-PMF-11899 (AJL 02158) AT 678:30 FH
						0N 31.07.2022
						9M-PMF-12350 (AJL 02171) AT 709:45 FH
						ON 14.08.2022
						TIC-AW139-20-199 DATED 02 DECEMBER
						2020.
						9M-PMF-11899 (AJL 02158) AT 678:30 FH
						ON 31.07.2022
						9M-PMF-12350 (AJL 02171) AT 709:45 FH
						ON 14.08.2022
						9M-PMF-12573 (AJL 02188) AT 740:20 FH
						ON 03.09.2022



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07/03/2023	Page No:	2	
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1: 915:05	Engine 2:	915:05	

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive ADs	2015-0226 REV 7 PARA 3 (SB139-443	400HL//6M HOIST LOAD TEST - EQUIPMENT / FURNISHINGS - H	0:00	400:00	400	TIC-AW139-22-0124 DATED 23 MAY 2022
	REV.A PARA III)					APPLICABLE TO 9M-PMF(31913) DUE TO
						COMPONENT P/N 44316/12-104 FITTED ON
						AIRCRAFT.
						HOIST NOT FITTED. REMOVED
						CARRIED IN WP-PMF-20-2095 @ 77:30 FH
						ON 22/07/2021, DUE FOR SB139-443 (PART
						3) WILL DUE ON 03/11/2021, REFER TO
						ARC ATTACHED IN WP-PMF-20-2095
Repetitive ADs	2015-0226 REV 7 PARA 3 (SB139-443	400HL//6M HOIST LOAD TEST - EQUIPMENT / FURNISHINGS - H	14/09/2022	14/03/2023	6	TIC-AW139-22-0124 DATED 23 MAY 2022
	REV.A PARA III)					APPLICABLE TO 9M-PMF (31913) DUE TO
						COMPONENT P/N 44316/12-104 FITTED ON
						AIRCRAFT.
						HOIST NOT FITTED REMOVED
						CARRIED IN WP-PMF-20-2095 @ 77:30 FH
						ON 22/07/2021, DUE FOR SB139-443 (PART
						3) WILL DUE ON 03/11/2021, REFER TO
						ARC ATTACHED IN WP-PMF-20-2095
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL//36M HOIST CLUCTH REPLACEMENT - ATA 25	0:00	2600:00	0	TIC-AW139-22-0124 DATED 23 MAY 2022
		EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT				APPLICABLE TO 9M-PMF(31913) DUE TO
						COMPONENT P/N 44316/12-104 FITTED ON
						AIRCRAFT.
						CARRIED IN WP-PMF-20-2095 @ 77:30 FH
						ON 22/07/2021, DUE FOR 36M / 2600 HL
						WILL DUE ON 03/05/2024, REFER TO ARC
						ATTACHED IN WP-PMF-20-2095



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	3
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL//36M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	04/05/2021	00/00/0000	0	TIC-AW139-22-0124 DATED 23 MAY 2022 APPLICABLE TO 9M-PMF(31913) DUE TO
						COMPONENT P/N 44316/12-104 FITTED ON
						AIRCRAFT.
						CARRIED IN WP-PMF-20-2095 @ 77:30 FH
						ON 22/07/2021, DUE FOR 36M / 2600 HL
						WILL DUE ON 03/05/2024, REFER TO ARC
						ATTACHED IN WP-PMF-20-2095
Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	AD 2022-0182-E PARA (7), (SBEA 139-	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND	-	-	-/SUPERSEDED	SUPERSEEDED BY AD 2022-0182-E.
	725 REV.A PART IV)	REPLACEMENT				
Standard ADs	AD 2022-0182-E PARA (3), (SBEA 139-	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND	-	-	-/SUPERSEDED	SUPERSEEDED BY AD 2022-0182-E
	725 REV.A PART III)	REPLACEMENT				
		(DUPLEX BEARING > 2400FH)				
Standard ADs	EASA AD NO. 2022-0182-E, NEW	TAIL ROTOR - DUPLEX BEARINGS - INSPECTION/REPLACEMENT //	-	-	-/Required	
	ISSUE (SBEA 139-725 REV.A)	ROTOR FLIGHT CONTROL - TAIL ROTOR ACTUATOR -				
		INSPECTION/REPLACEMENT (PARA 10)				
Standard ADs	EASA EAD NO. 2022-0209-E, NEW	HARNESS INSTALLATION - FORWARD ROOF AREA - INSPECTION	-	-	-/Required	
	ISSUE (PARA 1)					
Standard ADs	EASA AD No.: 2022-0154 (SBA 139-724	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	-	-	-/Required	TIC-AW139-22-0160 DATED 02 AUGUST
	REV.A)					2022
						NOT APPLICABLE DUE TO AFFECTED S/N
						OF COMPONENT TAIL ROTOR DAMPER
						BRACKET ASSEMBLY P/N 3G6420A06131
						NOT EQUIPPED ON AIRCRAFT.
Standard ADs	EASA AD No.: 2022-0154 (SBA 139-724	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	-	-	-/Required	TIC-AW139-22-0160 DATED 02 AUGUST
	REV.A)					2022
						NOT APPLICABLE DUE TO AFFECTED S/N
						OF COMPONENT TAIL ROTOR DAMPER
						BRACKET ASSEMBLY P/N 3G6420A06131
						NOT EQUIPPED ON AIRCRAFT.
Standard ADs	EASA AD 2022-0152-E PARA (2)(SBEA	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND	-	-	-/Required	TIC-AW139-22-0157 DATED 27 JULY 2022
	139-725 REV/PART 2)	REPLACEMENT(WITHIN 10FH AND EVERY 50FH)				APPLICABLE DUE TO AIRCRAFT TYPE
						AFFFECTED
Standard ADs	EASA AD 2022-0152 PARA 1 (EASB139-	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND	-	-	-/Required	TIC-AW139-22-0157 27 JULY 2022
	725 REV./ PART1	REPLACEMENT (BFF AND EVERY 10FH)				APPLICABLE DUE TO AIRCRAFT TYPE
						AFFFECTED



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	4
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA SIB 2019-09 R1	1Y INSP ELT & PLB ANNUAL TEST	31/01/2022	-		TIC-GEN-21-0017 DATED 08 MARCH 2021. LM WS# 2021/PMF/002-23 AT 12:50FH ON 12/04/2021 REF GAM/WO/20/2664 9M-PMF-9703 AT 337:43 FH ON 31/01/2022 (AJL 02015)
Standard ADs	EASA AD 2022-0209-E (SB 139-731 REV./ PART 1)	ATA 91 HARNESS INSTALLATION FORWARD ROOF AREA INSPECTION	778.92	-	-/COMPLIED WITH	9M-PMF-13069
Standard ADs	EASA AD 2022-0209-E (SB 139-731 REV./ PART 2)	ATA 91 HARNESS INSTALLATION FORWARD ROOF AREA INSPECTION		-	-/COMPLIED WITH	
Standard ADs	EASA AD 2017-0175-E (SB 139-508 REV. /)	MAIN ROTOR - MAIN ROTOR BLADES - INSPECTION / REPLACEMENT	-	-		TIC-AW139-21-0319 DATED 27 AUGUST 2021 NOT APPLICABLE. AIRCRAFT IS FITTED WITH NOT AFFECTED SERIAL NUMBER MRB WHICH ARE S/N 5266, 5268, 5273, 5277, 5270.
Standard ADs	EASA AD 2018-0002 NEW ISSUE (SB 139-500)	ATA 46 - INFORMATION SYSTEMS - "PRIMUS EPIC" SYSTEM SOFTWARE - SOFTWARE UPDATE	-	-		REFER TIC-AW139-21-0320. NOT APPLICABLE DUE TO HELICOPTER NOT EQUIPPED WITH PRIMUS EPIC SYSTEM SOFTWARE RELEASE 7.4 (PHASE 7 V1) OR 7.7 (PHASE 7 V3) OR 7.10 (PHASE 7 V4). HELICOPTER CURRENTLY EQUIPPED WITH SOFTWARE RELEASE 7.12.
Standard ADs	EASA AD 2018-0132, NEW ISSUE	TIME LIMIT/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION	-		-/COMPLIED WITH	TIC-AW139-21-0323. COMPLIED WITH. LATEST REVISION OF RMPAOF/CAMO/AMP/AW139 HAD INCORPORATED THE DOCUMENT 39-A- AMPI-00-P CHAPTER 4 LATEST ISSUE (ALS).
Standard ADs	EASA AD 2018-0208 (SB139-533)	EMERGENCY FLOTATION SYSTEM - AFT FLOAT ASSEMBLY INFLATION SYSTEM - REMOVAL / INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0324 DATED 27 AUGUST 2021 NOT APPLICABLE. DIFFERENT PART NUMBER INSTALLED.
Standard ADs	EASA AD 2018-0292 (ASB 139-569 REV. B PART I)	ATA-64, T/R SLIDER ASSEMBLY - INSPECTION	0.00	2450.00	-/TO BE COMPLIED	TIC-AW139-21-0325. APPLICABLE DUE TO AIRCRAFT FITTED WITH TAIL ROTOR SLIDER ASSEMBLY P/N 3G6430A00131.



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 0	7/03/2023	Page No:	5
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD2019-0022 (SB139-571 REV./)	ATA 64 - TAIL ROTOR DUPLEX BEARING REPLACEMENT	-	-	-/NOT APPLICABLE	REFER TIC-AW139-21-0326. NOT APPLICABLE DUE TO TAIL ROTOR (TR) DUPLEX BEARINGS S/N NOT AFFECTED. AIRCRAFT FITTED WITH TRDB P/N 3G6430V00153, S/N 19334.
Standard ADs	EASA AD NO 2019-0073 (ASB 139-580)	ATA 64 TAIL ROTOR FULL ICE PROTECTION SYSTEM TAIL ROTOR BLADES INSPECTION / REPLACEMENT	-	-		TIC-AW139-21-0327 DATED 27 AUGUST 2021. NOT APPLICABLE DUE TO FIPS KIT NOT INSTALLED.
Standard ADs	EASA AD 2019-0149 (ASB 139-593 REV./)	ATA 71 - POWER PLAN - ENGINE MOUNTING RODS)	-	-		TIC-AW139-21-0328 DATED 27 AUGUST 2021 NOT APPLICABLE. AIRCRAFT NOT FITTED WITH AFFECTED SERIAL NUMBER. AIRCRAFT FITTED WITH PART NUMBER: 3G7120V00132, SERIAL NUMBER: 03998, 03999, 03990, 04001.
Standard ADs	EASA AD2019-0036 (SB139-567)	ATA 63 - MAIN ROTOR DRIVE - MAIN GEAR BOX BEARING LOCT NUT - REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2019-0174
Standard ADs	EASA AD 2019-0174 (ASB 139-567 REV.A)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2020-0011
Standard ADs	EASA AD NO 2017-0083 NEW ISSUE (SB 139-472)	ATA 62 - MAIN ROTOR - MAIN ROTOR SLIP RING - INSPECTION / REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0318 DATED 27 AUGUST 2021 NOT APPLICABLE. AIRCRAFT IS NOT INSTALLED WITH FULL ICE PROTECTION SYSTEMS.
Standard ADs	EASA AD 2016-0087	MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2016-0140
Standard ADs	EASA AD 2017-0160	ATA 62 MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2018-0112
Standard ADs	EASA AD 2019-0311, NEW ISSUE (SBA NO. 139-610, NEW ISSU	ATA 25, 95 EQUIPMENT / FURNISHINGS, EMERGENCY FLOTATION SYSTEM INFLATION HOSES INSPECTION	-	-	-/COMPLIED WITH	TIC-AW139-21-0329 DATED 27 AUGUST 2021 COMPLIED WITH SB-025-69-19. REFER TO ARC EASA FORM 1 0050038912/11616776 FOR PN 3G9560V02231 (SN 172-RH FWD FLOAT) & ARC EASA FORM 1 0050038909 / 11603417 (SN 182-LH FWD FLOAT)



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	6
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	AD NO. 2022-0287, NEW ISSUE	SEAT BELT RESTRAINT SYSTEM - INSPECTION	-	-	-/FOR INFO ONLY	TIC-GEN-22-0024 DATED 27 JANUARY 2022
						NOT APPLICABLE. GAM CAMO FLEET DO
						NOT MANAGE MBB-BK117 C-2, D-2 AND D-
						3 HELICOPTERS.
Standard ADs	AD NO. 2022-04-09, NEW ISSUE	OXYGEN CYLINDER AND VALVE ASSEMBLIES AND OXYGEN	-	-	-/FOR INFO ONLY	TIC-GEN-22-0057 DATED 01 MARCH 2022
		VALVE ASSEMBLIES				NOT APPLICABLE TO ALL GAM CAMO
						FLEET DUE TO AIRCRAFT TYPE NOT
						AFFECTED.
Standard ADs	AD NO. 2022-01-03, NEW ISSUE	UMLAUT ENGINEERING GMBH (PREVIOUSLY P3 ENGINEERING	-	-	-/FOR INFO ONLY	TIC-GEN-22-0039 03 FEBRUARY 2022
		GMBH) HAFEX (HALON-FREE) HAND-HELD FIRE EXTINGUISHERS				NOT APPLICABLE. GAM CAMO LEONARDO
						AND AIRBUS HELICOPTERS FLEET ARE
						ONLY AFFECTED BY EASA AD AND IN
						THIS CASE IT IS THE EASA AD 2020-0013.
Standard ADs	AD NO. 2022-03-15,NEW ISSUE	FUEL QUANTITY INDICATOR	-	-	-/NOT APPLICABLE	TIC-GEN-22-0045 DATED 15 FEBRUARY
						2022.
						NOT APPLICABLE TO ANY GAM CAMO
						FLEET DUE TO AIRCRAFT TYPE NOT
						AFFECTED.
Standard ADs	AD NO. 2022-0024, NEW ISSUE	FLIGHT MANAGEMENT COMPUTER 2 / NAVIGATION MODULES -	-	-	-/NOT APPLICABLE	TIC-GEN-22-0042 07 FEBRUARY 2022.
		OPE				NOT APPLICABLE. GAM CAMO FLEET NOT
						EQUIPPED WITH FLIGHT MANAGEMENT
						COMPUTER 2 NAVIGATION MODULES
						PART NUMBER: C13084CA03
Standard ADs	AD No. G-2021-003, NEW ISSUE	LIFE JACKET - INSPECTION	=	-	-/NOT APPLICABLE	TIC-GEN-21-0137 DATED 09 JUNE 2021.
						EMERGENCY BREATHING SYSTEM (EBS)
						PART NUMBER 12677009, AS FITTED TO
						THE SURVITEC HALO PASSENGER
						LIFEJACKET P/NS 00031010 AND 00031031.
						NOT APPLICABLE TO GAM CAMO FLEET.
Standard ADs	AD NO. G-2021-0004, NEW ISSUE	LIFE RAFT - INSPECTION	-	-	-/NOT APPLICABLE	TIC-GEN-21-0150 DATED 29 JUNE 2021
						SURVITEC LIFE RAFT WITH PACKED
						ASSEMBLY PART NUMBER 00051054
						(PORT) AND 00051055 (STARBOARD).
						NOT APPLICABLE TO GAM CAMO FLEETS.



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	7
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EAD No. G-2021-0010-E, NEW ISSUE	FUEL - CYLINDER QUICK SHUT-OFF VALVE MOUNTING FLANGE -	-	-	-/NOT APPLICABLE	TIC-GEN-21-0220 DATED 04 OCTOBER
		INSPECTION/REPLACEMENT				2021
						CAMEROON BALLON FUEL CYLINDERS
						WITH PART NUMBER: CB2901, CB2902,
						CB2903
						NOTE: NOT APPLICABLE TO GAM CAMO
						FLEET
Standard ADs	EASA AD NO. 2021-0185, REVISION 2	HAFES (HALON-FREE) HAND-HELD FIRE EXTINGUISHERS	-	-	-/NOT APPLICABLE	TIC-GEN-21-0194 DATED 16 AUGUST 2021
						HAFEX (HALON-FREE) HAND-HELD FIRE
						EXTINGUISHERS, HAVING PART NUMBER
						(P/N) P3APP003010A, P/N P3APP003010B
						OR P/N P3APP003010C, ALL SERIAL
						NUMBERS (S/N).
						NOT APPLICABLE TO GAM CAMO FLEET
ENGINE #1 AD						
Standard ADs	AD CF-2012-24	SECOND STAGE POWER TURBINE DISK DAMAGE (ENG #1)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0332
						NOT APPLICABLE DUE TO ENGINE IS
						POST-SB 41056.
ENGINE #2 AD	1.0.05.0010.01	ASSOCIATION DOWNER TURBUNE PROVIDENTAGE (FINE (12)			**************************************	T-10 AV4400 04 0000
Standard ADs	AD CF-2012-24	SECOND STAGE POWER TURBINE DISK DAMAGE (ENG #2)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0332
						NOT APPLICABLE DUE TO ENGINE IS
AIRFRAME ADS						POST-SB 41056.
Standard ADs	TACA AD 2045 0226 DEV 7 DADA 5 0 8	ATA 25- EQUIPMENT/FURNISHINGS- HOIST- TEST REPLACEMENT			/FOR INFO ONLY	TIC-AW139-22-0124 DATED 23 MAY 2022
Standard ADS	12	ATA 25- EQUIPMENT/FURNISHINGS- HUIST- TEST REPLACEMENT	-	-	-/FOR INFO ONLY	APPLICABILITY: APPLICABLE TO DUE TO
	12					COMPONENT GOODRICH HOIST P/N 44316
						-12-104 FITTED ON AIRCRAFT. FOR
						INFORMATION ONLY.
Standard ADs	EACA AD 2015 0226 DEV 7 DADA 1 2 8	ATA 25 - EQUIPMENT/FURNISHING - HOIST - TEST /			/COMPLIED WITH	TIC-AW139-22-0124 DATED 23 MAY 2022
Standard ADS	9	REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED BY OEM. REFER ANNEX 1
	3	REFLACEMENT				AIRWORTHINESS DIRECTIVE.
Standard ADs	EASA AD 2015-0226 REV 7 PARA 4	ATA 25-EQUIPMENT / FURNISHINGS - HOIST - TEST /			/COMPLIED WITH	TIC-AW139-22-0124 DATED 23 MAY 2022
Stanuaru ADS	LAGA AD 2013-0220 REV / PARA 4	REPLACEMENT	-	-	-/CONFLIED WITH	REFER TO ARC ATTACHED IN WP-PMF-20-
		INLFLACLIVILIVI				2095 at 77:30 FH ON 22/07/2021
Standard ADs	EASA AD 2015-0226 REV 7 PARA 10	ATA 25-EQUIPMENT/FURNISHINGS-HOIST-TEST/REPLACEMENT			/COMPLIED WITH	TIC-AW139-22-0124 DATED 23 MAY 2022
Statiuatu ADS	EASA AD 2015-0226 REV 7 PARA 10	A TA 20-EQUIFMENT/FURINISHINGS-HUIST-TEST/REPLACEMENT	-	-	-/COMPLIED WITH	
						FITTED ON AIRCRAFT. COMPLIED WITH.



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	8
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD 2015-0226, REV 7 PARA 11	ATA 25-EQUIPMENT/FURNISHINGS-HOIST-TEST/REPLACEMENT	-	-		TIC-AW139-22-0124 DATED 23 MAY 2022 CARRIED IN WP-PMF-20-2095 AT 77:30 FH ON 22/07/2021, DUE FOR 36M / 2600 HL WILL DUE ON 03/05/2024, REFER TO ARC ATTACHED IN WP-PMF-20-2095
Standard ADs	**EASA AD 2021-0259 PARA 1 (ASB 139 -686 PART I)	ATA 53 - TAIL GEAR BOX FITTING INSPECTION (TGB FITTING LESS THAN 3000FH)	-	-	-/CANCELLED	TIC-AW139-21-0396 SUPERSEEDED. REFER TIC-AW139-21-0404 FOR AD 2021- 0259 DATED 17 NOVEMBER 2021 CORRECTION DATED 22 NOVEMBER 2021
Standard ADs	EASA AD 2021-0259 (ASB 139-686) [CORRECTION]	ATA 53 - FUSELAGE - TAIL GEARBOX FITTING INSPECTION/REPLACEMENT, ONCE REACH 3000FH, COMPLIANCE WITHIN 25FH)	0.00	3025.00	-/TO BE COMPLIED	TIC-AW139-21-0404 TO COMPLY WITHIN 25FH ONCE EFFECTED COMPONENT REACH 3000FH SINCE INSTALLATION
Standard ADs	EASA AD 2021-0186 REV. 1 [CORRECTION]	ATA 25 - EQUIPMENT/FURNISHINGS - EXTERNAL HOIST ASSEMBLY - RATED LOAD CHECK	-	-	-/NOT APPLICABLE	TIC-AW139-21-0272 DATED 24 AUGUST 2021 NOT APPLICABLE DUE TO AFFECTED COMPONENT NOT FITTED ON AIRCRAFT. AIRCRAFT FITTED DIFFERENT MODEL TYPE HOIST. AIRCRAFT FITTED WITH GOODRICH HOIST.
Standard ADs	EASA AD 2021-0121, NEW ISSUE (ASB 139-609)	ATA 63 MAIN ROTOR DRIVE MAIN GEARBOX BEARING LOCK NUT REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0228 NOT APPLICABLE DUE TO COMPONENT MGB LOCK NUT PN 3G6320A09152 ALREADY FITTED ON AIRCRAFT
Standard ADs	EASA AD 2021-0095	ATA 11 - PLACARDS AND MARKINGS - STRETCHER UNIT/PLACARD - INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0209 COMPLIANCE: NOT APPLICABLE DUE TO COMPONENT 3-STRETCHER KIT P/N 139084-5001 NOT EQUIPPED ON AIRCRAFT
Standard ADs	EASA AD 2021-0054 (ASB 139-648 AND ASB 139-662)	ATA 25 - EQUIPMENT / FURNISHINGS - LIFE RAFT RESERVOIR AND ACTUATOR CABLE - REPLACEMENT / INSPECTION.	-	-	-/NOT APPLICABLE	TIC-AW139-21-0032 NOT APPLICABLE DUE TO COMPONENT EMERGENCY FLOATATION KIT P/N 4G9560F00111 OR P/N 4G9560F00211 NOT FITTED ON AIRCRAFT THE APPLICABLE SB: NOT APPLICABLE TO ASB 139-648 AND ASB 139-662



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	9
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD 2021-0044 REV 1 PARA (1)	ATA 24 OVERHEAD PANEL INSPECTION		-	-/COMPLIED WITH	TIC-AW139-22-0120 DATED 13 MAY 2022
	(ASB139-661 REV B)					CARRIED OUT 9M-PMF-6025 ON 12.03.2021
						AT 12:50 AFH.
Standard ADs	EASA AD 2020-0271 PARA (1) (SBA	ATA 62 MAIN ROTOR SWASHPLATE BOOT INSPECTION		-	-/COMPLIED WITH	TIC-AW139-20-201 DATED 09 DECEMBER
	139-654 REV./ PART I)					2020
						FIRST COMPLIANCE PART 1 SB139-654 AT
						12:50FH ON 14-DEC-2020 (AJL 03283) W/S
						2020/PMF//019-04 ON 09/12/2020
Standard ADs	EASA AD 2020-0011, REVISION 1	ATA 63 - MAIN GEAR BOX - BEARING LOCK NUT - REPLACEMENT	0.00	28000.00	-/SUPERSEDED	SUPERSEDED BY EASA AD 2020-0121
						DATED 04 MAY 2021
Standard ADs	EASA AD NO. 2020-0191 REV. 1 (ASB	ATA 25 - EQUIPMENT/FURNISHINGS FORWARD FACING CENTRAL	-	-	-/NOT APPLICABLE	TIC-AW139-20-132 DATED 07 SEPTEMBER
	NO. 139-633 REV./)	SEAT(S)-REMOVAL				2020
						NOT APPLICABLE DUE TO FORWARD
						FACING SEAT NOT FITTED ON FIRST
						ROW.
Standard ADs	EASA AD 2020-0185, NEW ISSUE	ATA 25- EQUIPMENT/ FURNISHINGS- LIFE RAFT RESERVOIR AND	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2021-0054
		ACTUATOR CABLE- REPLACEMENT/ INSPECTION				
Standard ADs	EASA AD 2020-0131 (SBA 139-637)	ATA 25 HOIST CABLE CUTTER FRAME INSTALLATION	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
						REFER TO ANNEX 1 - AIRWORTHINESS
						DIRECTIVES STATUS LIST FOR 9M-PMF
						DATED 29/07/2020.
Standard ADs	EASA AD NO. 2020-0013 (SB 139-614)	ATA 26 - FIRE PROTECTION - HAND-HELD FIRE EXTINGUISHERS -	-	-	-/NOT APPLICABLE	TIC-AW139-21-0330 DATED 27 AUGUST
		REPLACEMENT				2021.
						NOT APPLICABLE TO COMPONENT PN
						INSTALLED ON AIRCRAFT.
Standard ADs	EASA AD 2018-0130	ATA 62 - MAIN ROTOR - MAIN ROTOR BLADES - INSPECTION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0322 DATED 27 AUGUST
						2021
						NOT APPLICABLE DUE TO MAIN ROTOR
						BLADES ARE NOT AFFECTED BY THIS AD
Standard ADs	EASA AD 2018-0112R1	ATA 62 - MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION /		-	-/COMPLIED WITH	TIC-AW139-21-0321 DATED 27 AUGUST
		REPLACEMENT				2021
						COMPLIED WITH BY MANUFACTURE FOR
						PART A. NOT APPLICABLE FOR PART B
						DUE TO PART NUMBER AFFECTED.
Standard ADs	EASA AD 2017-0124R1	TIME LIMITS/ MAINTENANCE CHECKS - AIRWORTHINESS	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2018-0132
		LIMITATIONS				



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	10
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due Interval/Statu	Limitation Notes
Standard ADs	EASA AD 2017-0028-E	ATA 62 - MAIN ROTOR - ROTATING SCISSORS - INSPECTION /	-	/NOT APPLICABL	TIC-AW139-21-0315 DATED 27 AUGUST
		REPLACEMENT			2021
					NOT APPLICABLE. AIRCRAFT IS NOT
					FITTED WITH AFFECTED P/N
					3G6230V00654, BUT FITTED WITH P/N
					3G6230V00655.
Standard ADs	EASA AD 2011-0205R1	AT 55 STABILIZER TAIL FIN ASSEMBLY INSPECTION /	-	/SUPERSEDE	SUPERSEDED BY EASA AD 2017-0124R1
		REPLACEMENT			
Standard ADs	EASA AD 2017-0011 (BT 139-465 REV A	ATA 65 TAIL ROTOR - TAIL ROTOR DRIVE SHAFT - INSPECTION /	-	/NOT APPLICABL	REFER TIC-AW139-21-0317. NOT
)	MODIFICATION			APPLICABLE TO AIRCRAFT SERIAL
					NUMBER
Standard ADs	EASA AD 2016-0255R1	ATA 63 - MAIN ROTOR DRIVE - MAIN GEARBOX INPUT MODULE -	-	/NOT APPLICABL	TIC-AW139-21-0316 DATED 27 AUGUST
		REPLACEMENT			2021
					NOT APPLICABLE. THIS IS BECAUSE
					AIRCRAFT IS FITTED WITH MGB INPUT
					MODULE P/N 3K6320A00136 HAVING NOT
					AFFECTED S/N KHI-P22 AND S/N KHI-P26
Standard ADs	EASA AD 2016-0246	ATA 65 - TAIL ROTOR DRIVE - TAIL GEARBOX CENTRAL HOUSING	-	/NOT APPLICABL	TIC-AW139-21-0314 DATED 27 AUGUST
		- DIMENSIONAL CHECK / REPLACEMENT			2021.
					NOT APPLICABLE. AIRCRAFT IS NOT
					FITTED WITH AFFECTED CENTRAL
					HOUSING PART NUMBER (P/N
					3T6522A05144 OR P/N 3T6522A05146).
Standard ADs	EASA AD 2016-0140	MAI ROTOR - MAIN ROTOR DAMPER - INSPECTION /	-	/SUPERSEDE	SUPERSEDED BY EASA AD 2017-0160
		REPLACEMENT			
Standard ADs	EASA AD NO 2016-0077	LANDING GEAR - MAIN LANDING GEAR SHOCK ABSORBER	-	/NOT APPLICABL	TIC-AW139-21-0302 DATED 27 AUGUST
		SCREWS - REPLACEMENT			2021.
					NOT APPLICABLE DUE TO KIT INCREASED
					GROSS WEIGHT 6800 KG PART NUMBER
					4G0000F00111 NOT INSTALLED.
Standard ADs	EASA AD NO 2015-0172 (BT 139-374)	ATA 32 - LANDING GEAR- EMERGENCY FLOTATION SYSTEM	-	/NOT APPLICABL	TIC-AW139-21-0301 DATED 27 AUGUST
		CONTROL PANEL - REPLACEMENT			2021.
					NOT APPLICABLE, AIRCRAFT IS FITTED
					WITH PART NUMBER: 3G9560V00559
Standard ADs	EASA AD 2015-0160	EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	-	/SUPERSEDE	SUPERSEDED BY EASA AD 2015-0226



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	11
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD NO 2015-0155	ATA 30 - ICE AND RAIN PROTECTION - FULL ICE PROTECTION SYSTEM TAIL ROTOR SLIP RING-INSPECTION / REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0300 DATED 27 AUGUST 2021. NOT APPLICABLE DUE TO AIRCRAFT IS NOT EQUIPPED WITH FIPS.
Standard ADs	EASA AD 2006-0357R2	FUSELAGE - FRAME 5700 MIDDLE SECTION - INSPECTION	_	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2017-0124R1
Standard ADs	EASA AD 2015-0069	EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	-	-		SUPERSEDED BY EASA AD 2015-0160
Standard ADs	EASA AD 2014-0254	EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT	-	-		SUPERSEDED BY EASA AD 2015-0069
Standard ADs	EASA AD 2014-0215-E	MAIN ROTOR - ROTATING SCISSORS - INSPECTION / MODIFICATION	-	-		SUPERSEDED BY EASA AD 2017-0028-E
Standard ADs	EASA AD 2014-0201	EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2014-0254
Standard ADs	EASA AD NO 2014-0172	ATA 30 - ICE AND RAIN PROTECTION -FULL ICING PROTECTION SYSTEM / CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0299 DATED 27 AUGUST 2021. NOT APPLICABLE DUE TO AAIRCAFT NOT EQUIPPED WITH FIPS (FULL ICING PROTECTION SYSTEM).
Standard ADs	EASA AD 2014-0073-E	MAIN ROTOR - ROTATING CONTROLS - LOWER HALF SCISSOR SPHERICAL BEARING - INSPECTION / REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA EAD 2014-0215-E
Standard ADs	EASA AD 2014-0048 (BT 139-311 REV B)	ATA 53 - FUSELAGE - SUBFLOOR FRAME STA 2105 - INSPECTION / MODIFICATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0298 DATED 27 AUGUST 2021. NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
Standard ADs	EASA AD 2012-0076R2	ATA 64 - TAIL ROTOR-TAIL ROTOR BLADES-INSPECTION / REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0293 NOT APPLICABLE DUE TO AIRCRAFT ALREADY FITTED WITH SERVICEABLE T/R BLADE P/N 3G6410A00133
Standard ADs	EASA AD 2014-0028	ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM / CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2014-0172
Standard ADs	EASA AD 2013-0298	ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM / CABLE INSPECTION TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT	-	-		SUPERSEDED BY EASA AD 2014-0028
Standard ADs	EASA AD 2013-0275R1	EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2014-0201



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07/03/2023	Page No:	12
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1: 915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD NO 2013-0177	ATA 29 - HYDRAULIC POWER - FLEXIBLE HYDRAULIC HOSES -	-	-	-/NOT APPLICABLE	TIC-AW139-21-0297 DATED 27 AUGUST
		REPLACEMENT				2021
						NOT APPLICABLE DUE TO MODIFICATION
						ALREADY INCORPORATED IN THE
						HELICOPTER.
Standard ADs	EASA AD 2013-0174	ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2013-0298
		CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT				
Standard ADs	EASA AD 2010-0237-CN	CANCELLED: EQUIPMENT / FURNISHINGS - SPECTROLAB	-	-	-/CANCELLED	TIC-AW139-21-0296
		NIGHTSUN XP SEARCHLIGHT - INSPECTION / REMOVAL /				AD CANCELLED.
		REPLACEMENT				
Standard ADs	EASA AD 2013-0124	ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2013-0174
		CABLE INSPECTION - TAIL ROTOR DISTRIBUTOR REPLACEMENT				
Standard ADs	EASA AD 2013-0090	ICE AND RAIN PROTECTION - FULL ICING PROTECTION SYSTEM /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2013-0124
		CABLES - INSPECTION				
Standard ADs	EASA AD 2013-0077R1	EQUIPMENT / FURNISHING - HOIST - INSPECTION /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2013-0275
		REPLACEMENT				
Standard ADs	EASA AD 2013-0065-E	EQUIPMENT / FURNISHING - HOIST - INSPECTION /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2013-0077-E
		REPLACEMENT				
Standard ADs	EASA AD NO 2012-0262	ATA 32 - LANDING GEAR - NOSE LANDING GEAR ARM PIN	-	-	-/NOT APPLICABLE	REFER TIC-AW139-21-0295. NOT
		INSTALLATION - INSPECTION				APPLICABLE TO AIRCRAFT SERIAL
						NUMBER.
Standard ADs	EASA AD NO 2012-0213-E	ATA 27 - FLIGHT CONTROL -COLLECTIVE AND CYCLIC CONTROL	-	-	-/NOT APPLICABLE	REFER TIC-AW139-21-0294. NOT
		SYSTEM -INSPECTION / RESTORATION				APPLICABLE. REASON: DUE TO AIRCRAFT
						S/N NOT AFFECTED.
Standard ADs	EASA AD 2012-0030	TAIL ROTOR TAIL ROTOR BLADES INSPECTION / REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2012-0076
Standard ADs	EASA AD NO 2011-0226-E	ATA 27 - FLIGHT CONTROL - COLLECTIVE CONTROL SYSTEM-	-	-	-/NOT APPLICABLE	TIC-AW139-21-0292 DATED 27 AUGUST
		INSPECTION/INSTALLATION				2021.
						NOT APPLICABLE DUE TO AIRCRAFT S/N
						NOT AFFECTED.
Standard ADs	EASA AD NO 2011-0207	ATA 29 - HYDRAULIC POWER - HYDRAULIC SYSTEM -	-	-	-/COMPLIED WITH	TIC-AW139-21-0291
		OPERATIONAL CHECKS/ REPLACEMENT				APPLICABLE TO AIRCRAFT S/N.
						COMPLIED WITH. OPERATIONAL CHECK
						PERFORMED DURING PRODUCTION.
						REFER ANNEX 1 - AIRWORTHINESS
						DIRECTIVES.
Standard ADs	EASA AD 2006-0358R1	STABILIZERS - FIN ASSEMBLY - INSPECTION/REPLACEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2011-0205
Standard ADs	EASA AD 2011-0156-E	TAIL ROTOR - TAIL ROTOR BLADES - INSPECTION /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2012-0030
		REPLACEMENT [REDUCED LIFE LIMITATION]				



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	13
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD NO 2011-0140, NEW ISSUE	ATA 23 - COMMUNICATIONS - PRIMUS EPIC SYSTEM HARNESSES	-	-	-/NOT APPLICABLE	TIC-AW139-21-0290
		SOLDER SPLICES - INSPECTION / REPLACEMENT				NOT APPLICABLE DUE TO AIRCRAFT S/N
						NOT AFFECTED.
Standard ADs	EASA AD 2011-0081	TAIL ROTOR - TAIL ROTOR BLADES - INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2011-0156-E
Standard ADs	EASA AD NO 2011-0019	ATA 53 - FUSELAGE - TAIL BOOM - INSPECTION / MODIFICATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0289
						NOT APPLICABLE DUE TO AIRCRAFT
						FITTED WITH TAIL ASSY P/N
						3G5350A00136.
Standard ADs	EASA AD 2010-0189	NAVIGATION - MODULAR AVIONIC UNIT - INSPECTION /	-	-	-/NOT APPLICABLE	TIC-AW139-21-0288
		REPLACEMENT / MODIFICATION				NOT APPLICABLE TO AIRCRAFT SERIAL
						NUMBER BECAUSE THIS AD ONLY
						APPLICABLE TO AIRCRAFT FROM S/N
						31005 TO S/N 31157 (EXCEPT S/N 31007,
						S/N 31094 AND S/N 31149) AND FROM S/N
						41001 TO S/N 41023.
Standard ADs	EASA AD 2010-0183R1	EQUIPMENT / FURNISHINGS - SPECTROLAB NIGHTSUN XP	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2010-0237
		SEARCH				
Standard ADs	2009-0183-CN	CANCELLATION NOTICE: EQUIPMENT/FURNISHING - D -LOCK	-	-	-/NOT APPLICABLE	TIC-AW139-21-0287
		HOOK OF THE RESCUE HOIST				NOT APPLICABLE. CANCELLATION
						NOTICE.
Standard ADs	EASA AD 2009-0234-ER1	FUSELAGE - TAIL BOOM - INSPECTION	-	-		SUPERSEDED BY EASA AD 2011-0019
Standard ADs	EASA AD 2009-0198-E	FUSELAGE - TAIL BOOM - INSPECTION	-	-		SUPERSEDED BY EASA AD 2009-0234-E
Standard ADs	EASA AD 2009-0179-E	EQUIPMENT/FURNISHING - D-LOCK HOOK OF THE RESCUE HIOST	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2009-0183-E
		- INSPECTION/REMOVAL FROM SERVICE/REPLACEMENT				
Standard ADs	EASA AD 2009-0148-E	EQUIPMENT/FURNISHING - D-LOCK HOOK OF THE RESCUE HIOST	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2009-0179-E
		- INSPECTION/REMOVAL FROM SERVICE/REPLACEMENT				
Standard ADs	EASA AD 2009-0124	EQUIPMENT/FURNISHING - LIFESAVING SYSTEMS' D-LOCK HOOK	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2009-0148-E
		OF THE RESCUE HIOST - INSPECTION/REPLACEMENT				
Standard ADs	EASA AD NO 2009-0042	ATA 24 - ELECTRICAL POWER - GENERATOR CONTROL UNIT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0286
		(GCU) - REPLACEMENT				NOT APPLICABLE DUE TO DIFFERENT
						PART NUMBER
Standard ADs	EASA AD 2008-0157	FUSELAGE - TAIL BOOM ASSEMBLY - INSPECTION / REPAIR /	-	-	-/SUPERSEDED	SUPERSEDED BY EASA AD 2009-0198-E
		REPLACEMENT				
Standard ADs	EASA AD NO 2008-0148	ATA 53 - FUSELAGE - WIRE STRIKE PROTECTION SYSTEM (WSPS)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0285
		TOP CABLE CUTTER - REWORK / REPLACEMENT				NOT APPLICABLE DUE TO A/C NOT
						EQUIPPED WITH WIRE STRIKE
						PROTECTION SYSTEM.



Aircraft Registration:	9M-PMF	Serial No:	31913	Date: 07	7/03/2023	Page No:	14
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1:	915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due Interval/Status	Limitation Notes
Standard ADs	EASA AD 2008-0108	ATA 56 - WINDOWS - COCKPIT DOOR WINDOWS - REPLACEMENT	-	/NOT APPLICABLE	TIC-AW139-21-0305 DATED 27 AUGUST 2021. NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
Standard ADs	EASA AD 2008-0011	WINDOWS - COCKPIT DOORS WINDOWS AND SEALING - INSPECTION/REPAIR/REPLACEMENT/MODIFICATION	-	/SUPERSEDED	SUPERSEDED BY EASA AD 2008-0108
Standard ADs	EASA AD 2007-0142	WINDOWS - COCKPIT DOORS WINDOWS SEALING - INSPECTION/REPAIR/REPLACEMENT	-	/SUPERSEDED	SUPERSEDED BY EASA AD 2008-0011
Standard ADs	EASA AD NO 2006-0360-E	ATA 78 - EXHAUST - TAILPIPE ASSEMBLY - INSPECTION/REPAIR/REPLACEMENT	-	/NOT APPLICABLE	TIC-AW139-21-0284 NOT APPLICABLE DUE TO TAILPIPE ASSEMBLIES AFFECTED BY THIS AD ARE NOT INSTALLED ON AIRCRAFT
COMPONENT ADS	s			·	
Standard ADs	AD NO. 2019-0235	ATA 25 - EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION/MODIFICATION/REPLACEMENT	-	/NOT APPLICABLE	TIC-AW139-21-0313 DATED 27 AUGUST 2021 NOT APPLICABLE TO THIS AIRCRAFT BECAUSE AIRCRAFT IS NOT FITTED WITH ANY AFFECTED ELT. AIRCRAFT FITTED WITH ELT 453-5001-247 S/N 210-10552.
Standard ADs	EASA AD 2014-0125	ATA 25 - EQUIPMENT/FURNISHINGS - CRASH POSITION INDICATOR SYSTEM - REPLACEMENT ; AIRCRAFT FLIGHT MANUAL - AMENDMENT	-	/NOT APPLICABLE	TIC-AW139-21-0311 DATED 27 AUGUST 2021 NOT APPLICABLE. KIT ELT DEPLOYABLE NOT INSTALLED.
Standard ADs	EASA AD NO 2010-0062R1	FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHER - IDENTIFICATION / REPLACEMENT	-	/NOT APPLICABLE	TIC-AW139-21-0308 DATED 27 AUGUST 2021 NOT APPLICABLE DUE TO AIRCRAFT EQUIPPED WITH DIFFERENT MANUFACTURER.
Standard ADs	EASA AD NO 2009-0262R1	FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHER - IDENTIFICATION / REPLACEMENT	-	/NOT APPLICABLE	TIC-AW139-21-0307 DATED 27 AUGUST 2021. NOT APPLICABLE. AFFECTED PN NOT FITTED IN AIRCRAFT.
Standard ADs	EASA AD NO 2009-0251-E	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER - IDENTIFICATION / REPLACEMENT	-	/NOT APPLICABLE	TIC-AW139-21-0306 DATED 27 AUGUST 2021. NOT APPLICABLE DUE TO FIRE EXTINGUISHERS INSTALLED ON HELICOPTER ARE NOT AFFECTED BY THIS AD.



Aircraft Registration:	9M-PMF	Serial No:	31913	Date:	07/03/2023	Page No:	15
Aircraft Hours:	915:05	Landings:	1612.00	Engine 1	1: 915:05	Engine 2:	915:05

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard ADs	EASA AD NO 2007-0256	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM	-	-	-/NOT APPLICABLE	TIC-AW139-21-0304 DATED 27 AUGUST
		PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT				2021
						NOT APPLICABLE DUE TO DIFFERENT
						EQUIPMENT INSTALLED.
Standard ADs	EASA AD NO 2007-0156	COMMUNICATION - COMM UNITS & TRANSPONDERS -	-	-	-/NOT APPLICABLE	TIC-AW139-21-0303 DATED 27 AUGUST
		MODIFICATION/REPLACEMENT				2021
						NOT APPLICABLE DUE TO MODE S
						TRANSPONDER INSTALLED ON AIRCRAFT
						IS NOT AFFECTED BY THIS AD.
Standard ADs	EASA AD 2015-0226 REV 7 PARA 6	ATA 25- EQUIPMENT/FURNISHING-HOIST-TEST/REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0124 DATED 23 MAY 2022
						NOT COMPLIED DUE TO HOIST
						INSTALLED WITH NEW OVERCLUTCH
						ASSEMBLY.
Standard ADs	EASA SIB NO. 2021-14, NEW ISSUE	HAND-OPERATED FIRE EXTINGUISHERS - REMOVAL FROM	-	-	-/FOR INFO ONLY	TIC-GEN-21-0154 DATED 02 JULY 2021
		SERVICE				NOT APPLICABLE. FOR INFORMATION
						ONLY.
Standard ADs	AD NO. 2007-0256-CN, NEW ISSUE	ATA 25 - EQUIPMENT AND FURNISHING - SEAT RESTRAINT	-	-	-/CANCELLED	REFER TIC-AW139-21-0304. NOT
		SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION /				APPLICABLE DUE AD CANCELLED
		REPLACEMENT				