

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	1
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
SBs						
Types	SB Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive SBs	BT 139-452 REV A PART II	MAIN ROTOR (MR) DAMPER BODY END	-	00/00/0000	0	PART II: MAIN ROTOR DAMPERS NOT AFFECTED BY PART NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Repetitive SBs	SB 139-728 PART I (50FH)	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS	23/04/2023	00/00/0000	2	LAST DONE WP NO 9M-JPM-13323 AT 153:02 FH ON 11-DEC-22 (AJL 03808) APPLICABLE DUE TO COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 FITTED ON AIRCRAFT AND HAS NOT BEEN REMOVED AND REINSTALLED ON SLIDER CONTROL ASSEMBLY P/N 3G6430A02531 COMPLIANCE: WITHIN AND NOT LATER THAN 50 FH OR 2 MONTHS WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN AND THEN EVERY 50 FH REFER TIC-AW139-22-0235

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	2
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive SBs	SB 139-728 PART I (50FH)	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS	244:22	294:22	50	<p>LAST DONE WP NO 9M-JPM-16107 AT 244:22 FH ON 16-AUG-23 (AJL 05429) LAST DONE 9M-JPM-14478 AT 197:12FH ON 23-APR-23 (AJL 03845) LAST DONE WP NO 9M-JPM-13323 AT 153:02 FH ON 11-DEC-22 (AJL 03808)</p> <p>APPLICABLE DUE TO COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 FITTED ON AIRCRAFT AND HAS NOT BEEN REMOVED AND REINSTALLED ON SLIDER CONTROL ASSEMBLY P/N 3G6430A02531</p> <p>COMPLIANCE: WITHIN AND NOT LATER THAN 50 FH OR 2 MONTHS WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN AND THEN EVERY 50 FH</p> <p>REFER TIC-AW139-22-0235</p>
Repetitive SBs	SBA139-724 REV. B (EASA AD 2022-0205) (50FH/6M)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	23/04/2023	23/10/2023	6	<p>TIC-AW139-22-0204</p> <p>APPLICABILITY: APPLICABLE DUE TO COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLIES P/N 3G6420A06131 FITTED ON AIRCRAFT.</p> <p>-</p> <p>LAST DONE 9M-JPM-13634 AT 197:12 AFH ON 23-APR-23 (AJL 03845) LAST DONE 9M-JPM-13000 AT 151:42 AFH ON 01-DEC-22 (AJL 03806)</p>

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	3
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive SBs	SBA139-724 REV. B (EASA AD 2022-0205) (50FH/6M)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	197:12	247:12	50	TIC-AW139-22-0204 APPLICABILITY: APPLICABLE DUE TO COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLIES P/N 3G6420A06131 FITTED ON AIRCRAFT. - LAST DONE 9M-JPM-13634 AT 197:12 AFH ON 23-APR-23 (AJL 03845) LAST DONE 9M-JPM-13000 AT 151:42 AFH ON 01-DEC-22 (AJL 03806)
Repetitive SBs	SB 139-725 REV A (PART IV)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0:00	2400:00	2400	TO BE COMPLIED BEFORE AFFECTED PART REACHED 2400 FH. REFER TIC-AW139-22-0167
Repetitive SBs	SBEA 139-725 REV. A PART I (EASA AD 2022-0182 PARA 1)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	0	NOT APPLICABLE DUE TO COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 HAVE NOT BEEN REMOVED AND REINSTALLED ON COMPONENT SLIDING CONTROL ASSEMBLY P/N 3G6430A02531. REFER TIC-AW139-22-0167
Repetitive SBs	SBA139-661 REV.B PART II (EASA AD 2021-0044R1 PARA)	300FH//1Y - ATA 24 OVERHEAD PANEL INSPECTION	0:00	0:00	300	APPLICABLE DUE TO AIRCRAFT S/N AFFECTED,EVERY THREE HUNDRED (300) FH OR ONE (1) YEAR WHICHEVER OCCURS FIRST AFTER THE COMPLIANCE OF PART I OF THIS SERVICE BULLETIN REFER TIC-AW139-22-0116
Repetitive SBs	SBA139-661 REV.B PART II (EASA AD 2021-0044R1 PARA)	300FH//1Y - ATA 24 OVERHEAD PANEL INSPECTION	-	00/00/0000	1	APPLICABLE DUE TO AIRCRAFT S/N AFFECTED,EVERY THREE HUNDRED (300) FH OR ONE (1) YEAR WHICHEVER OCCURS FIRST AFTER THE COMPLIANCE OF PART I OF THIS SERVICE BULLETIN REFER TIC-AW139-22-0116
Repetitive SBs	SB 139-526 REV / PART II	ATA 63 MGB OIL COOLING FAN INSPECTION	0:00	1200:00	1200	PART II: APPLICABLE ONCE THE COOLING FANS LOGGED REACHED BETWEEN 700 FH AND 1200 FH SINCE NEW OR SINCE LAST OVERHAUL. REPETITIVE EVERY 1200 FH

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	4
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive SBs	ASB139-654 PART II (EASA AD 2020-0271 PARA (2)) (50FH)	ATA 62 - MAIN ROTOR SWASHPLATE BOOT INSPECTION	244:23	294:23	50	<p>PART I: COMPLIED WITH BY MANUFACTURER. INSPECTION / ADHESIVE RESTORING PERFORMED AT 07.55 FH</p> <p>PART II: APPLICABLE.</p> <p>LAST DONE 9M-JPM-15410 AT 244:22FH ON 12-AUG-23 (AJL 05428) LAST DONE 9M-JPM-14921 AT 197:12FH ON 23-APR-23 (AJL 03845) LAST DONE 9M-JPM-12493 AT 160:32FH ON 31-JAN-23 (AJL 03819) LAST DONE - WP NO. 9M-JPM-11016 AT 119:07FH ON 27-MAY-22 (AJL 06161)</p>
Standard SBs	25 FH BT 139-467 - PART I REV A	TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET	-	-	-/INFO - MANDATORY	<p>PART I: APPLICABLE ONCE HELICOPTER WITHIN 25 FH AND THEN EVERY 25 FH ON GOING.</p> <p>17/02/2021 - OEM MAINTENANCE LOG BOOK C/O AT 15:55FH</p> <p>-</p> <p>LAST DONE: WP NO. 9M-JPM-9489 AT 95:12 FH ON 11-MAR-22</p>
Standard SBs	SB 139-688 NEW ISSUE	ATA 31 - KIT FAMILY HUMS INSTALLATION	-	-	-/OPTIONAL	<p>REFER TIC-AW139-23-0111</p> <p>APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER 31899. AT CUSTOMER'S OPTION</p>
Standard SBs	SBEA 139-725 REV. A PART II (EASA AD2022-0182 PARA 2)	ATA 64- TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	<p>NOT APPLICABLE DUE TO COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 HAVE NOT BEEN REMOVED AND REINSTALLED ON COMPONENT SLIDING CONTROL ASSEMBLY P/N 3G6430A02531</p> <p>REFER TIC-AW139-22-0167</p>

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	5
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-747, NEW ISSUE	ATA 53 - CABIN TIE DOWN (AMMO BOX) INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0277 NOT APPLICABLE TO AIRCRAFT S/N
Standard SBs	SB NO. 139-371 REV. A	ATA 25 - INSTALLATION OF HOIST PENDANT VARIANT P/N 3G2591A08211	-	-	-/NOT APPLICABLE	TIC-AW139-23-0273 1) NOT APPLICABLE DUE TO AIRCRAFT S/N IS NOT AFFECTED. 2) NOT APPLICABLE DUE TO AIRCRAFT S/N IS NOT AFFECTED. 3) NOT APPLICABLE DUE TO THE AIRCRAFT IS NOT EQUIPPED WITH HOIST COMPLETE PROVISION P/N 4G2591A01013 (DOUBLE HOIST) OR P/N 4G2591A01113 (SINGLE HOIST) AND TRACK P/N 3G5330A01251 (STA3900).
Standard SBs	SB NO. 139-469, REV. A	ATA 30 - PASSENGER CABIN DRAINAGES INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-23-0269 APPLICABLE DUE TO AIRCRAFT S/N IS AFFECTED. AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-764, NEW ISSUE	ATA 99 - MILDS SENSOR SOFTWARE UPGRADE	-	-	-/NOT APPLICABLE	TIC-AW139-23-0264 NOT APPLICABLE DUE TO AIRCRAFT S/N IS NOT AFFECTED.
Standard SBs	SB NO. 139-759 NEW ISSUE	ATA 11 - ADDITIONAL MARKINGS FOR CS26 AMDT 4 KIT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0260 NOT APPLICABLE DUE TO AIRCRAFT NOT OPERATED UNDER EASA AUTHORITY, NO CHANGES TO AW139 TCDS BY EASA
Standard SBs	SB NO. 139-639, REV. A	ATA 53 - UPPER DECK PANEL REINFORCEMENT	-	-	-/OPTIONAL	TIC-AW139-23-0256 APPLICABLE DUE TO AIRCRAFT S/N IS AFFECTED AND FITTED WITH KIT A/C PROVISION DUAL ZONE CABIN CONTROL PANEL P/N 4G2150F00611. AT CUSTOMER'S OPTION

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	6
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-711 NEW ISSUE	ATA 52 - PILOT HIGH VISIBILITY DOORS KIT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0252 NOT APPLICABLE DUE TO AIRCRAFT S/N IS NOT AFFECTED.
Standard SBs	SB NO. 139-700, NEW ISSUE	ATA 46 - PRIMUS EPIC® FLIGHT SOFTWARE RELEASE 8 (WITH ADG-400) UPGRADE	-	-	-/OPTIONAL	TIC-AW139-23-0248 APPLICABLE TO AIRCRAFT CURRENT PRIMUS SOFTWARE COMPLIANCE: OPTIONAL FOR PART I AND II. NOT APPLICABLE FOR PART III
Standard SBs	SB 139-587 REV. A	WINDSHIELD WASHING SYSTEM INSTALLATION	-	-	-/OPTIONAL	REFER TIC-AW139-23-0242 APPLICABLE IF AIRCRAFT FITTED WITH WIPER ARM LH P/N 3G3040V00951 AND WIPER ARM RH P/N 3G3040V01051.
Standard SBs	SB139-653 NEW ISSUE	ATA 21 - KIT HEATING RETROFIT	-	-	-/OPTIONAL	REFER TIC-AW139-22-0370 APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED.
Standard SBs	SB139-652 NEW ISSUE	ATA 21 - AIR CONDITIONING KIT INSTALLATION	-	-	-/OPTIONAL	REFER TIC-AW139-22-0366 APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED. OPTIONAL. DEPEND ON CUSTOMER DECISION.
Standard SBs	SB NO. 139-155, REV. C PART II & PART III	ATA 33 2ND ANTICOLLISION LIGHT KIT INSTALLATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0189 PART II - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED PART III - NOT APPLICABLE DUE TO AIRCRAFT ALREADY FITTED WITH 2ND ANTI COLLISION LIGHT P/N 4G3340F00612.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	7
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-155, REV. C PART I & PART IV	ATA 33 2ND ANTICOLLISION LIGHT KIT INSTALLATION	-	-	-/OPTIONAL	REFER TIC-AW139-23-0189 PART I - APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED PART IV - APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB NO. 139-266, REV. B PART I & II	ATA 25 - INSTALLATION OF KIT BAMBI BUCKET PROVISION	-	-	-/OPTIONAL	REFER TIC-AW139-23-0185 PART I AND II - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED PART III - APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB139-516 REV. A PART III, PART I, PART II, PART IV & PA	ATA 95 - EMERGENCY FLOTATION AND LIFE RAFT SYSTEMS CONVERSION TO DART INTEGRATED SYSTEM	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0178 PART I, II, IV, V - NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH DIFFERENT COMPONENT PART NUMBER PART III - NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-714, NEW ISSUE	ATA 25 - LIFE RAFT CABLES RETROMOD	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0174 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH KIT PART NUMBER 4G9560F00111 & 4G9560F00211
Standard SBs	41119, REVISION 5	ENGINE #2 TURBOSHAFT ENGINE IGNITION EXCITER - REPLACEMENT OF	-	-	-/OPEN	REFER TIC-AW139-23-0169 APPLICABLE TO THIS AIRCRAFT ENGINE S/N CATEGORY 7, TO BE COMPLIED WITH WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	8
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41119, REVISION 5	ENGINE #1 TURBOSHAFT ENGINE IGNITION EXCITER - REPLACEMENT OF	-	-	-/OPEN	REFER TIC-AW139-23-0169 APPLICABLE TO THIS AIRCRAFT ENGINE S/N CATEGORY 7, TO BE COMPLIED WITH WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	SB NO. 139-624, REV A PART I	ATA 23 - SATCOM SKYTRACK ISAT-200A KIT INSTALLATION	-	-	-/OPTIONAL	REFER TIC-AW139-23-0162 PART I - APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB NO. 139-624, REV A PART II & III	ATA 23 - SATCOM SKYTRACK ISAT-200A KIT INSTALLATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0162 PART II - NOT APPLICABLE DUE TO AIRCRAFT NOT EQUIPPED WITH KIT SATCOM ISAT-200A COMPLETE PROVISION P/N 3G2310A13511 PART III - NOT APPLICABLE DUE TO AIRCRAFT NOT EQUIPPED WITH KIT SATCOM SKYTRACK ISAT-200A P/N 4G2310F03012
Standard SBs	SB NO. 139-401, REV A PART II	ATA 97 - KIT COCKPIT LIPSTICK CAMERA INSTALLATION	-	-	-/OPTIONAL	REFER TIC-AW139-23-0133 OPTIONAL FOR PART II, AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-401, REV A PART I	ATA 97 - KIT COCKPIT LIPSTICK CAMERA INSTALLATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0133 PART I NOT APPLICABLE
Standard SBs	SB NO. 139-708, NEW ISSUE	ATA 97 - KIT HOIST BREEZE HD CAMERA P/N 4G9750F01211 INSTALLATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0232 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH KIT HOIST
Standard SBs	SB NO. 139-675, REV.A	ATA 97 - KIT CABIN CAMERA SOFT LINER INSTALLATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0227 NOT APPLICABLE TO AIRCRAFT S/N

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	9
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-757, NEW ISSUE	ATA 62 - MAIN ROTOR RETROMOD P/N 3G6200P00111 INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0193 DATED 22 JUNE 2023 NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH MAIN ROTOR P/N 3G6220A00134.
Standard SBs	SB NO. 139-727, NEW ISSUE	ATA 63 - MAIN GEARBOX CASE REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0330 DATED 16 NOVEMBER 2022 NOT APPLICABLE DUE TO COMPONENT MAIN GEARBOX (MGB) P/N 4G6320A00133 AND P/N 4G6320A00132 NOT FITTED ON AIRCRAFT.
Standard SBs	NO. 1 ENGINE - SB NO. 41052, REV.2	TURBOSHAFT ENGINE - OIL TRAY, ACCESSORY GEARBOX - REPLACEMENT /MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-22-0348 DATED 07 DECEMBER 2022 NOT APPLICABLE TO THIS ENGINE DUE TO SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-495, REV B	ATA 31 - FDR AND RIPS VARIANT ULB REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO MPFR P/N D51615-142 NOT FITTED ON AIRCRAFT. FITTED P/N D51615-102. REFER TIC-AW139-23-0129
Standard SBs	SB NO. 139-495, REV B	ATA 31 - FDR AND RIPS VARIANT ULB REPLACEMENT	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0129 NOT APPLICABLE DUE TO MPFR P/N D51615-142 NOT FITTED ON AIRCRAFT. FITTED P/N D51615-102
Standard SBs	SBA NO. 139-734, REV A	ATA 25 - LIFE RAFT INFLATION SYSTEM REPLACEMENT	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0123 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH APPLICABLE LIFE RAFT
Standard SBs	SB NO. 139-401, REV. A	ATA 97 - KIT COCKPIT LIPSTICK CAMERA INSTALLATION	-	-	-/OPTIONAL	PART I: NOT APPLICABLE. PART II: OPTIONAL REFER TIC-AW139-23-0133
Standard SBs	SB NO. 139-738, NEW ISSUE	ATA 53 TAIL BOOM ASSY CORROSION PREVENTION IMPROVEMENT	-	-	-/OPTIONAL	APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION. REFER TIC-AW139-23-0139

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	10
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-705, NEW ISSUE	ATA 34 KIT EGPWS - 034 INSTALLATION	-	-	-/OPTIONAL	APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION. REFER TIC-AW139-23-0145
Standard SBs	SBA NO. 139-734, REV A	ATA 25 - LIFE RAFT INFLATION SYSTEM REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-23-0123 DATED 02 MAY 2023 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH APPLICABLE LIFE RAFT
Standard SBs	SB NO. 139-684, REV B	ATA 93 - TURRET FLIR UNIT REPLACEMENT	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0099 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB 139-717, NEW ISSUE	ATA 31 - KIT QUICK ACCESS RECORDER (HOMP)	-	-	-/OPTIONAL	TIC-AW139-23-0011 DATED 13 JANUARY 2023 APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED.
Standard SBs	SB NO. 139-604, REVISION A	ATA 66 - INSTALLATION OF KIT MOORING	-	-	-/OPTIONAL	TIC-AW139-23-0021 DATED 31 JANUARY 2023 APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED.
Standard SBs	SB NO. 139-733, NEW ISSUE	ATA 95 - INSPECTION OF SEALANT OF RIGID COVERS OF EMERGENCY FLOTATION SYSTEM	-	-	-/NOT APPLICABLE	TIC-AW139-23-0025 DATED 03 FEBRUARY 2023 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH EFS REMOVABLE PARTS RIGID COVER PYROT P/N 3G9560A04211 AND/OR EFS REMOVABLE PARTS RIGID COVER SMA P/N 3G9560A04212.
Standard SBs	SB NO. 139-683, NEW ISSUE	ATA 52 - COCKPIT DOOR POCKET LH INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0056 DATED 23 FEBRUARY 2023 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH HIGH VISIBILITY DOORS.
Standard SBs	SB NO. 139-514, REVISION A	ATA 52 - INSTALLATION OF KIT SAR PROTECTION STEP	-	-	-/OPTIONAL	TIC-AW139-23-0065 DATED 17 MARCH 2023 APPLICABLE DUE TO KIT FOOTSTEPS PILOT P/N 3G5260F00112 FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-169, REVISION A	ATA 33 - 2ND SEARCH LIGHT KIT P/N 4G3340F01811 INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0084 DATED 28 MARCH 2023 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	11
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	EASB 139-754 PART III (AD No.: 2023-0071-E)	ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO P/N MENTIONED DOES NOT INSTALLED IN AIRCRAFT. LAST DONE 9M-JPM-15129 AT 191:27FH ON 01-APR-23 (AJL 03838)
Standard SBs	EASB 139-754 PART II (AD No.: 2023-0071-E)	ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	-	-	-/NOT APPLICABLE	
Standard SBs	EASB 139-754 PART I (AD No.: 2023-0071-E)	ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO P/N MENTIONED DOES NOT INSTALLED IN AIRCRAFT. LAST DONE 9M-JPM-15129 AT 191:27FH ON 01-APR-23 (AJL 03838)
Standard SBs	SB NO. 139-034, REVISION D	ATA 23 - INSTALLATION OF HF KIT P/N 3G2310F00211	-	-	-/NOT APPLICABLE	TIC-AW139-23-0037 DATED 13 FEBRUARY 2023 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO.139-680, NEW ISSUE	ATA 23 - ICS CABIN (12-15 PAX) RIGID LINERS KIT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-23-0006 DATED 11 JANUARY 2023 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-682, NEW ISSUE	ATA 24 - AUXILIARY OVERHEAD PANEL AND INTERSEAT CONSOLE	-	-	-/NOT APPLICABLE	TIC-AW139-23-0002 DATED 11 JANUARY 2023 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-682 REV./	ATA 24 - AUXILIARY OVERHEAD PANEL AND INTERSEAT CONSOLE MODIFICATIONS	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0002.NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-680 REV./	ATA 23 - ICS CABIN (12-15 PAX) RIGID LINERS KIT INSTALLATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0006. NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB 139-717 REV./	ATA 31 - KIT QUICK ACCESS RECORDER (HOMP)	-	-	-/OPTIONAL	REFER TIC-AW139-23-0011. APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED.OPTIONAL. DEPENDS ON CUSTOMERS DECISION.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	12
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	139-604 REV A	ATA 66 - INSTALLATION OF KIT MOORING	-	-	-/OPTIONAL	REFER TIC-AW139-23-0021. APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED. OPTIONAL. DEPEND ON CUSTOMER DECISION.
Standard SBs	139-034 REV D	ATA 23 - INSTALLATION OF HF KIT P/N 3G2310F00211	-	-	-/NOT APPLICABLE	REFER TIC-AW139-23-0037. NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-672, NEW ISSUE (PART I)	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	160.53	-	-/COMPLIED WITH	LAST DONE WP NO: 9M-JPM-13906 AT 160:32FH ON 24-JAN-2023 (AJL 03819) PART I: WITHIN AND NOT LATER THAN 300 FH OR 6 MONTHS WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN REFER TIC-AW139-22-0218
Standard SBs	SB NO. 139-672, NEW ISSUE (PART I)	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	24/01/2023	-	-/COMPLIED WITH	LAST DONE WP NO: 9M-JPM-13906 AT 160:32FH ON 24-JAN-2023 (AJL 03819) PART I: WITHIN AND NOT LATER THAN 300 FH OR 6 MONTHS WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN REFER TIC-AW139-22-0218
Standard SBs	SB NO. 139-672, NEW ISSUE (PART II)	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)	0.00	1342.37	-/TO BE COMPLIED	PART II: - IMMEDIATELY AFTER COMPLIANCE OF PART I, IF CHAFING IS DETECTED AND ITS ENTITY IS NOT NEGLIGIBLE. - WITHIN AND NOT LATER THAN 1200FH OR 12 MONTHS, WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN, IF DURING COMPLIANCE WITH PART I NO CHAFING IS DETECTED OR ITS ENTITY IS NEGLIGIBLE. REFER TIC-AW139-22-0218

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	13
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-672, NEW ISSUE (PART II)	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)	02/10/2023	03/10/2023	-/TO BE COMPLIED	PART II: - IMMEDIATELY AFTER COMPLIANCE OF PART I, IF CHAFING IS DETECTED AND ITS ENTITY IS NOT NEGLIGIBLE. - WITHIN AND NOT LATER THAN 1200FH OR 12 MONTHS, WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN, IF DURING COMPLIANCE WITH PART I NO CHAFING IS DETECTED OR ITS ENTITY IS NEGLIGIBLE. REFER TIC-AW139-22-0218
Standard SBs	SB NO. 41122, NEW ISSUE	INCREASED NUMBER OF COMPRESSOR ROTOR BALANCING RIVETS AND WEIGHT	-	-	-/Category 5	REFER TIC-AW139-22-0212. APPLICABILITY: APPLICABLE DUE TO ENGINE S/N AFFECTED COMPLIANCE: CATEGORY 5 - P&WC RECOMMENDS TO DO THIS SERVICE BULLETIN WHEN THE ENGINE IS DISASSEMBLE AND ACCESS IS AVAILABLE TO THE NECESSARY SUBASSEMBLY
AIRFRAME SBs						
Standard SBs	SB NO. 139-681, REV. A	ATA 33 - HELICOPTER EMERGENCY EXIT LIGHTS SYSTEM INSTALLATION.	-	-	-/NOT APPLICABLE	TIC-AW139-22-0341 DATED 29 NOVEMBER 2022 NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO 139-697 NEW ISSUE	ATA 25 - KIT LIFE RAFTS 14 PAX P/N 4G2560F01011	-	-	-/OPTIONAL	APPLICABLE UPON CUSTOMERS REQUEST. REFER TIC-AW139-22-0335
Standard SBs	SB NO 139-727, NEW ISSUE	ATA 63 MAIN GEARBOX CASE REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT MAIN GEARBOX (MGB) P/N 4G6320A00133 AND P/N 4G6320A00132 NOT FITTED ON AIRCRAFT REFER TIC-AW139-22-0330

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	14
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-619, NEW ISSUE	ATA 56- REPLACEMENT OF BUBBLE WINDOW WITH STANDARD WINDOW	-	-	-/NOT APPLICABLE	TIC-AW139-21-0275 APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REASON: THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTIONS ON HOW TO PERFORM THE STANDARD WINDOW RESTORE.
Standard SBs	SB NO. 139-619, REV. B (PART I & II)	ATA 56 - REPLACEMENT OF BUBBLE WINDOW WITH STANDARD WINDOW	-	-	-/NOT APPLICABLE	REFER TIC-AW139-22-0260 DATED 09 NOVEMBER 2022 PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED PART II: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-723, NEW ISSUE	CABIN PROVISION MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. REFER TIC-AW139-22-0249
Standard SBs	SB NO. 139-564, NEW ISSUE	AV900 CABIN STATION, POWER SOCKET AND AVIONIC VARIANT INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. REFER TIC-AW139-22-0240
Standard SBs	SBEA 139-731 REV./ PART I (EASA AD 2022-0209-E)	ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION	143.78	-	-/COMPLIED WITH	PART I: COMPLIED WITH AT 143:47FH ON 15-OCT-22 (AJL 06195) PART II: APPLICABLE. LAST DONE - WP NO. 9M-JPM-13072 AT 143:47FH ON 15-OCT-22 (AJL 06195)
Standard SBs	SBEA 139-731 REV./ PART II (EASA AD 2022-0209-E)	ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION	143.78	-	-/COMPLIED WITH	PART I: COMPLIED WITH AT 143:47FH ON 15-OCT-22 (AJL 06195) PART II: APPLICABLE. LAST DONE - WP NO. 9M-JPM-13073 AT 143:47FH ON 15-OCT-22 (AJL 06195)

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	15
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-692, NEW ISSUE	DRIVE PULLEY WASHER INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO 9M-JPM DUE TO COMPRESSOR FITTED ON AIRCRAFT NOT AFFECTED. REFER TO TIC-AW139-22-0192. TO BE DISTRIBUTE AS INFO ONLY.
Standard SBs	SB NO. 139-623, REV. B	MISCELLANEOUS RETROFIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. REFER TO TIC-AW139-22-0187
Standard SBs	SB NO. 139-234, REV. A	DF935-11 DIRECTION FINDING SYSTEM KIT P/N 4G3450F00711, INSTALLATION OF	-	-	-/OPTIONAL	NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-22-0183
Standard SBs	SB NO 139-718, NEW ISSUE	ATA 93 OPLS KIT COMPLETION	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-22-0175
Standard SBs	SB NO. 139-722, NEW ISSUE	MAIN ROTOR HEAD ASSY UPGRADE	-	-	-/NOT APPLICABLE	REFER TIC-AW139-22-0170. NOT APPLICABLE DUE TO COMPONENT MAIN ROTOR HEAD ASSEMBLIES P/N 3G6220A00132 NOT FITTED ON AIRCRAFT.
Standard SBs	SB 139-725 REV. A PART I, II AND III	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 EQUIPPED ON AIRCRAFT AND COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 HAVE BEEN REMOVED AND REINSTALLED ON COMPONENT SLIDING CONTROL ASSEMBLY P/N 3G6430A02531 DURING APPLICATION OF 4-YEARS INSPECTION AND HAS NOT LOGGED 2400 FH OR MORE. REFER TIC-AW139-22-0167
Standard SBs	SBEA 139-725 REV. A PART III (EASA AD 2022-0182)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT TAIL ROTOR DUPLEX BEARING P/N 3G6430V00153 HAS NOT LOGGED 2400 FH OR MORE. REFER TIC-AW139-22-0154
Standard SBs	SB 139-725, REV A (PART IV)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0.00	2400.00	-/TO BE COMPLIED	TO BE COMPLIED WHEN AFFECTED PART REACHED 2400 FH. REFER TIC-AW139-22-0167

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	16
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SBEA 139-725 REV.A PART IV (EASA AD 2022-0182-E)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0.00	2400.00	-/TO BE COMPLIED	TIC-AW139-22-0154 APPLICABLE DUE TO AIRCRAFT TYPE, AND AFFECTED COMPONENT FITTED ON AIRCRAFT. TO BE COMPLIED WITH THE PART 4-B
Standard SBs	SB NO. 139-362, REV A	ATA 76 - ENGINE CONTROL MECHANICAL BACKUP	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT AFFECTED REFER TIC-AW139-22-0163
Standard SBs	SB NO. 139-726, NEW ISSUE	MODULAR AVIONIC UNIT (MAU) MARKING	-	-	-/OPTIONAL	APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REFER TIC-AW139-22-0162
Standard SBs	SBA 139-569 REV B	ATA 64 - TAIL ROTOR SLIDER ASSY DETAILED INSPECTION	0.00	2400.00	-/TO BE COMPLIED	TIC-AW139-22-0155 PART 1: WITHING 50FH ONCE REACH 2400FH PART 2: EVERY 1Y, IF FOUND SIGNS OF REFINISHING
Standard SBs	SBA 139-569 REV.B PART I(AD2018-0292) COMPLIANCE	ATA 64 TAIL ROTOR SLIDER ASSY DETAILED INSPECTION	0.00	2400.00	-/TO BE COMPLIED	PART I: APPLICABLE ONCE SLIDER ASSY LOGGED REACHED 2400 FH OR MORE WITHIN 50 FH AND NOT EXCEEDING 2450 FH. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SBA NO 139-569, REVISION B PART II	ATA 64 - TAIL ROTOR SLIDER ASSY DETAILED INSPECTION	0.00	2400.00	-/TO BE COMPLIED	PART II: APPLICABLE ONCE COMPLIED WITH PART I. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021 DATED 18.02.2021
Standard SBs	SB 139-710, NEW ISSUE	ATA 23 - SATCOM FLIGHTCELL IMPROVEMENT	-	-	-/OPTIONAL	TIC-AW139-22-0149 APPLICABLE AND COMPLIANCE AT CUSTOMER OPTION.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	17
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-685, NEW ISSUE	ATA 93 - AIRCRAFT SURVIVABILITY EQUIPMENT (ASE) MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-22-0144
Standard SBs	SB NO. 139-685,NEW ISSUE	LEONARDO HELICOPTERS - AW139 SERVICE BULLETIN ATA 93 - AIRCRAFT SURVIVABILITY EQUIPMENT (ASE) MODIFICATION	-	-	-/NOT APPLICABLE	TIC-AW139-22-0144 APPLICABILITY: NOT APPLICABLE DUE TO SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB 139-699, NEW ISSUE	ATA 33 - TAIL ROTOR LIGHTS IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH AFFECTED PART NUMBER. REFER TIC-AW139-22-0145
Standard SBs	SB NO. 139-678 REV./ PART 1 (EASA AD 2020-0191 R1)	ATA 53 - MIDDLE PANEL RETROMOD INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. REFER TIC-AW139-22-0143
Standard SBs	SB NO. 139-678 REV./ PART 2 (EASA AD 2020-0191 R1)	ATA 53 - MIDDLE PANEL RETROMOD INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED REFER TIC-AW139-22-0143
Standard SBs	SB NO. 139-678 REV./ PART 3 (EASA AD 2020-0191 R1)	ATA 53 - MIDDLE PANEL RETROMOD INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED REFER TIC-AW139-22-0143
Standard SBs	SB NO. 139-586, NEW ISSUE	ATA 95 - DART INTEGRATED EMERGENCY FLOTATION AND LIFE RAFT SYSTEM KIT INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-22-0133 OPTIONAL SB - APPLICABLE TO DISCUSS WITH OPERATOR ON SB COMPLIANCE
Standard SBs	SB 139-695 NEW ISSUE	ATA 56 - INSTALLATION OF ACRYLIC WINDSHIELDS	-	-	-/OPTIONAL	TIC-AW139-22-0131 APPLICABILITY: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED OPTIONAL SB TO DISCUSS WITH THE OPERATOR ON SB COMPLIANCE.
Standard SBs	SB 139-719 NEW ISSUE	ATA 93 OPLS LASER SENSOR UNIT FIRMWARE UPDATE.	-	-	-/NOT APPLICABLE	TIC-AW139-22-0130 APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	18
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-665 REV A	ATA 34 - EGPWS INSTALLATION, ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-22-0128 OPTIONAL SB APPLICABILITY: PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO. 139-669, NEW ISSUE	SATCOM FLIGHTCELL DZMX ELECTRICAL VARIANT INSTALLATION	-	-	-/NOT APPLICABLE	APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REFER TIC-AW139-22-0129
Standard SBs	BT 139-360 REV. /	ATA 24 - KIT BATTERY START IN PARALLEL 44 AH AND 27 AH	-	-	-/SUPERSEDED	SUPERSEDE TO BT 139-360 REV. A DATED 22-OCTOBER-2021.
Standard SBs	SB NO. 139-360 REV B PART I	ATA 24 - KIT BATTERY START IN PARALLEL 44 Ah AND 27 Ah	-	-	-/NOT APPLICABLE	TIC-AW139-22-0126 PART I: NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-360 REV B PART II	ATA 24 - KIT BATTERY START IN PARALLEL 44AH AND 27 AH	-	-	-/OPTIONAL	TIC-AW139-22-0126 PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)
Standard SBs	SB NO. 139-360 REV B PART III	ATA 24 - KIT BATTERY START IN PARALLEL 44 Ah AND 27 Ah	-	-	-/NOT APPLICABLE	TIC-AW139-22-0126 PART III: NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER NOT AFFECTED OPTIONAL SB
Standard SBs	SB NO. 139-715, NEW ISSUE	ATA 62 - MAIN ROTOR BLADE S/N MARKING	-	-	-/NOT APPLICABLE	TIC-AW139-22-0122 NOT APPLICABLE BY MR BLADE SN
Standard SBs	SB 139-601 REV A PART I	ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-21-0440. NOT APPLICABLE DUE TO COMPONENT TRAKKA A800 SEARCHLIGHT P/N P/N 4G3340F02411, P/N 4G3340F02412, P/N 4G3340F02413, P/N 4G3340F02414 or P/N 4G3340F03011 AND SUPPPORT SEARCHLIGHT ASSY P/N 3G3340A01133 NOT INSTALLED ON AIRCRAFT.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	19
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-601 REV A PART II	ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SUPPPORT SEARCHLIGHT ASSY P/N 3G3340A01133 NOT INSTALLED ON AIRCRAFT. REFER TIC-AW139-21-0440 DATED 28.12.2021
Standard SBs	SB NO. 139-647,NEW ISSUE	INTERSEAT CONSOLE CONNECTORS REPOSITIONING	-	-	-/NOT APPLICABLE	APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REFER TIC-AW139-22-0118
Standard SBs	SBA 139-661 REV. B PART I	ATA 24 - OVERHEAD PANEL INSPECTION	-	-	-/NOT APPLICABLE	PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED REFER TIC-AW139-21-0274 DATED 25.08.2021
Standard SBs	SBA 139-661 REV. / PART I	ATA 24 - OVERHEAD PANEL INSPECTION	-	-	-/SUPERSEDED	SUPERSEDE TO SBA 139-661 REV. A DATED 04-FEBRUARY-2022
Standard SBs	SB 139-600, NEW ISSUE	ATA 46 - 'PRIMUS EPIC' FLIGHT SOFTWARE RELEASE 8 UPGRADE	-	-	-/OPTIONAL	REFER TIC-AW139-22-0113
Standard SBs	SB NO. 139-651, NEW ISSUE	ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER CONVERSION TO P/N 965-1595-034.	-	-	-/OPTIONAL	REFER TIC-AW139-22-0114
Standard SBs	BT 139-398	FOOTSTEP FAST REMOVAL KIT P/N 4G5260F00311.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED IN CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	20
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-035 REV D	ATA 25 - AUTOMATICALLY DEPLOYABLE ELT INSTALLATION	-	-	-/OPTIONAL	PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. PART II: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. PART III: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. PART IV: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. PART V: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE: OPTIONAL. DEPEND ON CUSTOMER DECISION. REFER TIC-AW139-22-0028
Standard SBs	BT 139-035 REV B PART I AND II	ELT DEPLOYABLE KIT P/N 3G2560F00311, INSTALLATION OF.	-	-	-/SUPERSEDED	SUPERSEDE TO BT 139-035 REV C DATED 19-OCTOBER-2016
Standard SBs	SB NO 139-035 REVISION C PART I & II	ATA 25 - AUTOMATICALLY DEPLOYABLE EMERGENCY LOCATOR TRANSMITTER	-	-	-/SUPERSEDED	SUPERSEDE TO BT 139-035 REV. D DATED 18-MARCH-2022
Standard SBs	SB NO 139-035 PART III, REVISION C	ATA 25 - AUTOMATICALLY DEPLOYABLE EMERGENCY LOCATOR TRANSMITTER	-	-	-/OPTIONAL	SUPERSEDE TO BT 139-035 REV. D DATED 18-MARCH-2022
Standard SBs	SB NO. 139-624, REV. A PART I	ATA 23 - SATCOM SKYTRACK ISAT-200A KIT INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-22-0026 APPLICABILITY: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-406, PART I, NEW ISSUE	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-21-0244 OPTIONAL SB - PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-406, PART II, NEW ISSUE	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-21-0244 OPTIONAL SB - PART II, NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-406, PART III, NEW ISSUE	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-21-0244 OPTIONAL SB, PART III: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-406, REV. A (PART I)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-22-0025 APPLICABILITY: PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	21
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-406, REV. A (PART II)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-22-0025 APPLICABILITY: PART II: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-406, REV. A (PART III)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/OPTIONAL	TIC-AW139-22-0025 PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-406, REV. A (PART IV)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-22-0025 PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-709, NEW ISSUE	ATA 33 PLACARD PROVISION REMOVAL	-	-	-/NOT APPLICABLE	TIC-AW139-22-0015 OPTIONAL SB NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	BT 139-135 REV. /	WIRE STRIKE PROTECTION SYSTEM (WSPS) KIT	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	SB NO. 139-135, REV. A PART I	ATA 25 - INSTALLATION OF KIT WIRE STRIKE PROTECTION SYS	-	-	-/OPTIONAL	TIC-AW139-22-0013 PART I: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)
Standard SBs	SB NO. 139-135, REV. A PART II	ATA 25 - INSTALLATION OF KIT WIRE STRIKE PROTECTION SYS	-	-	-/OPTIONAL	TIC-AW139-22-0013 PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)
Standard SBs	SB NO. 139-135, REV. A PART III	ATA 25 - INSTALLATION OF KIT WIRE STRIKE PROTECTION SYS	-	-	-/NOT APPLICABLE	TIC-AW139-22-0013 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED OPTIONAL SB
Standard SBs	SB NO. 139-135, REV. A PART IV	ATA 25 - INSTALLATION OF KIT WIRE STRIKE PROTECTION SYS	-	-	-/NOT APPLICABLE	TIC-AW139-22-0013 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED OPTIONAL SB

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	22
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-135, REV. A PART V	ATA 25 - INSTALLATION OF KIT WIRE STRIKE PROTECTION SYS	-	-	-/OPTIONAL	TIC-AW139-22-0013 APPLICABLE DUE TO AIRCRAFT S/N AFFECTED OPTIONAL SB - COMPLIANCE UPON CUSTOMER REEQUEST
Standard SBs	SB NO. 139-623, REV. B	ATA 00 - MISCELLANEOUS RETROFIT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0012 (OPTIONAL SB) NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-524 REV A	ATA 25 - LIFERAFT RESERVOIR ASSEMBLY ALIGNMENT LABEL POSITIONING	-	-	-/OPEN	APPLICABLE TO LH LIFERAFT RESERVOIR P/N 3G2560V01251 DUE TO SN VT117146-R IS AFFECTED BY THIS SB. APPLICABLE TO RH LIFERAFT RESERVOIR P/N 3G2560V01951 DUE TO SN VT128646 IS AFFECTED BY THIS SB. REFER TIC-AW139-22-0010
Standard SBs	BT 139-467 PART II REV A	TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET	-	-	-/COMPLIED WITH	PART II: COMPLIED WITH BY MANUFACTURE
Standard SBs	BT 139-467 PART II REV A	TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET	-	-	-/COMPLIED WITH	PART II: COMPLIED WITH BY MANUFACTURE
Standard SBs	EVERY 25FH INSPECTION SB139-539 PART I	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT (PART I COMPLIANCE UNTIL ACCOMPLISHMENT PART III)	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT. REFER TIC-AW139-22-0007
Standard SBs	SB139-539 PART II (3M BEFORE COMPLIANCE PART III) (MMIR	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT	-	25/10/2023	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT. REFER TIC-AW139-22-0007
Standard SBs	SB139-539 PART III (1500H//2Y)	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT. REFER TIC-AW139-22-0007
Standard SBs	SB139-539 PART III (1500H//2Y)	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT	-	25/01/2024	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT. REFER TIC-AW139-22-0007
Standard SBs	SB 139-516 REV. A PART I, II, IV & V	ATA 95 EMERGENCY FLOTATION AND LIFE RAFT SYSTEMS CONVERSION TO DART INTEGRATED SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED. REFER TIC-AW139-22-0002 DATED 19.01.2022

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	23
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-696, NEW ISSUE	ATA 63 - MAIN GEAR BOX REMARKING	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT MGB P/N 3G6320A00134 WITH AFFECTED S/N NOT FITTED ON THE AIRCRAFT. REFER TO TIC-AW139-21-0410
Standard SBs	SB NO. 139-615 NEW ISSUE	ATA 00 INSTALLATION OF SPECIFIC VARIANTS FOR OFFSHORE CONFIGURATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0406 DATED 02 DECEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-503 REV. /	ATA 00 INTERIOR RECONFIGURATION FROM UTILITY TO VIP	-	-	-/NOT APPLICABLE	TIC-AW139-21-0398 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-502 REV./	ATA 95 - COCKPIT AND CABIN PASSENGER FLOOR BALLISTIC PROTECTIONS INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0397 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB 139-502 REV. /	ATA 95 - COCKPIT AND CABIN PASSENGER FLOOR BALLISTIC PROTECTIONS INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-21-0397 DATED 18.11.2021
Standard SBs	SB NO. 139-407 REV. A PART I	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/COMPLIED WITH	PART I: COMPLIED WITH BY MANUFACTURER LEONARDO HELICOPTERS ANNEX 2 BOLLETTINO TECNICI STATUS LIST DATED: 17.12.2020
Standard SBs	SB NO. 139-407 REV C PART I	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/OPTIONAL	TIC-AW139-21-0399 (OPTIONAL SB) APPLICABLE TO PART I DUE TO ALL AIRCRAFT SERIAL NUMBER. COMPLIANCE AT CUSTOMER'S OPTION

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	24
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-407 REV. A PART II	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/NOT APPLICABLE	PART II: NOT APPLICABLE BY COMPONENT PART NUMBER LEONARDO HELICOPTERS ANNEX 2 BOLLETTINO TECNICI STATUS LIST DATED: 17.12.2020 THIS SB HAS BEEN CANCELLED AND SUPERSEDED BY SB NO. 139-407 REVISION B DATED 30-APRIL-2020
Standard SBs	SB NO. 139-407 REV C PART II AND III	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/NOT APPLICABLE	TIC-AW139-21-0399 OPTIONAL SB: PART II & III NOT APPLICABLE DUE IBF PN NOT INSTALLED ON AIRCRAFT
Standard SBs	SB NO. 139-407 REV. A PART III	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/OPTIONAL	PART III: APPLICABLE. COMPLY UPON CUSTOMER REQUEST LEONARDO HELICOPTERS ANNEX 2 BOLLETTINO TECNICI STATUS LIST DATED: 17.12.2020 THIS SB HAS BEEN CANCELLED AND SUPERSEDED BY SB NO. 139-407 REVISION B DATED 30-APRIL-2020
Standard SBs	SB NO. 139-483	ATA 23- MR6000R RADIO SYSTEM INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0402 DATED 18 NOVEMBER 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-496	ATA 06 - AVIONIC VARIANT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0400 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	25
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-576	ATA 21-VENTILATION AND WATER DRAIN LINES VARIANT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0401 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-684, REVISION A	ATA 93 - TURRET FLIR UNIT REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-23-0052 DATED 22 FEBRUARY 2023 NOT APPLICABLE TO THIS AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO. 139-649, NEW ISSUE	ATA 67 TAIL ROTOR ACTUATOR UPGRADE	0.00	3000.00	-/TO BE COMPLIED	TIC-AW139-21-0393 APPLICABLE TO THIS AIRCRAFT DUE FITTED WITH PN 3G6730V00731 TO BE COMPLIED NEXT REPAIR/OVERHAUL
Standard SBs	ASB NO. 139-686, NEW ISSUE PART I (EASA AD 2021-0259)	ATA 53 - TAIL GEAR BOX FITTING INSPECTION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0392 APPLICABILITY: NOT APPLICABLE DUE TO COMPONENT TGB FITTING P/N 3G5351A01152 FITTED ON AIRCRAFT IS NOT MORE THAN 3000FH. REFER LOG CARD
Standard SBs	ASB NO. 139-686, NEW ISSUE PART II	ATA 53 - TAIL GEAR BOX FITTING INSPECTION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0392 APPLICABILITY: NOT APPLICABLE DUE TO COMPONENT TGB FITTING P/N 3G5351A01152 FITTED ON AIRCRAFT IS NOT MORE THAN 3000FH. REFER LOG CARD
Standard SBs	SB NO. 139-664	ATA 25 - D-LOCK HOOK BREEZE HOIST INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0379 DATED 29 OCTOBER 2021 NOT APPLICABLE DUE TO COMPONENT BREEZE EASTERN 90M RESCUE HOIST KIT PART NUMBER 3G2591F00113 NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-671, NEW ISSUE (ERRATA CORRIGE)	ATA 26- FIRE EXTINGUISHER REPLACEMENT (ERRATA CORRIGE)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0373 NOT APPLICABLE DUE TO COMPONENT FIRE EXTINGUISHER P/N P3APP003010A NOT FITTED ON AIRCRAFT. (FITTED WITH PN P3APP003010d)

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	26
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-641, NEW ISSUE	ATA 25 - COLLECTIVE EMERGENCY LIFE-RAFT NEW HANDLE COVER	-	-	-/NOT APPLICABLE	TIC-AW139-21-0372 OPTIONAL SB: NOT APPLICABLE DUE TO COMPONENT KIT EMERGENCY FLOAT AND LIFERAFTS P/N 3G9560F0011 NOT INSTALLED ON AIRCRAFT. REFER ATTACHEMENT
Standard SBs	BT 139-515 REV B	ATA 46 - "PRIMUS EPIC" FLIGHT SOFTWARE RELEASE 7.12 & 7.14 UPGRADE	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED: DIFFERENT SOFTWARE RELEASE INSTALLED. REF: ANNEX 2 BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB NO. 139-642, REV A PART I	ATA 64 - TAIL ROTOR HEAD INSPECTION AND MODIFICATION	-	-	-/COMPLIED WITH	SB TO BE CANCEL DUE TO INSPECTION TASK HAS BEEN INTRODUCED IN AMPI CHAPTER 5 (TASK 64-38) REFER TIC-AW139-21-0349 DATED 28.09.2021
Standard SBs	SB NO. 139-642, REV. A PART II	ATA 64 - TAIL ROTOR HEAD INSPECTION AND MODIFICATION	-	-	-/COMPLIED WITH	LAST DONE WP NO. 9M-JPM-6465 ON 24-AUG-21 AT 43:47FH (AJL 04390) TIC-AW139-21-0349 REFER TO REVISION A OF THIS SB TASK ALREADY INCLUDED IN AMPI CHAP 5 TAKS 64-38 EVERY 50FH INSP
Standard SBs	SB NO. 139-660	ATA 46 - "PRIMUS EPIC" FLIGHT SOFTWARE RELEASE UPGRADE FROM PHASE 7.12 & 7.14 TO PHASE 7.12.2 & 7.14.2	-	-	-/OPTIONAL	TIC-AW139-21-0348 DATED 28 SEPTEMBER 2021 APPLICABLE DUE TO COMPONENT PRIMUS EPIC FLIGHT SOFTWARE RELEASE AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-670, NEW ISSUE	ATA 11 - ADDITIONAL MARKING PLACARD INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-21-0347 DATED 28.09.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	27
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-596, REVISION A	ATA 21 - INSTALLATION OF INSULATION TUBES ON ECS PIPE	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-21-0346, NOT APPLICABLE DUE TO COMPONENT AIR CONDITIONING P/N P/N 3G2150A04211, OR P/N 3G2150A04811, OR P/N 3G2150A05011, OR P/N 3G2150A05411, OR P/N 3G2150A05611 AND SUBSEQUENT NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-596, NEW ISSUE	INSTALLATION OF INSULATION TUBES ON ECS PIPE	-	-	-/NOT APPLICABLE	THIS SB HAS BEEN SUPERSEDED BY SB 139-596 REVISION A DATED 22.09.2021
Standard SBs	SB NO. 139-577 PART I, NEW ISSUE	ATA 53 - LOWER INSPECTION COVER INSTALLATION	-	-	-/NOT APPLICABLE	APPLICABILITY: PART I: NOT APPLICABLE TO DUE TO AIRCRAFT S/N AFFECTED. COMPLIANCE: AT CUSTOMER OPTIONS REFERENCE: TIC-AW139-21-0345
Standard SBs	SB NO. 139-577 PART II, NEW ISSUE	ATA 53 - LOWER INSPECTION COVER INSTALLATION	-	-	-/OPTIONAL	APPLICABILITY: PART II : APPLICABLE TO DUE TO AIRCRAFT S/N AFFECTED. COMPLIANCE: AT CUSTOMER OPTIONS REFERENCE: TIC-AW139-21-0345
Standard SBs	SB 139-675 REV. A	ATA 97 - KIT CABIN CAMERA SOFT LINER INSTALLATION	-	-	-/NOT APPLICABLE	APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED PLEASE REFER TO TIC-AW139-21-0344
Standard SBs	SB 139-656 NEW ISSUE	ATA 21 - INSTALLATION OF ENVIRONMENTAL CONTROL SYSTEM (ECS) HIGH EFFICIENCY PARTICULATE AIR (HEPA) FILTER	-	-	-/NOT APPLICABLE	APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REASON: THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION ON HOW TO PERFORM THE ECS HEPA FILTER INSTALLATION P/N 3G2150P01611. PLEASE REFER TO TIC-AW139-21-0341

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	28
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SBEA NO. 139-679, NEW ISSUE	ATA 25 - HOIST RATED LOAD CHECK (BREEZE)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0267 NOT APPLICABLE DUE NOT FITTED WITH HOIST-VIP CONFIG (REFER LOG CARD/EQUIPMENT LIST)
Standard SBs	SB NO. 139-348, REV A PART III	ATA 34 - KIT TCAS II INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0259 OPTIONAL SB - PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO. 139-348, REV A PART II	ATA 34 - KIT TCAS II INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0259 OPTIONAL SB - PART 2: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO. 139-348, REV A PART I	ATA 34 - KIT TCAS II INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0259 OPTIONAL SB - PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	BT 139-348	KIT TCAS II P/N 4G34SOF00211	-	-	-/OPTIONAL	PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REFER TIC-AW139-21-0259
Standard SBs	SB 139-667 NEW ISSUE	ATA 24 - AUXILIARY OVERHEAD PANEL AND INTERSEAT CONSOLE MODIFICATIONS	-	-	-/NOT APPLICABLE	APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION PLEASE REFER TO TIC-AW139-21-0262
Standard SBs	SB NO. 139-271, REVISION A (PART I)	ATA 23 - INSTALLATION OF KIT RADIO V/UF FLEXCOMM II P/N 3G2310F00111	-	-	-/NOT APPLICABLE	TIC-AW139-21-0260 OPTIONAL SB - PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-271, REVISION A (PART II)	ATA 23 - INSTALLATION OF KIT RADIO V/UF FLEXCOMM II P/N 3G2310F00111	-	-	-/OPTIONAL	TIC-AW139-21-0260 OPTIONAL SB - PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO. 139-271, REVISION A (PART III)	ATA 23 - INSTALLATION OF KIT RADIO V/UF FLEXCOMM II P/N 3G2310F00111	-	-	-/OPTIONAL	TIC-AW139-21-0260 OPTIONAL SB - PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	29
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-271	KIT RADIO V/UHF FLEXCOMM II P/N 3G2310F00111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER SERIAL NUMBER. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-666, NEW ISSUE	ATA 23 - KIT SATCOM FLIGHTCELL DZMX (4G) INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0261 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-658, NEW ISSUE	ATA 23 - SATCOM FLIGHTCELL DZMX (4G) RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0256 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-663, NEW ISSUE	ATA 30 - WIPER BLADESPRAY NOZZLE REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0257 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH COMPONENT KIT WINDSHIELD WASHING P/N 4G3040F00116, WIPER BLADE SPRAY NOZZLE P/N 3G3040V01151 & WIPER BLADE ASSY P/N 3G3040A02931 OR P/N 3G3040A03031.
Standard SBs	SB NO. 139-518, NEW ISSUE	ATA 33 - HELICOPTER EMERGENCY EXIT LIGHTS SYSTEM INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0247 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-559, NEW ISSUE PART I	ATA 71 - FIREWALLS RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0246 OPTIONAL SB ~ PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-559, NEW ISSUE PART II	ATA 71 - FIREWALLS RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0246 OPTIONAL SB: PART II: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-559, NEW ISSUE PART III	ATA 71 - FIREWALLS RETROMOD	-	-	-/OPTIONAL	TIC-AW139-21-0246 OPTIONAL SB: PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO. 139-674, NEW ISSUE	ATA 93 - AIRCRAFT SURVIVABILITY EQUIPMENT (ASE) RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0245 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-625, NEW ISSUE	ATA 33 - UTILITY LIGHT IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0243 NOT APPLICABLE DUE TO COMPONENT NVG UTILITY LIGHT P/N 3G3310A00231 OR LIGHT ASSY P/N 90-004-1 NOT EQUIPPED ON AIRCRAFT.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	30
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-455, PART I, REVISION A	ATA 53 - TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-21-0237 DATED 08.06.2021
Standard SBs	SB NO. 139-455 PART II, REVISION A	ATA 53 - TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS REPLACEMENT	-	-	-/OPTIONAL	TIC-AW139-21-0237 OPTIONAL SB: PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED.
Standard SBs	SB NO. 139-455 PART III, REVISION A	ATA 53 - TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS REPLACEMENT	-	-	-/OPTIONAL	TIC-AW139-21-0237 OPTIONAL SB - PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED.
Standard SBs	SB NO. 139-455 PART IV, REVISION A	ATA 53 - TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS REPLACEMENT	-	-	-/OPTIONAL	TIC-AW139-21-0237 OPTIONAL SB-PART IV: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED.
Standard SBs	BT 139-455 PART I	ATA 53 - REPLACEMENT OF TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS	-	-	-/NOT APPLICABLE	PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. COMPLIANCE: AT CUSTOMER'S OPTION. REFER TIC-AW139-21-0237
Standard SBs	BT 139-455 PART II,III AND IV	ATA 53 - REPLACEMENT OF TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS	-	-	-/OPTIONAL	PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED. PART III: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED. PART IV: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED. COMPLIANCE: AT CUSTOMER'S OPTION REFER TIC-AW139-21-0237
Standard SBs	SB NO. 139-636 ,NEW ISSUE	ATA 78 - REAR FIREWALL MODULE ASSY RETROMOD INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0232 DATED 12 MAY 2021 APPLICABLE TO THIS AIRCRAFT WITH THIS SERIAL NUMBER. AIRCRAFT IS FITTED WITH PART NUMBER 3G7810A02033, PART NUMBER 3G7810A02034 AND PART NUMBER 3G7810A02035. COMPLIANCE TIME AT CUSTOMER OPTION.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	31
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-618 NEW ISSUE	ATA 71 TUNNEL ASSY RETROMOD.	-	-	-/OPTIONAL	NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH PN: P/N 3G7130A13433 OR P/N 3G7130A13434 OR P/N 3G7130P00131 OR P/N 3G7130A13431 OR P/N 3G7106P10031. REFER TIC-AW139-21-0231
Standard SBs	SB NO. 139-578, NEW ISSUE	ATA 23 KIT RADIO MOTOROLA XiR 8268 PROVISION INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0226 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB 139-553, NEW ISSUE	ATA 23 - INSTALLATION OF KIT RADIO MOTOROLA XIR	-	-	-/SUPERSEDED	SUPERSEDE TO SB 139-553 REV. A DATED 26-APRIL-2021
Standard SBs	SB NO. 139-553, REVISION A	ATA 23 - KIT RADIO MOTOROLA XIR INSTALLATION	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER TIC-AW139-21-0224 DATED 27.04.2021
Standard SBs	SB NO. 139-575, NEW ISSUE	ATA 23 COMMUNICATION CUSTOMIZATION RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0225 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-629, REVISION A	ATA 95 FORWARD FLOATS COVERS UPGRADE	-	-	-/NOT APPLICABLE	TIC-AW139-21-0220 NOT APPLICABLE DUE TO COMPONENT LH FORWARD COVER ASSY P/N 3G9560V04131 & RH FORWARD COVER ASSY P/N 3G9560V04231 WITH THE S/N LISTED IN THE SB NOT FITTED ON AIRCRAFT (REFER LOG CARD)
Standard SBs	SB NO. 139-629, NEW ISSUE	FORWARD FLOATS COVER UPGRADE	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT LH FORWARD COVER ASSY P/N 3G9560V04131 & RH FORWARD COVER ASSY P/N 3G9560V04231 WITH THE S/N LISTED IN THE SB NOT FITTED ON AIRCRAFT REFER TIC-AW139-21-0220 DATED 21.04.2021
Standard SBs	ASB NO. 139-609, REVISION A (EASA AD 2020-0011R1)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	28000.00	-/TO BE COMPLIED	TIC-AW139-21-0218 APPLICABLE DUE TO AFFECTED MGB PN 3G6320A00135 FITTED ON AIRCRAFT.
Standard SBs	SBA NO. 139-609, NEW ISSUE (EASA AD 2020-0011R1)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	6000.00	-/SUPERSEDED	THIS SB HAS BEEN SUPERSEDED BY SB 139-609 REVISION A DATED 18.12.2019
Standard SBs	SBA NO. 139-609, NEW ISSUE (EASA AD 2020-0011R1)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	28000.00	-/SUPERSEDED	THIS SB HAS BEEN SUPERSEDED BY SB 139-609 REVISION A DATED 18.12.2019

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	32
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ASB NO. 139-609, REVISION A (EASA AD 2020-0011R1)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	6000.00	-/TO BE COMPLIED	TIC-AW139-21-0218 APPLICABLE DUE TO AFFECTED MGB PN 3G6320A00135 FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-613, NEW ISSUE	ATA 95 - IMPROVEMENT OF EMERGENCY FLOATS RIGID COVER	-	-	-/NOT APPLICABLE	TIC-AW139-21-0216 NOT APPLICABLE DUE TO EMERGENCY FLOAT SYSTEM (DART) FITTED ON AIRCRAFT
Standard SBs	SB NO. 139-240, REVISION D	ATA 67 - INSTALLATION OF PILOT/CO-PILOT COLLECTIVE GRIP P/N 3G6711V00951 AND P/N 3G6711V01051	-	-	-/OPTIONAL	TIC-AW139-21-0214 APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	BT 139-240 REV B	PILOT/COPILOT COLLECTIVE GRIP P/N 3G6711V00951 AND P/N 3G6711V01051, INSTALLATION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON AIRCRAFT BY MANUFACTURER
Standard SBs	SB NO. 139-646, NEW ISSUE	ATA 23 - RADIO HARRIS KIT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0215 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-587, NEW ISSUE	ATA 30 - WINDSHIELD WASHING SYSTEM INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0206 APPLICABILITY: OPTIONAL SB AND WP# 9M-JPM-6537 ISSUE FOR PHYSICAL CX
Standard SBs	SB NO. 139-588, NEW ISSUE	ATA 28 - AUXILIARY LONGITUDINAL FUEL TANK COMPLETION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-AW139-21-0205 DATED 31.03.2021
Standard SBs	SB NO. 139-581, NEW ISSUE	ATA 21 - VENTILATION INSULATION IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0207 COMPLIANCE: NOT APPLICABLE DUE TO A/C SERIAL
Standard SBs	SB NO. 139-617, NEW ISSUE	ATA 62 - MAIN ROTOR BLADE LIGHTNING STRIP CORROSION PROTECTION IMPROVEMENT	25/03/2021	-	-/COMPLIED WITH	COMPLIED WITH. REFER 9M-JPM-9656 ON 28-JAN-22 (83:12FH) AJL 06126) COMPLIED WITH MR BLADE PN 366210A00131 SN AW5192, AW5186, AW5169, AW5162, AW5119.
Standard SBs	SB NO. 139-574, NEW ISSUE	ATA 24 LH UTILITY CB PANEL RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0079 COMPLIANCE: OPTIONAL SB AND NOT APPLICABLE DUE TO AIRCRAFT SN NOT AFFECTED TO ALL AW139 UNDER CAMO

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	33
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-605, REVISION A	ATA 32 - ELECTRICAL WHEEL BRAKE CABLE ASSY REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0281 COMPLIANCE: NOT APPLICABLE DUE TO S/N AIRCRAFT NOT AFFECTED AND AIRCRAFT ACCOMPLISHED SB 139-137 REVISION C
Standard SBs	SB NO. 139-605	ATA 32 - ELECTRICAL WHEEL BRAKE CABLE ASSY REPLACEMENT	-	-	-/SUPERSEDED	THIS SB HAS BEEN SUPERSEDED BY SB 139-605 REVISION A DATED 04.06.2020
Standard SBs	SB NO. 139-464, NEW ISSUE	ATA 93 - INSTALLATION OF KIT SKYFORCE DIGITAL MAP	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST (OPTIONAL SB) REFER TIC-AW139-21-0280 DATED 25.08.2021
Standard SBs	SB NO. 139-462, NEW ISSUE	ATA 25 - INSTALLATION OF ACTIVE NOISE REDUCTION HEADSET	-	-	-/OPTIONAL	TIC-AW139-21-0279 OPTIONAL SB AND COMPLIANCE AT CUSTOMER REQUEST APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO 139-474, NEW ISSUE	ATA 97 - INSTALLATION OF MAX VIZ UNDER FUSELAGE	-	-	-/OPTIONAL	OPTIONAL SB: APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER TIC-AW139-21-0278 DATED 25.08.2021
Standard SBs	SB NO. 139-463, NEW ISSUE	ATA 46 - INSTALLATION OF KIT CENTRAL DISPLAY	-	-	-/OPTIONAL	OPTIONAL SB: APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER TIC-AW139-21-0277 DATED 25.08.2021
Standard SBs	SB NO. 139-548, REVISION A - PART 1	ATA 30 - LH VERNIER ICE DETECTOR WITH LIGHT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED REFER TIC-AW139-21-0276 DATED 25.08.2021
Standard SBs	SB NO. 139-548, REVISION A PART II	ATA 30 - LH VERNIER ICE DETECTOR WITH LIGHT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED REFER TIC-AW139-21-0276 DATED 25.08.2021
Standard SBs	SB NO. 139-548, REVISION A PART III	ATA 30 - LH VERNIER ICE DETECTOR WITH LIGHT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED REFER TIC-AW139-21-0276 DATED 25.08.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	34
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-548	ATA 30 - LH VERNIER ICE DETECTOR WITH LIGHT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	300H//1Y SBA139-661 REV.A PART II (EASA AD NO.: 2021-00	ATA 24 OVERHEAD PANEL INSPECTION REFERENCES: EASA AD NO	83.20	383.20	-/SUPERSEDED	SUPERSEDE TO SBA 139-661 REV. B DATED 09-MAY-2022
Standard SBs	300H//1Y SBA139-661 REV.A PART II (EASA AD NO.: 2021-00	ATA 24 OVERHEAD PANEL INSPECTION REFERENCES: EASA AD NO	28/01/2022	27/01/2023	-/SUPERSEDED	SUPERSEDE TO SBA 139-661 REV. B DATED 09-MAY-2022
Standard SBs	SB NO. 139-643, NEW ISSUE	ATA 25 - SINGLE TO DOUBLE HOIST CONVERSION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0273 APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION REASON: THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION ON HOW TO PERFORM THE INSTALLATION OF SINGLE TO DOUBLE HOIST VARIANT P/N 3G2591P01511.
Standard SBs	SB NO. 139-545 REVISION A	ATA 78 - EXHAUST RETROMOD	-	-	-/OPTIONAL	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	ASB NO. 139-648, REVISION A (PART I)	ATA 25 - LIFERAFT RESERVOIR INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE, REFER TO OEM BULLETIN TECHNICAL STATUS
Standard SBs	ASB NO. 139-648, REVISION A	ATA 25 - LIFERAFT RESERVOIR INSPECTION AND REPLACEMENT	-	-	-/COMPLIED WITH	PART II: APPLICABLE. TO BE COMPLIED WITHIN 25 FH FROM ISSUE DATE OR UPON REACH 50 FH, WHICEVER COMES LATER PART III: APPLICABLE. TO BE COMPLIED WITHIN 25 FH FROM ISSUE DATE COMPLIED WITH BY OEM, REFER TO OEM TECHNICAL BULLETIN STATUS

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	35
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-543, NEW ISSUE	ATA 71 - TUNNEL ASSY AND FIREWALLS RETROMOD	-	-	-/NOT INSTALLED	NOT APPLICABLE DUE TO HELICOPTER CONFIGURATION. REFER ANNEX 2 BOLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-630, NEW ISSUE	ATA 46 COMPLETION OF KIT PRIMUS EPIC PHASE 8 SOFTWARE RELEASE INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-554 REV A	ATA 28 - FEEDING LINE FUEL DRAIN INSTALLATION	-	-	-/NOT APPLICABLE	THIS SB HAS BEEN SUPERSEDED BY SB 139-554 REVISION B DATED 23.12.2020
Standard SBs	SB NO 139-554, REVISION B	ATA 28 FEEDING LINE FUEL DRAIN INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-639, NEW ISSUE	ATA 53 UPPER DECK PANEL REINFORCEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. HELICOPTER NOT AFFECTED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-622, NEW ISSUE	ATA 28 - KIT CLOSED CIRCUIT REFUELLING RECEIVER (CCRR)	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	ASB139-654 PART I	MAIN ROTOR SWASHPLATE BOOT INSPECTION	7.55	-	-/COMPLIED WITH	PART I: COMPLIED WITH BY MANUFACTURER. INSPECTION / ADHESIVE RESTORING PERFORMED AT 07.55 FH PART II: APPLICABLE. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB NO. 139-157 REV C	PRIMUS EPIC® FLIGHT SOFTWARE RELEASE 5.6.0 INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	36
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-284 REV F	ATA 31 - INSTALLATION OF FDR AND RIPS VARIANTS P/N 3G3106P01311 AND P/N 3G3106P01312	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-620, REVISION B PART I	ATA 31 - INSTALLATION OF MPFR P/N D51615-142-090	-	-	-/COMPLIED WITH	NOT APPLICABLE. MPFR P/N D51615-142-090 ALREADY INSTALLED ON AIRCRAFT. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-620, REVISION B PART II	ATA 31 - INSTALLATION OF MPFR P/N D51615-142-090	-	-	-/COMPLIED WITH	NOT APPLICABLE. MPFR P/N D51615-142-090 ALREADY INSTALLED ON AIRCRAFT. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO.139-620, REVISION A PART II	INSTALLATION OF MPFR P/N D51615-142-090	-	-	-/SUPERSEDED	THE REVISION B OF THIS SB CANCELS AND SUPERSEDES THE REVISION A DATED APRIL 9, 2020
Standard SBs	SB NO. 139-620, NEW ISSUE	ATA 31- INSTALLATION OF MPFR P/N D51615-142-090	-	-	-/SUPERSEDED	THE REVISION B OF THIS SB CANCELS AND SUPERSEDES THE REVISION A DATED APRIL 9, 2020 REVISION A IS ISSUED TO UPDATE THE TEST PROCEDURE IN PART II
Standard SBs	SB NO. 139-584, NEW ISSUE	ATA 25 - KIT PILOT/COPILOT GENERAL HOLDERS	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SBA 139-637 REV. A (EASA AD 2020-0131)	ATA 25 HOIST CABLE CUTTER FRAME INSTALLATION	-	-	-/KIT NOT INSTALLED	NOT APPLICABLE DUE TO KIT NOT INSTALLED REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	37
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-634, NEW ISSUE	ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS)	-	-	-/OPTIONAL	APPLICABLE. INSTALLED PART NUMBER 965-1595-024. COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-512, NEW ISSUE	ATA 53 TAIL PLANE FITTING BUSHINGS INSPECTION	-	-	-/NOT APPLICABLE	TAIL PLANE NOT AFFECTED. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-358 REV. A	ATA 71- EXHAUST DUCTS AND REAR FIREWALL RETROMOD	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB NO.139-599 PART I	ATA 18 - ACTIVE VIBRATION CONTROL SYSTEMS (AVCS) OMNI CONTROL PANEL & SOFTWARE UPGRADE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT CONFIGURATION. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO.139-599 PART II	ATA 18 - ACTIVE VIBRATION CONTROL SYSTEMS (AVCS) OMNI CONTROL PANEL & SOFTWARE UPGRADE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT CONFIGURATION. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-635 REV./	ATA 29 TORQUE CHECK OF THE POWER CONTROL MODULE BOLTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-635 REV./	ATA 29 TORQUE CHECK OF THE POWER CONTROL MODULE BOLTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	38
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ASB NO. 139-633, REV A	ATA 25 - RESTRICTION IN FORWARD FACING PASSENGER SEATS INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	ASB NO. 139-633, NEW ISSUE	ATA 25 - RESTRICTION IN FORWARD FACING PASSENGER SEAT INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	ASB NO. 139-633, NEW ISSUE	ATA 25 - RESTRICTION IN FORWARD FACEING PASSENGER SEATS INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-631, NEW ISSUE	ATA 33 - HELICOPTER EMERGENCY EXIT LIGHT SYSTEM (HEELS) INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-583, NEW ISSUE PART III	ATA 62 - ROTATING SWASHPLATE ASSY P/N 3G6230A00333	-	-	-/NOT APPLICABLE	PART III: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-583 (PART II)	ATA 62 - ROTATING SWASHPLATE ASSY P/N 3G6230A00333	-	-	-/NOT APPLICABLE	PART I AND II: NOT APPLICABLE DUE TO DIFFERENT COMPONENT PART NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-583 (PART I)	ATA 62 - ROTATING SWASHPLATE ASSY P/N 3G6230A00333	-	-	-/NOT APPLICABLE	PART I AND II: NOT APPLICABLE DUE TO DIFFERENT COMPONENT PART NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	39
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO.139-585 (PART II)	ATA 95 - RIGHT AFT FLOAT INSPECTION AND BAGGAGE FLOOR PANEL RETROMODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-334	VHF/FM NAT NPX138 KIT P/N 4G2310F02411, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB NO 139-334, PART I	ATA 23-VHF/FM NAT NPX138 KIT P/N 4G2310F02411	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-544, REV A	ATA 25 - INSTALLATION OF KIT LIFE RAFTS	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-471	ATA 52 - SOFT COVER FAIRING LIFERAFT RETROMOD	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-627, NEW ISSUE	ATA 93 PROVISION INSTALLATION FOR KIT FLIR SAFIRE 380 HD ON REPLACEMENT TAIL ASSEMBLY	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-626 REV./	ATA 23 PROVISION INSTALLATION FOR KIT SATCOM SKYCONNECT ON REPLACEMENT TAIL ASSEMBLY	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-628 REV./	ATA 23 PROVISION INSTALLATION FOR KIT HF ON REPLACEMENT TAIL ASSEMBLY	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	40
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB139-557 REV. A	ATA 25 HOIST CABLE CUTTER FRAME INSTALLATION	-	-	-/CANCELLED	REVISION A IS ISSUED IN ORDER TO CANCEL THIS SERVICE BULLETIN. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-396 REV. B	ATA 25 - INSTALLATION OF KIT SINGLE HOIST GOODRICH	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-608, NEW ISSUE	ATA 53 INSPECTION OF BL 275 (LH/RH) AT STA 3500	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-148, REVISION A	ATA 25 - COMPLETE PROVISION FOR EMS (MEDEVAC) P/N 4G2564F00211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-148	COMPLETE PROVISIONS FOR EMS (MEDEVAC) P/N 4G2564F00211, INSTALLATION OF.	-	-	-/SUPERSEDED	THIS SB HAS BEEN SUPERSEDED BY SB NO. 139-148 REVISION A DATED 11-MAY-2020
Standard SBs	SB NO. 139-537, NEW ISSUE	ATA 95 - DART EMERGENCY FLOTATION LIFE RAFT IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-540 REV./	ATA 25 - BREEZE HOIST CHANGE FROM 90M TO 75M	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-604 REV./	ATA 66 INSTALLATION OF KIT MOORING	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	41
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-570, NEW ISSUE	ATA 95 EFS FLOAT ASSY INFLATION SYSTEM NEW THERMOMANOMETER	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-595, NEW ISSUE	ATA 52 - COCKPIT DOOR EMERGENCY RELEASE MECHANISM CHECK	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-132 REVISION A	COLLECTIVE EMERGENCY LIFERAFT CONVERSION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-563, NEW ISSUE	ATA 93 - AVIONIC VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-550, NEW ISSUE	ATA 93 - INSTALLATION OF KIT FLIR WESCAM MX-10	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-551 REVISION A	ATA 93 - INSTALLATION OF KIT FLIR WESCAM MX-10	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-357 REV A	KIT 2ND GPS P/N 4G3450F00611 OR 2ND GPS SBAS P/N 4G3450F00613	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-357 REV B DATED 23-MAR-2020

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	42
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-357, REVISION B	ATA 34 - KIT 2ND GPS P/N 4G3450F00611 OR KIT 2ND SBAS P/N 4G3450F00613	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-130, REVISION A	ATA 34- KIT 2ND GPS P/N 4G3450F00611 OR KIT GPS SBAS P/N 4G3450F00613	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-061, REVISION B	KIT 2ND GPS P/N 4G3450F00611 OR KIT 2ND GPS SBAS P/N 4G3450F00613, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT139-061 REV. A	KIT 2ND GPS P/N 4G3450F00611 OR KIT 2ND GPS SBAS P/N 4G3450F00613, INSTALLATION OF.	-	-	-/SUPERSEDED	SUPERSEDE TO BT 139-061 REV. B DATED 23-MAR-2020.
Standard SBs	139-061 REV A.	Kit 2ND GPS P/N 4G3450F00611 or KIT 2ND GPS SBAS P/N 4G3450F00613, installation of	-	-	-/SUPERSEDED	SUPERSEDE TO BT 139-061 REV. B DATED 23-MAR-2020.
Standard SBs	SB NO. 139-598, NEW ISSUE (PART I & II)	ATA 78 - INSTALLATION OF EXHAUST NOZZLE BLANKET	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-598, NEW ISSUE (PART III & IV)	ATA 78 - INSTALLATION OF EXHAUST NOZZLE BLANKET	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-037 REV./	ATA 53 - NLG ACTUATOR FITTING RETRO MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-083, REVISION A	ATA 25 - FAST ROPING KIT P/N 4G2590F00211.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	43
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-612	ATA 11 - FAST ROPING DECAL REPLACEMENT	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-621, NEW ISSUE	ATA 71- INSTALLATION OF EAPS REMOVABLE PARTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-597 NEW ISSUE	ATA 31 - KIT FAMILY HUMS RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-607, NEW ISSUE	ATA 21- INSTALLATION OF DUAL ZONE HEATING CABIN DUCT VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SBA 139-614, NEW ISSUE	ATA 26 FIRE EXTINGUISHER INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-594, NEW ISSUE (PART I AND II)	ATA 32 - INSPECTION OF MAIN LANDING GEAR ACTUATOR BOLTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SBA NO. 139-610, NEW ISSUE	ATA 95 - EMERGENCY FLOATATION SYSTEM, FLOAT SUPPLY HOSE INSPECTION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	44
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-527, NEW ISSUE	ATA 95- INSTALLATION OF COCKPIT AND CABIN PASSENGER FLOOR BALLISTIC PROTECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB NO. 139-153 REVISION A	LONGITUDINAL AUXILIARY FUEL TANK KIT P/N 4G2800F00111, INSTALLATION OF	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER OPTION. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-475 PART I	ATA 23 - INSTALLATION OF KIT ICS 9000 CABIN STATION 4	-	-	-/NOT APPLICABLE	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-475 PART II	ATA 23 - INSTALLATION OF KIT ICS 9000 CABIN STATION 4	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	TMI 139-475, REVISION C	ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REPLACEMENT PROCEDURE	-	-	-/NOT APPLICABLE	REFER TIC-AW139-22-0103
Standard SBs	SB NO. 139-491	ATA 63 - AGB INPUT MODULE ASSY VARIANT	-	-	-/NOT APPLICABLE	KIT FIPS NOT INSTALLED. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-579	ATA 99 INSTALLATION OF KIT SIAP AND RWR AND LWR	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-525, REVISION A	ATA 95 - INSTALLATION OF INFLATION SERVICE CHARTS	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-558, NEW ISSUE	ATA 24 - UTILITY CB PANEL LH RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	45
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-510, NEW ISSUE	ATA 34 - WEATHER RADAR (1500B+) 2ND CONTROL PANEL INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER LEONARDO HELICOPTERS ANNEX 2 BOLLETTINO TECNICI STATUS LIST DATED: 17.12.2020
Standard SBs	SB NO. 139-592 PART I & IV	ATA 21 - ECS FIRE BLANKET IMPROVEMENT	-	-	-/COMPLIED WITH	PART I AND IV: COMPLIED WITH BY MANUFACTURER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-592 PART II & III	ATA 21 - ECS FIRE BLANKET IMPROVEMENT	-	-	-/NOT APPLICABLE	PART II AND III: NOT APPLICABLE DUE TO COMPONENT NOT INSTALLED ON AIRCRAFT. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-567 REVISION B	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	-	-	-/SUPERSEDED	THIS SB IS CANCELLED AND SUPERSEDED BY SB 139-609
Standard SBs	SB 139-137 REV C PART I AND II	KIT POWERED PARKING BRAKE MODULE P/N 3G3240F00111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	PART I AND II: NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-137 REVISION C PART III	KIT POWERED PARKING BRAKE MODULE P/N 3G3240F00111, INSTALLATION OF.	-	-	-/COMPLIED WITH	PART III: COMPLIED WITH BY MANUFACTURER
Standard SBs	SB NO 139-258, REVISION A	ATA 33- INSTALLATION OF SX16 IFCO NVG VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REFER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-590, NEW ISSUE	ATA 34 - INSTALLATION OF KIT DF	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	46
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-542, NEW ISSUE	ATA 25 - INSTALLATION OF KIT BAGGAGE BOX	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-316, NEW ISSUE	ATA 53 - ANCHOR NUTS IN FUEL TANK AREA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-439, REVISION A PART I	ATA 22 - INSTALLATION OF KIT FOUR AXIS ENHANCED FLIGHT	-	-	-/NOT APPLICABLE	PART I: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB NO 139-439, REVISION A	ATA 22 - INSTALLATION OF KIT FOUR AXIS ENHANCED FLIGHT DIRECTOR	-	-	-/OPTIONAL	PART II: TO BE COMPLIED. AIRCRAFT EQUIPPED WITH KIT 4AXIS BASIC FD P/N 4G2210F00511
Standard SBs	SB NO 139-541 PART I & II, NEW ISSUE	ATA 23 - KIT EXTERNAL LOUDSPEAKERS 900W	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-603, NEW ISSUE	ATA 93 - FLIR SS380HDC TFU VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-591, NEW ISSUE	ATA 24 - CB PANEL VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-487	ATA 53 - BL 0.0 NOSE REINFORCEMENT RETROMOD N	-	-	-/NOT APPLICABLE	PART I AND II: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	47
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-555, NEW ISSUE	ATA 00- INTERIORS RECONFIGURATION FROM VIP TO OFFSHORE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-318 REV A PART I AND II	ATA 33 - INSTALLATION OF STROBE LIGHTS KIT P/N 4G3340F00412	-	-	-/NOT APPLICABLE	PART I AND PART II: NOT APPLICABLE DUE TO COMPONENT DIFFERENT PART NUMBER
Standard SBs	BT 139-318 REV A PART III	ATA 33 - INSTALLATION OF STROBE LIGHTS KIT P/N 4G3340F00412	-	-	-/COMPLIED WITH	PART III: COMPLIED WITH BY MANUFACTURE
Standard SBs	BT 139-038 REV G PART I, II AND III	ATA 31 - INSTALLATION OF KIT HEALTH AND USAGE MONITORING SYSTEM	-	-	-/OPTIONAL	INSTALLED KIT FAMILY HUMS. COMPLY UPON CUSTOMER REQUEST.
Standard SBs	SB NO 139-546, NEW ISSUE	ATA 24 - AUXILIARY OVER HEAD PANEL RETRO MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-457 REV A	ATA 25 - INSTALLATION OF BREEZE-EASTERN EXTERNAL HOIST	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-457 REV./	ATA 25-INSTALLATION OF BREEZE-EASTERN EXTERNAL HOIST	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB NO 139-556, NEW ISSUE	ATA 64 - TAIL ROTOR BLADE LIGHTNING STRIPS P/N 3G6410A03053	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO 139-495 REV.A	ATA 31 - FDR AND RIPS VARIANT ULB REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH DURING MANUFACTURE. REFER ANNEX 2 BOLLETTINO TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-572	ATA 25 - FORWARD FACING 1ST ROW PASSENGER SEATS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	48
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB139-549	ATA 97- INSTALLATION OF KIT AVALEX DIGITAL VIDEO RECORDER	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-552 REV./	ATA 93 - AVIONIC VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-573, NEW ISSUE	ATA 31 - KIT HUMS COMPLETION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-593 REV. A	ATA 71 - ENGINE MOUNTING RODS REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-450 REV D	ATA 62 - MAIN ROTOR DAMPER INSPECTIONS	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT AFFECTED BY PART NUMBER
Standard SBs	SB 139-501 REV B	ATA 62 -MAIN ROTOR BLADE ASSY UPGRADE	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB139-535 REV./	ATA 23 - INSTALLATION OF KIT EXTERNAL LOUDSPEAKERS	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-198 REV. B	SECONDARY AVIONIC BAY, MODIFICATION OF	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATE 18.02.2021
Standard SBs	BT 139-027 REV B	PART I: CARGO HOOK KIT P/N 3G2592F00111 INSTALLATION. PART II: VIDEO MODULE INTERFACE KIT P/N 3G9310F00212 INSTALLATION. PART III: CARGO HOOK VIDEO CAMERA KIT P/N 3G9770F00111 INSTALLATION.	-	-	-/OPTIONAL	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	49
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-385 PART I	ATA 93 - INSTALLATION OF KIT VIDEO MODULE INTERFACE P/N 3G9310F00212, 4G9310F00211 OR P/N 4G9310F00212	-	-	-/NOT APPLICABLE	PART I: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	139-385 PART II	ATA 93 - INSTALLATION OF KIT VIDEO MODULE INTERFACE P/N	-	-	-/COMPLIED WITH	PART II: COMPLIED WITH BY MANUFACTURER
Standard SBs	SB139-532 REV. /	ATA 99 - INSTALLATION OF KIT SIAP AND RWR AND LWR	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	B139-580, NEW ISSUE	SATA 64 - FIPS TAIL ROTOR BLADES INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-561 REV. /	ATA 93 - VIDEO CUSTOMIZATION AND CB PANEL REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-521 REV./	ATA 28 - INSTALLATION OF MAIN LH AND RH SELF-SEALING FUEL TANKS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB 139-529 REV./	ATA 97 - INSTALLATION OF KIT AVALEX DIGITAL VIDEO AUDIO RECORDER	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	SB 139-536 REV./	ATA 23 - ICS CABIN STATION 4 REPOSITIONING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-531 REV./	ATA 99 - SDU SUPPORT IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB139-566 REV./	ATA 99 - EWP/CDU SOFTWARE UPGRADE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	50
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB139-560 REV./	ATA 25 - INSTALLATION OF THE TWO-PIECE DRESS COVER AND CUSHION ON OFFSHORE PASSENGER SEAT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB139-571, NEW ISSUE	ATA 64 - DUPLEX BEARING P/N 3G430V00153 RECALL	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-375 PART I, II, III, AND IV	ATA 24 - AUXILIARY CIRCUIT-BREAKER PANEL MODIFICATIONS	-	-	-/NOT APPLICABLE	PART I: NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED PART II, III, AND IV: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-156 REV. A	EADS TETRA RADIO KIT P/N 3G2310A02511, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB 139-499	ATA 30 - ROTORS ICE PROTECTION CABLES CONNECTORS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-025 REV.A	INSTALLATION OF THE KTA 970 TCAS I SYSTEM, WITH APPLICATION OF THE KIT P/N 3G3450F00311.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-528	ATA 62 - MAIN ROTOR SLIP RING CONNECTOR MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED
Standard SBs	SB 139-509	ATA 71 - INSTALLATION OF EAPS REMOVABLE PARTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-498	ATA 32 - NLG SERVICING PLATE REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	51
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	TMI 139-533, NEW ISSUE	FRAME STA 3120 - SPECIFIC REPAIR PROCEDURE	-	-	-/NOT APPLICABLE	KIT NOT INSTALLED REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB139-533	ATA 95 EFS AFT FLOAT ASSY INFLATION SYSTEM RESET PROCEDURE	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	SB 139-266 REV. A	ATA 25 - INSTALLATION OF KIT BAMBİ BUCKET PROVISION	-	-	-/SUPERSEDED	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-517	ATA 25 - INSTALLATION OF KIT SACKSAFOAM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-523	ATA 25 - HELICOPTERS SOUNDPROOFING REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-492	ATA 29 - INSTALLATION OF HYDRAULIC PULSATION DAMPENER	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-489	ATA 46 - INSTALLATION OF KIT CENTRAL DISPLAY SIRIO PANEL	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-513	ATA 30 - INSTALLATION OF WINDSHIELD WASHING SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-514	ATA 52 - INSTALLATION OF KIT SAR PROTECTION STEP	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-444 REV C	ATA 78 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD	-	-	-/OPTIONAL	APPLICABLE.AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	EXHAUST DUCTS AND REAR FIREWALL RETROMOD - INSTALLATION	BT 139-444 REV A	-	-	-/COMPLIED WITH	SUPERSEDED BY BT 139-144 REV B
Standard SBs	ATA 78 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD	BT 139-444 REV B	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT 139-444 REVISION C DATED 28-JUNE-2018
Standard SBs	SB 139-534 REV. /	ATA 53 - STA 3120 FRAME INSPECTION	-	-	-/NOT APPLICABLE	AIRCRAFT NOT AFFECTED BY SERIAL NUMBER
Standard SBs	SB 139-530 REV. /	ATA 22 - REPLACEMENT OF AUTO FLIGHT TRIM ACTUATOR	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	52
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-511	ATA 53 - REMOVABLE OANELS RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-453 REV A	ATA 32 - LEFT AND RIGHT MAIN LANDING GEAR UPGRADE	-	-	-/COMPLIED WITH	NOT APPLICABLE. MODIFICATION ALREADY IMPLEMENTED
Standard SBs	BT 139-506	ATA 30 - WIPERS AND WASHING SYSTEM RETROMOD	-	-	-/NOT APPLICABLE	PART I, II, III AND IV: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER PART V: NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED
Standard SBs	BT 139-520	ATA 62 - MAIN ROTOR BLADE TIP CAP RECURRENT INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT COMPONENT SERIAL NUMBER
Standard SBs	BT 139-341 REV A	ATA 62 - INSTALLATION OF MAIN ROTOR SCISSORS P/N 3G6230A00733	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH MAIN ROTOR SCISSORS PART NUMBER 3G6230A00732
Standard SBs	BT 139-452 REV B PART II	ATA 62 - MAIN ROTOR DAMPER INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	PART II: NOT APPLICABLE DUE TO COMPONENT NOT AFFECTED BY PART NUMBERS
Standard SBs	BT 139-452 REV B PART I	ATA 62 - MAIN ROTOR DAMPER INSPECTION AND REPLACEMENT	-	-	-/COMPLIED WITH	PART I: COMPLIED WITH BY MANUFACTURE
Standard SBs	BT 139-452 REV A PART I	MAIN ROTOR (MR) DAMPER BODY END	-	-	-/FOR INFO ONLY	PART I: COMPLIED WITH BY MANUFACTURE
Standard SBs	BT 139-452 REV A PART I	MAIN ROTOR (MR) DAMPER BODY END	-	-	-/COMPLIED WITH	PART I: COMPLIED WITH BY MANUFACTURE
Standard SBs	MAIN ROTOR (MR) DAMPER BODY END INSPECTION	BT 139-452 REV / PART I	-	-	-/COMPLIED WITH	PART I: COMPLIED WITH BY MANUFACTURE
Standard SBs	MAIN ROTOR (MR) DAMPER BODY END INSPECTION	BT 139-452 REV / PART I	-	-	-/CANCELLED	PART I: COMPLIED WITH BY MANUFACTURE
Standard SBs	BT 139-526 PART I (INITIAL - WITHIN 50FH ONCE REACH 70	ATA 63 - MGB OIL COOLING FAN INSPECTION	0.00	700.00	-/TO BE COMPLIED	PART I: APPLICABLE IF THE COOLING FANS LOGGED REACHED 700 FH AND 1200 FH SINCE NEW OR SINCE LAST OVERHAUL.
Standard SBs	BT 139-494	ATA 71 - INSTALLATION OF THE EJECTION SPRING ASSY	-	-	-/COMPLIED WITH	NOT APPLICABLE. MODIFICATION ALREADY IMPLEMENTED
Standard SBs	BT 139-441 REV. A	ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) SOFTWARE	-	-	-/NOT APPLICABLE	NOT APPLICABLE. INSTALLED EGPWS COMPUTER NOT AFFECTED

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	53
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ATA 34 - INSTALLATION OF TRANSPONDER (XPDR) WITH ADS-B	BT 139-313 REVISION A PART II & V	-	-	-/NOT APPLICABLE	PART I, III AND IV: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER PART II AND V: NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON HELICOPTER
Standard SBs	BT 139-313 PART I, III & IV	TRANSPONDER (XPDR) WITH ADS-B OUT - INSTALLATION	-	-	-/NOT APPLICABLE	PART I, III AND IV: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER PART II AND V: NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON HELICOPTER
Standard SBs	139-173 REV. C PART II	ATA 22 - INSTALLATION OF KIT 4 AXIS ENHANCED FLIGHT DIRECTOR WITH SAR MODES	-	-	-/OPTIONAL	PART II: APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-173 REV C PART I,III,AND IV	KIT FOUR AXIS ENHANCED FLIGHT DIRECTOR WITH SAR MODES	-	-	-/NOT APPLICABLE	PART I AND III: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER PART IV: NOT APPLICABLE. RESCUE HOIST KIT PART NUMBER 3G2591F00111 NOT INSTALLED
Standard SBs	BT 139-382 REV B PART II	ATA 34 - INSTALLATION OF KIT 2ND TRANSPONDER ADS-B OUT	-	-	-/OPTIONAL	PART II: APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-382 REV B PART I AND III	ATA 34 - INSTALLATION OF KIT 2ND TRANSPONDER ADS-B OUT	-	-	-/NOT APPLICABLE	PART I AND III: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-382 REV PART II	INSTALLATION OF KIT 2ND TRANSPONDER ADS-B OUT P/N 3G3450F00517.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-382 REVISION B DATED 14-MAR-2018
Standard SBs	BT 139-382 REV A PART I	INSTALLATION OF KIT 2ND TRANSPONDER ADS-B OUT P/N 3G3450F00517.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-382 REVISION B DATED 14-MAR-2018
Standard SBs	BT 139-451 REV A	ATA 28 - INSTALLATION OF KIT AUXILIARY FUEL TANK	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-504	ATA 00 - HELICOPTER S/N 31724 RECONFIGURATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	54
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-237 REV A	KIT STATIC DISCHARGE - INSTALLATION	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-237 REV A	KIT STATIC DISCHARGE - INSTALLATION	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-237 REV A PART I	ATA 23 - INSTALLATION OF KIT STATIC DISCHARGE	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-497 REV. /	ATA 00 - CORROSION PROTECTION IMPROVEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-279 REV A	ATA 71 - ADDITIONAL COWLING LATCHES KIT	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB 139-505 REV. /	ATA 21-VCs CONDENSER PACK RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON AIRCRAFT
Standard SBs	SB 139-507 REV. /	ATA 24-AUX O/H CB PANEL RETRO MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-018 REV C	MIDDLE SECTION FRAME 5700 INSPECTION.	-	-	-/CANCELLED	CANCELLED. SUPERSEDED BY AMPI MANDATORY INSPECTION MI53-12 (REF. DM 39-A-04-20-00-00A-028E-P).

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	55
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ATA 46 - PRIMUS EPIC® FLIGHT SOFTWARE RELEASE 7.12 & 7.	SB NO. 139-500 REV. / PART II & IV	-	-	-/COMPLIED WITH	PART II, IV: APPLICABLE. AIRCRAFT INSTALLED WITH THE LATEST VERSION OF SOFTWARE 7.12.2
Standard SBs	ATA 46 - PRIMUS EPIC® FLIGHT SOFTWARE RELEASE 7.12 & 7.	SBO NO. 139-500 REV. / PART I & III	-	-	-/NOT APPLICABLE	PART I, III: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB 139-493 REV. /	ATA 25 - INSTALLATION OF KIT CHART HOLDER	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-143 REV. /	ATA 28 - KIT CLOSE CIRCUIT REFUEL RECEIVER P/N 4G2820F00211	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-459 REV. /	ATA 71 - EAPS TO IBF RETROFIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-473 REV A	ATA 53 - CABIN DRAIN HOLES RETROMOD	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	SB 139-508 REV. /	ATA 62 -MAIN ROTOR BLADE TIP CAP INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFEERENT COMPONENT SERIAL NUMBER
Standard SBs	BT 139-352 REV. /	ATA 32 - INSTALLATION OF SLUMP PROTECTION PADS	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-461 REV. /	ATA 00-JOINT AVIATION COMMAND (JAC) RE-CONFIGURATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB139-490 REV. /	ATA 63 -MGB OIL COOLING FAN INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED AND REPLACED BY SB139-526
Standard SBs	BT 139-477 REV. /	ATA 53 - RH SHACKLE TIEDOWN FITTINGS	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT139-480 REV A	ATA 31- HUMS UPLOAD OF ON-BOARD SYSTEM CONFIGURATION (OBSC)	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT INSTALLED KIT FAMILY HUMS PART NUMBER 4G3130F00611
Standard SBs	BT 139-379 REV A	ATA 98 - INSTALLATION OF LIGHTNING SENSOR SYSTEM KIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT139-437 REV. /	ATA 53 - INSPECTION AND REPLACEMENT OF LIGHTNING SENSOR SYSTEM SUPPORT ASSY P/N 3G5315A82231	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-182 REV A	ATA 98- INSTALLATION OF LIGHTNING SENSOR SYSTEM KIT	-	-	-/OPTIONAL	COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-449 REV A	ATA 31-INSTALLATION OF QUICK ACCESS RECORDER	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-434 REV A	ATA 71 - TUNNEL ASSY RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH TUNNEL ASSY PART NUMBER 3G7130A13431
Standard SBs	BT 139-484 REV. /	ATA 18 - INSTALLATION OF ACTIVE VIBRATION CONTROL SYSTEM OMNI (SAR) KIT P/N 4G1830F00611	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	56
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-479 REV. /	ATA 21- REMOVAL OF ENVIRONMENTAL CONTROL SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-482 REV. /	ATA 29 - INSTALLATION OF KIT HYDRAULIC PULSATION DAMPEN	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-485 REV. /	ATA 98 - INSTALLATION OF LIGHTNING SENSOR SYSTEM	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	139-155 REV. B PART II	ATA 33 - 2ND ANTICOLLISION LIGHT KITS	-	-	-/NOT APPLICABLE	PART II: NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-155 REV B PART I AND III	ATA 33 - 2ND ANTICOLLISION LIGHT KITS.	-	-	-/COMPLIED WITH	PART I AND III: COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-486 REV. /	ATA 25 - INSTALLATION OF KIT ELT	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-347 REV A	ATA 46- REMOVABLE PARTS OF MISSION EQUIPMENTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-478 REV. /	ATA 52 INSTALLATION OF KIT NOSE LANDING GEAR DOORS	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	SB 139-469	ATA 30 - PASSENGER CABIN DRAINAGES INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB 139-481 REV. /	ATA 33 - INSTALLATION OF PULSE LIGHTS ON SPONSONS	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	SB 139-468	ATA 26- LEFT AND RIGHT FIRE DETECTION SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	SB 139-472 REV. /	ATA 62 - MAIN ROTOR SLIP RING	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED
Standard SBs	BT 139-141 REV. /	ATA 25 - CHART HOLDER REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH KIT PILOT/COPILOT CHART HOLDER WITH PART NUMBER 4G2510F00911
Standard SBs	SB 139-215 REV. /	ATA 33 - INSTALLATION OF HID STEERABLE LANDING LIGHTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-442 REV. /	ATA 25 - DEPLOYABLE ELT INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO THE ELT KIT WITH DEPLOYABLE P/N 3G2560F00311 NOT FITTED ON AIRCRAFT
Standard SBs	BT 139-297 REV A	TRAKKA A800 SEARCHLIGHT KITS P/N 4G3340F02411 AND P/N 4G3340F02412	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	TRAKKA A800 SEARCHLIGHT KITS INSTALLATIONS	BT 139-297 REV /	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	57
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-364 REV. /	TRAKKA SEARCHLIGHT ASSEMBLY	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-392 REV A	MAIN ROTOR (MR) SCISSOR LEVER BEARING P/N 3G6230V00654	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED MAIN ROTOR SCISSOR LEVER BEARING PART NUMBER 3G6230V00655 LEONARDO HELICOPTERS ANNEX 2 BOLLETTINO TECNICI STATUS LIST DATED: 17.12.2020
Standard SBs	BT 139-465 REV A	TAIL ROTOR DRIVE SHAFT (TRDS) INTERFERENCE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	TAIL ROTOR DRIVE SHAFT (TRDS) INTERFERENCE	BT 139-465 REV /	-	-	-/SUPERSEDED	SUPERSEDED TO BT 139-465 REV A N/A BY AIRCRAFT S/N
Standard SBs	TAIL ROTOR DRIVE SHAFT (TRDS) INTERFERENCE	BT 139-465 REV A	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-429 REV. /	WEIGHT EXTENSION 7000 KG	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-440	PRIMUS EPIC WIRINGS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT139-435 REV. /	DISPLAY INSTALLATION UPDATE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-460 REV. /	BREEZE RESCUE HOIST EXTENDED CABLE LENGTH KIT COMPLETION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-470 REV. /	TAIL/REAR FUSELAGE ATTACHMENT FITTINGS	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT EQUIPPED WITH TAIL ASSY PART NUMBER 3G5350A00136
Standard SBs	BT 139-466 REV. /	MAIN ROTOR (MR) SERVOACTUATOR DOWEL PINS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-287 REV. /	USB VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-063 REV. /	FIRE PANEL CONNECTIONS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/ N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	58
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-040 REV B	WIRE STRIKE PROTECTION KIT P/N: 4G9540F00211 INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/ N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-040 REV B	WIRE STRIKE PROTECTION KIT P/N: 4G9540F00211 INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/ N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-432 REV. /	POWER LINE DETECTOR RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-034 REV C	HF SYSTEM KIT P/N 3G2310F00211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N REFER ANNEX2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-422 REV. /	EMERGENCY MEDICAL SERVICE (EMS) MEDEVAC PROVISION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-393 REV. /	SLIDING PASSENGER DOOR ASSEMBLY IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-158 REV A	KIT RIGID HANDLE ON PASSENGER DOORS	-	-	-/NOT APPLICABLE	NOT APPLICABLE ON ENHANCED PLUS FUSELAGE. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-454 REV. /	KIT ICS 9000 CABIN STATION 4 P/N 4G2350F00911	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-456 REV. /	KIT SATCOM LATITUDE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-303 REV. /	MAIN GEARBOX (MGB) INPUT MODULES BEARINGS	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED.
Standard SBs	BT 139-274	TAIL GEAR BOX (TGB) CENTRAL HOUSING - INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED TAIL GEARBOX ASSY PART NUMBER 3T6522A00246
Standard SBs	BT 139-413 REV. /	KIT SATCOM SKYCONNECT (PTA12-300) P/N 4G2310F01111	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-268 REV. /	UPPER REAR PANEL - REPLACEMENT	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	59
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-394 REV. /	CIRCULAR FORCE (CF) ACTIVE VIBRATION CONTROL SYSTEM (AVCS) SOFTWARE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-389 REV A	GASKETS ANTENNA, LIGHTS AND ELECTRICAL EQUIPMENTS INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-433 REV. /	VHF/FM NAT NPX138 RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-296 REV /	TAIL ROTOR (TR) SHAFT REINFORCEMENT RETROMODIFICATION	-	-	-/NOT APPLICABLE	N/A BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-296 REV A	TAIL ROTOR (TR) SHAFT REINFORCEMENT RETROMODIFICATION P/N 3G5306P42512	-	-	-/NOT APPLICABLE	N/A BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-373 REV A	LEFT ENGINE ASSY FUEL INLET HOSE AND FIREWALL/FIRE DETECTION SYSTEM.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-428 REV. /	SIMOCO SRM9000 AND MOTOROLA XTL5000 RADIO EQUIPMENTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-066 REV A	DK120 UNDERWATER ACOUSTIC BEACON, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-448 REV. /	GOODRICH HOIST PENDANT VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-443 REV A	GOODRICH RESCUE HOIST OVERLOAD CLUTCH	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT INSTALLED ON AIRCRAFT
Standard SBs	BT 139-419	TAIL STRUCTURE ASSY IMPROVEMENT	-	-	-/NOT APPLICABLE	PART I,II,III: NOT APPLICABLE. AIRCRAFT FITTED WITH TAIL ASSY PART NUMBER 3G5350A00136
Standard SBs	BT 139-419 PART I, II AND III	TAIL STRUCTURE ASSY IMPROVEMENT	-	-	-/NOT APPLICABLE	TAIL ASSY NOT AFFECTED BY PART NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-366 REV A	LH (COPILOT) COLLECTIVE TORQUE TUBE COVER AND UNDERLYING CABLE ASSY	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-397	MAIN LANDING GEAR (MLG) SHOCK ABSORBER SCREWS REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH KIT INCREASED GROSS WEIGHT 6800 KG
Standard SBs	BT 139-418	REAR FUSELAGE STRUCTURE ASSY IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-436	R4A AIRBORNE AIS TRANSPONDER-SOFTWARE UPDATE	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON AIRCRAFT

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	60
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-401	KIT COCKPIT LIPSTICK CAMERA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-446	MAIN ROTOR (MR) DAMPER INSPECTIONS.	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT139-450 DATED 28.05.19
Standard SBs	BT 139-410 REV A	MAIN ROTOR (MR) DAMPER SPHERICAL BEARINGS AND ROD END INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT139-450 DATED 28.05.2019
Standard SBs	BT 139-424	PRIMUS EPIC® FLIGHT SOFTWARE RELEASE 7.10 (PHASE 7 V4)	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. SOFTWARE PHASE 7.12.2 INSTALLED
Standard SBs	BT 139-417	NEW ELASTOMERIC TAIL ROTOR DAMPER	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED ELASTOMERIC TAIL ROTOR DAMPER PART NUMBER 3G6420V00851
Standard SBs	BT 139-388	EXHAUST NOULE BLANKET REPLACEMENT RH P/N 3G7810P00131 OR P/N 3G7810P00132 AND LH P/N 3G7810P00231 OR P/N 3G7810P00232.	-	-	-/NOT APPLICABLE	APPLICABLE ONLY IN CASE OF NON REPAIRABLE DAMAGES OF THE THERMAL BLANKETS.
Standard SBs	BT 139-414	BRACKETS NOSE INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-445	ELT EQUIPMENT COMPLETION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-420	VADU FAREM ELECTRICAL VARIANT P/N 3G9310P002U	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-426	FLIR WESCAM MX-15I HD RETROMOD.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-409	RADIO TETRA EADS (THR9I)	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-438	KIT RH UTILITY CB PANEL	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT139-431	DEPLOYABLE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM INTERFACE UNIT (SIU)	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON AIRCRAFT
Standard SBs	BT 139-403	ROTOR ANALYSIS DIAGNOSTIC SYSTEM - ADVANCED TECHNOLOGY (RADS-AT) RETROMOD P/N 3G3130P00311	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-427	POWER CONTROL MODULE	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON AIRCRAFT
Standard SBs	BT 139-425	MAIN ROTOR ACTUATOR (MRA) P/N 3G6730V00531	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON AIRCRAFT
Standard SBs	BT 139-408	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) SLIP RING CABLES	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	61
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-374	EMERGENCY FLOATS CONTROL PANEL P/N 3G9560V00556 (NIGHT VISION GOGGLE -NVG) AND P/N 3G9560V00557 (STANDARD -STD).	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED WITH EMERGENCY FLOATS CONTROL PANEL PART NUMBER 3G9560V00558
Standard SBs	BT 139-430	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT 139-443 DATED 21.04.2016
Standard SBs	BT 139-402	MAIN ROTOR (MR) DAMPER BOLT P/N 3G6220A01252	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON HELICOPTER
Standard SBs	BT 139-412	CABIN LOAD INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-345	PENALTY FACTORS.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	TMI 139-345 Rev B	REAR FUSELAGE CENTRAL FITTING AT STA8700 P/N 3P5340A14153 REPLACEMENT PROCEDURE AW139	-	-	-/FOR INFO ONLY	TIC-AW139-21-0266 APPLICABILITY: APPLICABLE DUE TO COMPONENT MIDDLE LEFT BRACKET STA 8700 P/N 3P5340A14153 AND REAR FUSELAGE ASSY P/N 3P5340A00133 FITTED ON AIRCRAFT WITHOUT REAR FITTING REINFORCEMENT RETRO-MOD P/N 3G5306P38811 (SB 1390418). REFER TO SB STATUS.
Standard SBs	BT 139-219	SINGLE HOIST ELECTRICAL PROVISION MODIFICATION	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-218	DOUBLE HOIST ELECTRICAL PROVISION MODIFICATION.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-350 PART I AND III	TGB/IGB AND TAIL PLANE FITTINGS RETROMODIFICATIONS.	-	-	-/NOT APPLICABLE	PART I AND III: NOT APPLICABLE DUE TO DIFFERENT COMPONENT PART NUMBER
Standard SBs	BT 139-350 PART II	TGB/IGB AND TAIL PLANE FITTINGS RETROMODIFICATIONS.	-	-	-/OPTIONAL	PART II: APPLICABLE IF PRESENT COMPONENTS DAMAGED AND REPLACE WITH THE NEW ONE.
Standard SBs	BT 139-350 PART I	TGB/IGB AND TAIL PLANE FITTINGS RETROMODIFICATIONS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT COMPONENT PART NUMBER
Standard SBs	BT 139-395 REV A	KIT TCAS II P/N 4G3450F00211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-335 REV A	KIT SATCOM SKYTRAC ISAT-200 P/N 4G2310F03011	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-377	RETROMOD REWORKED PIPE ASSEMBLY LEFT P/N 3G7806P06031 AND RIGHT P/N 3G7806P06131 AND THERMAL BLANKET REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE
Standard SBs	BT 139-355	EXHAUST DUCT SUPPORTS RETROMOD P/N 3G7806P08811	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	62
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-387	SMA CONFIGURATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-363	PILOTS FOOTSTEPS KIT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-376	VIDEO DOWNLINK 4.5 GHz RETROMOD P/N 3G9306P04211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-404	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) SLIP RING	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH KIT FIPS
Standard SBs	BT 139-380	AUXILIARY CB PANEL KIT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-391	TAIL ROTOR (TR) SHUT-OFF VALVE (SOV) P/N 3G2910V00231	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED
Standard SBs	BT 139-390 REV A	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT139-430 DATED 11.06.2015
Standard SBs	BT 139-369	EMS FLOOR MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER AIRCRAFT CONFIGURATION
Standard SBs	BT 139-365	ALGERIAN DEPARTMENT OF DEFENCE HELICOPTERS CONFIGURATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-372 REV A	FULL ICE PROTECTION SYSTEM (FIPS) TAIL GEARBOX (TGB) FAIRING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-370	RIGHT ENGINE ASSY FUEL INLET HOSE, INSPECTION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-384	INSTALLATION OF HEATED WINDSHIELDS KIT P/N 3G5610F00611.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-331 REV B	MAIN ROTOR (MR) SERVOACTUATOR, MEASUREMENT OF LAYSHAFT PLAY	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED
Standard SBs	BT 139-381	FULLY ADJUSTABLE PILOT SEAT P/N 3G2510V01631 AND CO-PILOT SEAT P/N 3G2510V01731.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-359	LH REAR PANEL ASSY RETROMOD P/N 3G5306P52711 AND RH REAR PANEL ASSY RETROMOD P/N 3G5306P52811 OR P/N 3G5306P53211.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-323	WEATHER RADAR PRIMUS 701 INSTALLATION P/N 4G3441A00611, IMPROVEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH KIT WEATHER RADAR PRIMUS 660
Standard SBs	BT 139-310 REV A	KIT LOW SPEED LANDING AURAL WARNING P/N 4G2350F01SI2, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A BY AIRCRAFT SERIAL NUMBER & COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-293 REV A	GPS L1-L2 ANTENNA - INSTALLATIONS OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER & COMPLIANCE AT CUSTOMER'S OPTION

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	63
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-190	DATA ACQUISITION UNIT (DAU) MOUNTING WEDGES RIVET INSPECTION AND MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH KIT HUMS HAVING DIFFERENT PART NUMBER
Standard SBs	BT 139-311 REV B	SUBFLOOR FRAME STA2105 RETROMODIFICATION P/N 3G5306P47211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER HELICOPTERS AFFECTED: ALL AW139 HELICOPTERS FROM 31005 (EXCEPT S/N 31007) TO S/N 31517 (EXCEPT S/N 31415, 31431, 31491, 31500, 31508, 31516) AND FROM S/N 41001 TO S/N 41356 (EXCEPT S/N 41355).
Standard SBs	BT 139-339 REV B	FULL ICE PROTECTION SYSTEM (FIPS) AUTO TRANSFORMER RECTIFIER UNIT (ATRU) REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT NOT EQUIPPED WITH KIT FIPS
Standard SBs	BT 139-361	COMPRESSOR PACK ASSY AND AIR CONDITIONING RELIABILITY, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED COMPRESSOR PACK ASSY WITH PART NUMBER 3G2150V10151
Standard SBs	BT 139-371	HOIST PENDANT VARIANT P/N 3G2591A08211 - INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON HELICOPTER
Standard SBs	BT 139-116 REV A	RIGHT AFT FLOAT RETRO-MODIFICATION P/N 3G5306P47011, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-272 REV A	KIT MAX VIZ CAMERA ENHANCED VISION SYSTEM (EVS) 1500 UNDER FUSELAGE P/N 4G9750F00312, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER & COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-368	INSPECTION / REPLACEMENT OF LOWER HALF SCISSOR SPHERICAL BEARING P/N 3G6230V00654.	-	-	-/NOT APPLICABLE	NOT APPLICABLE INSTALLED COMPONENTS PART NUMBER NOT AFFECTED
Standard SBs	BT 139-353	KIT REMOVABLE RIGID HANDLE PASSENGER LH P/N 4GS212FOOS11 AND RH P/N 4G5212F00611, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-315 REV B	"PRIMUS EPIC" FLIGHT SOFTWARE RELEASE 7.4 (PHASE 7 VERSION 1), INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER INSTALLED WITH THE LATEST VERSION OF FLIGHT SOFTWARE
Standard SBs	BT 139-400	"PRIMUS EPIC_ FLIGHT SOFTWARE RELEASE 7.7 (PHASE 7 VERSION 3), INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT INSTALLED WITH THE LATEST VERSION OF FLIGHT SOFTWARE
Standard SBs	BT 139-367	TAIL ROTOR (TR) SERVOACTUATOR, MEASUREMENT OF LAYSHAFT PLAY.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT COMPONENT SERIAL NUMBER
Standard SBs	BT 139-337	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) SLIP RING, IMPROVEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON HELICOPTER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	64
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-286 REV B	PRECAUTIONARY INSPECTION AND QUARANTINE LIMIT OF IMPROVED TAIL ROTOR BLADES P/N 3G6410A00133 AND P/N 4G6410A00133.	-	-	-/CANCELLED	REVISION B CANCELS AND SUPERSEDES THE REV. A. THE AIRWORTHINESS OF THE IMPROVED TAIL ROTOR BLADES IN SUBJECT IS NOW MANAGED THROUGH THE AIRWORTHINESS LIMITATIONS SECTION OF THE AW139 AMPI MANUAL LATEST REVISION.
Standard SBs	BT 139-265 REV B	PRECAUTIONARY INSPECTION AND QUARANTINE OF TAIL ROTOR BLADES P/N 3G6410V00131 AND P/N 4G6410V00131	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH IMPROVED T/R BLADES PART NUMBER 3G6410A00133
Standard SBs	BT 139-285 REV B	PRECAUTIONARY INSPECTION AND QUARANTINE OF IMPROVED TAIL ROTOR BLADES P/N 3G6410A00132 AND P/N 4G6410A00132	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH IMPROVED TAIL ROTOR BLADES 3G6410A00133
Standard SBs	BT 139-340 REV B	FULL ICE PROTECTION SYSTEM (FIPS) AC GENERATOR CONTROL UNIT (GCU)	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT NOT EQUIPPED WITH KIT FIPS
Standard SBs	BT 139-336 REV A	FULL ICE PROTECTION SYSTEM (FIPS) MAIN ROTOR (MR) CABLES REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT NOT EQUIPPED WITH KIT FIPS
Standard SBs	BT 139-338	FULL ICE PROTECTION SYSTEM (FIPS) MAIN ROTOR SLIP RING HALF BUMPER RINGS, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT NOT EQUIPPED WITH KIT FIPS
Standard SBs	BT 139-349	DEPARTMENT OF CIVIL AVIATION (DCA) MALAYSIA VARIANT P/N 3G0206P01611 AND OWNER/OPERATOR PLACARD RETROMOD P/N 3G0206P01811, INSTALLATION OF.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-221 REV B	RETROMOD EXHAUST DUCT BLANKET REPLACEMENT LEFT P/N 3G7806P01531 OR P/N 3G7806P01532 AND RIGHT P/N 3G7806P01631 OR P/N 3G7806P01632.	-	-	-/NOT APPLICABLE	COMPLIANCE AT CUSTOMER'S OPTION, IN CASE OF NON REPAIRABLE DAMAGES REPORTED ON THE THERMAL BLANKETS OF EXHAUST PIPES
Standard SBs	BT 139-354	RESCUE HOIST CLUTCH LOAD CHECK	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-390 DATED 20.11.2014
Standard SBs	BT 139-329 REV A	CARGO HOOK KIT P/N 3G2592F00111, LONGERON BL +/-275 RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-342	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) BLADES ASSY SEALING MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED WITH TAIL ROTOR BLADES PART NUMBER 3G6410A00133
Standard SBs	BT 139-283	LH AIR INTAKE FAIRING RETROMOD P/N 3G5306P47411, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-319	NIGHT VISION GOGGLES (NVG) RE-CONFIGURATION.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-344	INCREASE OF MAIN GEARBOX (MGB) OVERHAUL INTERVAL FROM 5000 FH TO 6000 FH.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	65
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-332	SUN GEAR OIL NOZZLES VARIANT P/N 3G6306P01511, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED
Standard SBs	BT 139-343	ACCESSORY DRIVE ECS COMPRESSOR VISUAL INSPECTION AND MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH MGB ACCESSORY DRIVE IN SUBJECT
Standard SBs	BT 139-186	MISSION CONSOLE RH RACK RETROMODIFICATION P/N 3G5306P40111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-320	FIPS TAIL ROTOR SLIP RING DRIVE INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-291	EMS MEDEVAC PROVISION KIT P/N 4G2564F00213, INSTALLATION OF.	-	-	-/OPTIONAL	COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-333	2ND DISTANCE MEASURING EQUIPMENT (DME) KIT P/N 4G3450F00111, INSTALLATION OF.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-289	NOSE LANDING GEAR, ALTERNATIVE SHIMMY DAMPER FLUID	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT DIFFERENT PART NUMBER
Standard SBs	BT 139-325 REV A	MAIN ROTOR SERVOACTUATOR INSPECTION AND REPAIR	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED
Standard SBs	BT139-325 REV. A DTD 01.07.13	MAIN ROTOR SERVOACTUATOR INSPECTION AND REPAIR	-	-	-/NOT APPLICABLE	OEM SB DECLARATION:- INSTALLED M/R SERVO ACTUATORS HAVING P/N NOT AFFECTED BY THIS BT
Standard SBs	MSB NO. 139-325, REVISION A	MAIN ROTOR SERVOACTUATOR INSPECTION AND REPAIR	-	-	-/NOT APPLICABLE	OEM SB DECLARATION:- INSTALLED M/R SERVO ACTUATORS HAVING P/N NOT AFFECTED BY THIS BT
Standard SBs	BT 139-307	HYDRAULIC SYSTEM FEXIBLE HOSES REPLACEMENT IN THE UPPER DECK AREA.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-301	INSTALLATION OF POSITION LIGHTS OR POSITION/STROBE LIGHTS ON TAIL PLANE WINGLETS, IMPROVEMENT OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-330	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR DISTRIBUTOR (TRD) REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-324 REV A	MR FULL ICE PROTECTION SYSTEM (FIPS) CABLES, INSPECTION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-317	KIT PARTIAL CABIN EXTENSION P/N 4G5340F00211, INSTALLATION OF.	-	-	-/OPTIONAL	N/A DUE TO AIRCRAFT SERIAL NUMBER & COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-327 REV A	SECONDARY FUEL PROBE P/N 3G2840V01051 (AERAZUR P/N 506252 OR P/N 506252A) HEAD SEALING, IMPROVEMENT OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON AIRCRAFT BY MANUFACTURER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	66
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-224	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) MAINTENANCE CONNECTOR, REPOSITIONING OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-326	RESCUE HOIST ASSEMBLY PART REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH GOODRICH RESCUE HOIST KIT
Standard SBs	BT 139-322	UTILITY CB PANEL KIT UPGRADE	-	-	-/OPTIONAL	COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-051 REV A	WEATHER RADAR PRIMUS 701 KIT P/N 4G3441F00111 INSTALLATION.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-207 REV B	KIT FANS FOR REAR AVIONIC BAYS P/N 4G2150F00311, INSTALLATION OF	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-294	HEELS CABIN DOORS/WINDOWS LIGHTS -INSPECTIONS	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-321 REV B	INSPECTION OF THE RESCUE HOIST	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-354 DATED 21.11.13
Standard SBs	BT 139-144	KIT TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) P/N 3G3450F00311, INSTALLATION OF.	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-300	EMERGENCY FLOATATION SYSTEM (EFS) CONNECTIONS MODIFICATION	-	-	-/NOT APPLICABLE	N/A DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-302	PEDAL SET ASSY INSPECTION AND RECONFIGURATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT ENTERED IN SERVICE JANUARY 2021
Standard SBs	BT 139-192	SLIDING PASSENGER DOOR CHECK AND ADJUSTMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT ENTERED IN SERVICE JANUARY 2021
Standard SBs	BT 139-262	REAR UPPER DECK PANEL ASSY P/N 3P5340A01131, P/N 3P5340A01132, P/N 3P5340A01133 OR P/N 3P5340A01135, REPLACEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH TAIL ROTOR DRIVE SHAFT INSTALLATION PART NUMBER 4G6500A00212.
Standard SBs	BT 139-108	ADDITIONAL LOWER MOORING INSTALLATION P/N 3G5330A12011.	-	-	-/OPTIONAL	COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	BT 139-305	TAIL ROTOR BEARING SUPPORT BRACKET INSPECTION.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-296 REVISION A DATED 21.06.16
Standard SBs	BT 139-312	AW139 HEALTH AND USAGE MONITORING SYSTEM (HUMS) - ON BOARD SYSTEM CONFIGURATION (OBS()) FILE VERSION 5.3.0 OR AGB4 UPLOAD ON HUMS DATA ACQUISITION UNIT (DAU) AND AW139 CONFIGURED HUMS GROUND STATION (HGS) SOFTWARE RELEASE V4.1.0 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH FAMILY HUMS KIT
Standard SBs	BT 139-314	FLOOR REMOVABLE PANELS RETROMODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT ATTACHED ON HELICOPTER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	67
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-306	NOSE LANDING GEAR, INSPECTION OF ARMS PIN INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO NOSE LANDING GEAR ASSY AFFECTED NOT INSTALLED ON HELICOPTER
Standard SBs	BT 139-114	ACCESSIBILITY IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-280	CORROSION PROTECTION IMPROVEMENT	-	-	-/OPTIONAL	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-105 REV A	AIRCRAFT WATERPROOFING IMPROVEMENT.	-	-	-/OPTIONAL	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-282	28VDC ACTIVE NOISE REDUCTION (ANR) HEADSET RETROMOD P/N 3G2306P10111, INSTALLATION OF.	-	-	-/OPTIONAL	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-214 REV A	REPLACEMENT OF STANDBY ATTITUDE DIRECTOR INDICATOR P/N 501-1860-0201/-0601 PRE-MOD #17	-	-	-/NOT APPLICABLE	DIFFERENT PART NUMBER INSTALLED REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-033	FLIR SAFIRE III HD WITH CEU P/N 3203134-340, IMPROVEMENT OF	-	-	-/NOT APPLICABLE	KIT NOT INSTALLED. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-250	ECS HD VIDEO UP/DOWNLINK RETRO-MODIFICATION P/N 3G9306P01711.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	68
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-304	2ND ADDITIONAL LANDING LIGHT KIT P/N 4G3340F01812, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-298	MISSION DISPLAY P/N LCD1507-300 AND P/N LCD1507-340 MOD STATE C	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT FITTED ON HELICOPTER
Standard SBs	BT 139-292	NUMBER 2 DRAIN LINE INSTALLATION - MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-290	PASSENGER SEAT KIT P/N 4G2520F05911 OR P/N 4G2520F05811, INSTALLATION OF.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-179	SINGLE HOIST ELECTRICAL PROVISION MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-308	VISUAL INSPECTION OF THE COLLECTIVE AND CYCLIC STICKS INSTALLATIONS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-299	DIGITAL VIDEO-AUDIO RECORDER (DVAR) HD - RECORDING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT CONFIGURATION
Standard SBs	BT 139-170	DOUBLE HOIST ELECTRICAL PROVISION MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-295	ADS-B UAT FREE FLIGHT EQUIPMENT INSTALLATION	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH ADS-B FREE FLIGHT COMPLETE PROVISION IN SUBJECT. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	69
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-256 REV A	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-261	TAIL ROTOR FIPS INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-288 PART I AND II	TAIL ROTOR CONTROL DUPLEX BEARING	-	-	-/FOR INFO ONLY	APPLICABLE ON HELICOPTERS EQUIPPED WITH TR CONTROL DUPLEX BEARING P/N 3G6430V00151, P/N 3G6430V00152 OR P/N 3G6430V00153, THAT HAVE ACCUMULATED 3000 FLIGHT HOURS (OR MORE) SINCE INSTALLATION. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 139-288, NEW ISSUE	TAIL ROTOR DUPLEX	-	-	-/NOT APPLICABLE	PART I & II: NOT COMPLIED WITH PART III: NOT APPLICABLE. APPLICABLE ON SPARE PARTS KEPT IN STOCK. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-064 REV A	HEELS COCKPIT DOORS LIGHTS P/N 3G3350A00411 INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-253	RESCUE HOIST ASSEMBLY P/N 3G2591V01531 AND CONTROL PENDANT ASSEMBLY P/N 3G2591V02151, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH RESCUE HOIST SYSTEM KIT
Standard SBs	BT 139-255	EXHAUST DUCT BAY VENTILATION RETROMOD P/N 3G7806P00811, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-180	UPPER COWLING ASSY RETROMODIFICATION P/N: 3G7106P08431 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	70
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-267	INSTRUMENT PANEL IMPROVED FIXING SUPPORTS, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-277	LONGITUDINAL LITTERS RETROMODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH THE KIT IN SUBJECT
Standard SBs	BT 139-238 REV A	CONTROL ROD ASSY YAW6 AND YAW9 INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. COMPONENT NOT AFFECTED
Standard SBs	BT 139-067	VHF COMM 5 EMS AND UHF/VHF COMM 3/4 EMS, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-203 REV A	BATTERY PANEL REINFORCEMENT RETRO MOD P/N: 3G5306P26511	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT139-092	WINDSHIELD WASHING KIT, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-169	2ND SEARCH LIGHT KIT P/N: 4G3340F01811, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-246	SX 16 SEARCHLIGHT ELEVATION ENVELOPE, EXTENSION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. KIT NOT INSTALLED ON AIRCRAFT.
Standard SBs	BT 139-161 REV A	HIGH INTENSITY LANDING LIGHT VARIANT P/N 3G3306P01411 AND HIGH INTENSITY SECONDARY LANDING LIGHT VARIANT P/N 3G3306P05611,INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-104	INTEGRATED ECS MAINTENANCE AND SERVICE PANEL, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH ENVIRONMENTAL CONTROL SYSTEM PART NUMBER 3G2150F00114

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	71
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-248	TAIL ROTOR BEARING SUPPORT INSPECTION.	-	-	-/SUPERSEDED	SUPERSEDED BY BT139-305
Standard SBs	BT 139-254 REV A	ENGINE STARTER GENERATOR V-BAND CLAMP VISUAL INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-260	QUICK ACCESS RECORDER KIT P/N 4G3130F00411, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-257	BREEZE-EASTERN RESCUE HOIST - BL-7720 BUMPER ASSEMBLY OVER TRAVEL BUMPER REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH BREEZE-EASTERN RESCUE HOIST KIT
Standard SBs	BT 139-263	TAIL ROTOR FIPS SLIP RING DRIVE INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-225 REV A	MISSION BUS (NON ESS 2) VARIANT P/N 3G2406P02511, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-121	STATIC INVERTER P/N: 1152572-1, REPLACEMENT OF	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH WEATHER RADAR PRIMUS 701 REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-281	SX16 SEARCH LIGHT KIT P/N 3G3340F00111 - INSTALLATION	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-235 REV A	INTERMEDIATE GEARBOX (IGB) FITTING ASSEMBLY REWORK	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH TAIL ASSEMBLY PART NUMBER 3G535A00136

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	72
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-273	AW139 HEALTH AND USAGE MONITORING SYSTEM (HUMS) - ON BOARD SYSTEM CONFIGURATION (OBSC) FILE VERSION 5.1.0 OR AGB2 UPLOAD ON HUMS DATA ACQUISITION UNIT (DAU) AND AW139 CONFIGURED HUMS GROUND STATION (HGS) SOFTWARE RELEASE V4.0.0 INSTALLATION OF.A	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-227	NUMBER 2 AC GENERATOR (25 KVA) INLET DUCT ASSY P/N 4G2420A04931, REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-278	SIMOCO SRM9000 MOBILE RADIOS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-252	DATA MANAGEMENT UNIT KIT P/N 4G4620F00211, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-163 REV A	TAIL ROTOR BLADE LIGHTNING STRIP, IMPROVEMENT OF.	-	-	-/SUPERSEDED	SUPERSEDED BY SERVICE BULLETIN 139-556 REVISION - DATED 08.08.2019.
Standard SBs	BT 139-276	VISUAL INSPECTION OF THE CYCLIC CONTROL SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-275	VISUAL INSPECTION OF THE COLLECTIVE CONTROL SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-270	TR SLIP RING MOUNTING PLATE INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	AIRCRAFT NOT EQUIPPED WITH KIT FIPS
Standard SBs	BT 139-264	ACTIVE VIBRATION CONTROL SYSTEM KIT P/N 4G1830F00111 (AVCS 2+2) OR P/N 4G1830F00211 (AVCS 3+1), INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	73
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-245	FUEL TANK ANGLE RETROMODIFICATION P/N 3G5306P33211 AND P/N 3G5306P33212	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-244	MGB ROD BACKUP STRUCTURE CRUCIFORM FITTING RETROMODIFICATION P/N 3G5306P36711, INSTALLATION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-154	SATCOM WIRELESS TELEPHONE, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-233 REV A	HYDRAULIC SYS HOSE INSP AND REPLACE IN THE UPPER DECK AREA.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-269	OPERATIONAL CHECK OF NR.1 AND NR.2 HYDRAULIC SYSTEMS	-	-	-/NOT APPLICABLE	NOT APPLICABLE. FUNCTIONAL SYSTEM TEST ALREADY PERFORMED BY MANUFACTURER
Standard SBs	BT 139-259	MAIN ROTOR FIPS INSTALLATION IMPROVEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-336 REVISION A DATED 16.01.2014
Standard SBs	BT 139-222 REV A	CEILING LINER SPLIT RETRO-MODIFICATION P/N 3G2506P07811 OR P/N 3G2506P07812, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-020 REV C	PART I: LIFE LIMIT OF THE FIN ASSY. PART II: FIN ASSY INSPECTION.	-	-	-/CANCELLED	CANCELLED
Standard SBs	139-043 REV. A PART IV	HEATED WINDSHIELDS KIT P/N 3G5610F00611, INSTALLATION OF	-	-	-/OPTIONAL	PART IV: APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-043 REV A PART I,II AND III	HEATED WINDSHIELDS KIT P/N 3G5610F00611, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	74
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-249	SOLDER SPLICES P/N D-110-41 INSPECTION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-152	FORWARD LONGERON - END CONE PANEL	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED TAIL BOOM ASSY WITH PART NUMBER 3G5350A00136
Standard SBs	BT 139-239	HEATING/FORCED VENTILATION SYSTEMS JET PUMP P/N 3G2140V00851, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH THE KIT IN SUBJECT
Standard SBs	BT 139-139	CONTROL MODULE 1 & 2 FILTER DIFFERENTIAL PRESSURE INDICATOR SWITCHES REPLACEMENT.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-026	STROBE LIGHTS KIT P/N 3G3340F00411 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-251	TAIL ROTOR BLADES ASSY PRECAUTIONARY INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED BY BT139-265
Standard SBs	BT 139-184	MGB INPUT MODULE ASSY P/N 3K6320A00135, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. MGB INPUT MODULE ASSY PART NUMBER 3K6320A00136 INSTALLED WITH SEAL ASSY PART NUMBER 3K6320V00952 ALREADY EMBEDDED.
Standard SBs	BT 139-243	MODIFICATION OF TAIL UNIT ASSEMBLY.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH TAIL ASSEMBLY PART NUMBER 3G5350A00136
Standard SBs	BT 139-151	AW139 HEALTH AND USAGE MONITORING SYSTEM (HUMS), UPLOAD OF THE NEW ON BOARD SYSTEM CONFIGURATION (OBSC) FILE VERSION AGB2 ON HUMS DATA ACQUISITION UNIT (DAU) AND INSTALLATION OF THE AW139 CONFIGURED HUMS GROUND STATION (HGS) V4.0.0.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED MAIN GEARBOX WITH PART NUMBER 3G6320A00134
Standard SBs	BT 139-205 REV A	CHAFING BETWEEN ENGINE FUEL SUPPLY TUBE AND HEATING SYSTEM TUBE ASSY	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	75
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-209	TAIL CABLE ASSY. INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-062	ROTOR BRAKE CABLE ASSEMBLY VARIANT, INSTALLATION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-216	SEARCH AND RESCUE WEATHER RADAR PRIMUS 701 KIT P/N 4G3441F00111, INSTALLATION OF.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-228	POSITION LIGHTS AND POSITION/STROBE LIGHTS ON TAIL PLANE WINGLETS, IMPROVEMENT OF	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-301 DATED 14.06.2013
Standard SBs	BT 139-247	44Ah MAIN BATTERY ADDITIONAL CELL MODIFICATION (CONVERSION FROM 19-CELL INTO 20-CELL).	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH MAIN BATTERY PART NUMBER 1152552-1
Standard SBs	BT 139-065 REV A	KIT NOSE LANDING GEAR DOORS P/N 3G5280F00111 AND P/N 4G5280F00111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE ON ENHANCED PLUS FUSELAGE REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-146	INTEGRATED ENVIRONMENTAL CONTROL SYSTEM (ECS) MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-175 REV B	STARTER-GENERATOR GROUNDING CHECK AND IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-117	TCAS TOP ANTENNA GROUNDING IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-171 REV B	OVERHEAT CB PANEL VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	76
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-208 REV B	DIODE SUPPORT RETROMODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-217	INSTALLATION OF HINGE BAGGAGE DOOR RETROFIT KIT P/N 3G5230F00111.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-229	INTEGRATED SECONDARY FLIGHT DISPLAY SOFTWARE MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-165	FLIGHT CONTROL BALANCE SYSTEM INSTALLATION, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-106	AIR CONDITIONING SYSTEM COCKPIT AND CABIN EVAPORATORS, IMPROVEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH AIR CONDITIONING SYSTEM PART NUMBER 3G2150F00114
Standard SBs	BT 139-211 REV A	MGB BEARING 3G6320V01252	-	-	-/NOT APPLICABLE	MGB SERIAL NUMBER NOT AFFECTED. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-213 REV A	GENERAL VISUAL INSPECTION OF NLG ACTUATOR FITTING AREA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-160	PEDAL ASSY EXCESSIVE FORCE KIT P/N 3G6706P01531	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED WITH PEDAL ASSY PART NUMBER 3E6721A00138

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	77
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-140 REV C	INCREASE OF AIRCRAFT MAXIMUM TAKE-OFF WEIGHT (MTOW) UP TO 6800 KG	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-236	MAIN ROTOR PITCH LINK ASSY P/N 3G6230A01032, UPGRADE OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH MR PITCH LINK ASSY PART NUMBER 3G6230A01032
Standard SBs	BT 139-212	HOIST PENDANT SUPPORT ASSY P/N 3G2591A05431, REPLACEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. DAIRCRAFT NOT EQUIPPED WITH EXTERNAL RESCUE HOIST INSTALLATION
Standard SBs	BT 139-231	SPECTROLAB NIGHTSUN II XP, GIMBAL DUAL LOCKING DEVICE	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH KIT NIGHTSUN XP II SEARCHLIGHT
Standard SBs	BT 139-232	REMARKING OF PALL AEROSPACE P/N ON THE ENGINE AIR PARTICLE SEPARATOR LEFT AND RIGHT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH THE EAPS KIT
Standard SBs	BT 139-150	CARGO HOOK CALIBRATION CONFIRMATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH KIT CARGO HOOK
Standard SBs	BT 139-100	MAIN ROTOR FIPS INSTALLATION, REPLACEMENT OF THE SLIP RING ASSY. BOLTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-230	DIODE SUPPORT RETROMODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-109 REV B	ENGINE EXHAUST PIPE FAIRINGS, MODIFICATION OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-226	NEW SBAS (WAAS) CAPABLE GPS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT EQUIPPED WITH KIT 2ND GPS HAVING PART NUMBER 4G3450F00613
Standard SBs	BT 139-159 REV B	TAIL BOOM RETRO-MODIFICATION PROCEDURE	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED TAIL BOOM ASSY WITH PART NUMBER 3G5350A00136
Standard SBs	BT 139-220	DOOR STEP ASSY RETROMOD P/N 3G2506P07011 / 3G2506P07111	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH DOOR STEP LH AND RH ASSY AFFECTED PART NUMBER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	78
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-107 REV B	STROBE LIGHT UNDER FUSELAGE KIT, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-176	TAIL ROTOR DRIVE MGB ADAPTER VARIANT P/N: 3G6306P01011,INSTALLATION OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-202	INSTALLATION OF BREEZE HOIST 90M CABLE LENGTH	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH KIT EXTERNAL HOIST PART NUMBER 3G2591F00111
Standard SBs	BT 139-057 REV B	INTRODUCTION OF VARIANT P/N 3G0206P00311 / 3G0206P00312 ON TCCA REGISTERED AIRCRAFT	-	-	-/NOT APPLICABLE	HELICOPTER NOT REGISTERED TCCA REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-189	INCREASE OF TAIL ROTOR PITCH ANGLE BY APPLICATION OF THE KIT P/N 4G6722F00111.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-149	EGPWS (Enhanced Ground Proximity Warning System) AURAL WARNING INHIBIT CABLE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-024	DIGITAL MAP KIT P/N 3G9310F00112 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-145	INTERMEDIATE GEARBOX (IGB) FITTING ASSEMBLY	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-041	NVG LIGHTS KIT P/N 4G3360F00111 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	79
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	139-115 REV. D PART I AND PART III	MAST VIBRATION ABSORBER KIT P/N 4G1860F00113, INSTALLATION OF.	-	-	-/COMPLIED WITH	PART I: COMPLIED WITH. PART II: NOT APPLICABLE. PART III: MANDATORY CHECKS AFTER 5 TO 7 FLIGHT HOURS AFTER INSTALLATION
Standard SBs	BT 139-115 REV D PART II	MAST VIBRATION ABSORBER KIT P/N 4G1860F00113, INSTALLATION OF. PART I: INSTALLATION OF MAST VIBRATION ABSORBER KIT P/N: 4G1860F00133. PART II: INSTRUCTION FOR UPGRADING KIT P/N:4G1860F00112 INTO IMPROVED KIT P/N: 4G1860F00113. PART III: MANDATORY CHECK AFTER 5 TO 7 FLIGHT HOURS	-	-	-/NOT APPLICABLE	REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-183	EMERGENCY EXIT DECALS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-210	CABIN DOUBLE LAYER WINDOW	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-206	LANDING GEAR CONTROL PANEL P/N 3G3230V00632, FRONT PANEL UPGRADE	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-103 REV A	QUICK ACCESS RECORDER P/N 4G3130F00311, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-187 REV B	MAIN ROTOR DAMPER EYE END INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT MAIN ROTOR DAMPERS WITH PART NUMBER 3G6220V01353
Standard SBs	BT 139-089	FRAME STA 3900 AND FRAME STA 5700 STRUCTURAL REPAIR RETROMODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT INSTALLED FRAMES 3900 WITH PART NUMBER 3P5335A10455 AND FRAMES 5700 WITH PART NUMBER 3P5338A13355 AND 3P5338A13455.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	80
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-199	REPLACEMENT OF INTERFACE UNIT MOUNTING TRAY	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH TELEPHONICS 1500B+ WEATHER AND SEARCH RADAR
Standard SBs	BT 139-200	TAILBOOM REINFORCEMENT STRUCTURAL RETRO MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED TAIL ASSEMBLY WITH PART NUMBER 3G5350A00136
Standard SBs	BT 139-195 REV B	TAIL ASSY. INSPECTIONS	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT FITTED TAIL ASSEMBLY WITH PART NUMBER 3G5350A00136
Standard SBs	BT 139-112 REV A	ELECTRICAL MODIFICATION ON LONG NOSE HELICOPTERS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-197	REPLACEMENT OF THE EXISTING HOIST SEARCH LIGHTS WITH THE NEW HID STEERABLE LIGHT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-196	REPLACEMENT OF THE EXISTING LEFT AND RIGHT ADDITIONAL LANDING LIGHTS WITH THE NEW HID STEERABLE LIGHTS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE
Standard SBs	BT 139-122	FISCHER LIGHT-WEIGHT PILOT SEATS KIT P/N 4G2510F00211 OR P/N 4G2510F00311, INSTALLATION OF.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	BT 139-174	HINGED WINDOW IN CREW DOORS, INSTALLATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-188	VHF COMM 4 (ERICSSON C54) RETRO MOD P/N: 3G2306P04211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-185	WATER SEPARATOR ASSEMBLY P/N 3G2120A01331, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT FITTED WITH FORCED VENTILATION AND HEATING KIT PART NUMBER 3G2141F00114. AIRCRAFT FITTED HEATING AND FORCE VENTILATION WITH PART NUMBER 3G2141A00112.
Standard SBs	BT 139-162	INSTALLATION OF N°2 ICS ADDITIONAL HEADSETS IN AW139 PASSENGERS CABIN WITH THE APPLICATION OF THE ICS EMS VARIANT CABLE ASSY P/N 3G9B02B03001.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	81
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-181	PACKING POSITION OF CONDUIT / FAIRING CABLE FOR THE LEFT LIFE-RAFTS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-201	PASSENGER CABIN UTILITY SOCKET, UPGRADING OF MAXIMUM CURRENT RATING FROM 5A TO 15A.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-168	VIDEO MANAGEMENT UNIT P/N 4G9310F00611, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-113	FULL CABIN EXTENSION KIT P/N: 4G5340F00111, INSTALLATION OF	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-022 REV C	EMERGENCY FLOATS AND LIFE RAFTS P/N 3G9560F00111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-178	RELOCATION OF HEELS BT7 BATTERY	-	-	-/NOT APPLICABLE	AIRCRAFT NOT EQUIPPED WITH KIT HEELS
Standard SBs	BT 139-191	: INSTALLATION OF SEARCH LIGHT C/A EXTENSION RETROMOD 3G3306P01711.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE
Standard SBs	BT 139-194	TAIL ASSY. INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED BY BT139-195
Standard SBs	BT 139-193	TAIL ASSY. INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED BY BT139-195
Standard SBs	BT 139-177	ELECTRICAL HARDNESS CHAFING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-124	BATTERY CABLE ASSEMBLY INSTALLATION RETROMODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-142	FIRE DETECTION/EXTINGUISHING CONTROL PANEL P/N 3G2600V0	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	82
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-164	RIGID HANDLE INSTALLATION KIT P/N: 4G5212F00311	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-172	ROTOR BRAKER RUBBER STOP ADJUSTMENT AND INSTALLATION PROCEDURE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-166	MODULAR AVIONIC UNITS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-133 REV A	GENERATOR CONTROL UNIT (GCU) P/N 1152550-5.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-128	FLOOR PANEL RETRO MODIFICATION P/N: 3P5306P03011 OR P/N: 3P5306P02911 PART I: HELICOPTER AB/AW139 EQUIPPED WITH VIP FLOOR PANEL P/N: 3P5306P02911 AND 3P5332A00332 PART II: HELICOPTER AB/AW139 NOT EQUIPPED WITH VIP FLOOR PANEL P/N: 3P5332A00232 AND 3P5332A00332	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE
Standard SBs	BT 139-167	LIFE-RAFTS INFLATION SYSTEM VALVE INSPECTION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-125	NI-900 NETWORK INTERFACE MODULE ASSEMBLY (NIM) P/N 7517964-914.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-120	PASSENGER FIXED FOOTSTEP PROTECTION KIT P/N 3G5260A20611, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE. AIRCRAFT NOT EQUIPPED WITH RESCUE HOIST KIT
Standard SBs	BT 139-102	INSTALLATION OF THE KIT RADS-AT WITH FUSELAGE BASIC CABLE ASSY ON THE AW139 HELICOPTERS, WITH THE APPLICATION OF THE RETROFIT KIT P/N 3G3130F00412.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	83
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-118 REV B	PASSENGER DOOR INSTALLATION VISUAL INSPECTION AND REINFORCEMENT INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-098	FLOAT SWITCH P/N: 3G9560V01151	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-136	CIRCUIT BREAKER CB27 REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-074 REV C	AW139/AB139 HEALTH AND USAGE MONITORING SYSTEM (HUMS), UPLOAD OF THE NEW ON BOARD SYSTEM CONFIGURATION (OBSC) FILE VERSION 5.1.0 ON HUMS DATA ACQUISITION UNIT (DAU) AND INSTALLATION OF THE AW139/AB139 CONFIGURED HUMS GROUND STATION (HGS) V3.6.0.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-147	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) KIT P/N 3G3440F00211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-095 REV A	W/D HYDRAULIC SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-119	SECONDARY LANDING LIGHT AND SX16 SEARCH LIGHT SYSTEMS CONTROL, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-110	MLG SPONSON REAR FAIRING SEEP AREA EXTENSION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-079	TAIL POSITION LIGHT ADAPTER, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	84
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-138	27 AH AUXILIARY BATTERY, INSTALLATION OF	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-048	MAIN LANDING GEAR PN 3G3210V00133 (LH) AND P/N 3G3210V00233 (RH), REPLACEMENT WITH THE SUPERSEDING P/N 3G3210V00135 (LH) AND P/N 3G3210V00235 (RH).	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-123	ACTIVE VIBRATION CONTROL SYSTEM KIT P/N 4G1830F00211, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-134	TAIL ASSY. INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-003 REV A	VARIANT 4TH PANEL DISPLAY P/N: 3G4630F00111 INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-127 REV A	RADIO TALON RT-8108 KIT P/N 3G2310F00311, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-097 REV A	TAIL GEARBOX FITTING INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-129 REV A	COCKPIT DOORS WINDOWS REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-126	WIRE STRIKE PROTECTION SYSTEMS (WSPS) TOP CABLE CUTTER ASSY P/N 423-83001-1 REWORK.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-090 REV A	"PRIMUS EPIC@" FLIGHT SOFTWARE RELEASE 4.8.0 INSTALLATION (4 AXIS BASIC FLIGHT DIRECTOR KIT P/N 4G2210F00311).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	85
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-131	PEDAL ASSY P/N 3E6721A00137 CHECK REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-029 REV A	SNOW SKIS AND SLUMP PADS PROTECTION INSTALLATION.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-111 REV A	2nd GPS WIRING DIAGRAM MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT139-093	CHART HOLDER PLT/CPLT KIT, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-099	KIT CENTRAL DISPLAY P/N: 4G4630F00111	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-101	VIP CABIN INTERFACES WIRING DIAGRAM MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-077 REV A	INSTALLATION OF VIP CABIN PASSENGER ELECTRICAL PROVISION P/N 3G2520A00311 (COMPLETE PROVISION FOR 115V AC POWER INSTALLATION).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-094	PILOT DOOR EXTERNAL HANDLE RETRO MODIFICATION P/N 3G5206P05511.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER
Standard SBs	BT 139-096	FLIR (SEAFLIR II)STRUCTURAL AND ELECTRICAL PROVISION INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-050	DIRECTION FINDER KIT P/N 3G3450F00911 INSTALLATION.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-087 REV A	PART I: DIMENSIONAL CHECK OF COCKPIT DOOR AND WINDOWS INSTALLATION. COCKPIT DOOR WINDOWS SEAL REPLACEMENT PART II: SLIDING WINDOW REINFORCEMENT INSTALLATION	-	-	-/SUPERSEDED	SUPERSEDED BY BT139-129

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	86
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-088	MAIN ROTOR BLADE ELECTRICAL BONDING.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-081	Y9/Y10 BELLCRANK ASSY RETRO MODIFICATION P/N 3G6706P00611.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-046	4 AXIS AUTOPILOT KIT P/N 3G2210F00211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	DIFFERENT PART NUMBER INSTALLED. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-019	REPLACEMENT OF THE PILOT AND COPILOT ICS PANEL P/N 7511900-982 OR 7511900-98201 WITH THE NEW PILOT AND COPILOT ICS PANEL P/N 7511900-98202.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-082	ELASTOMERIC BEARINGS P/N 3G6220V00154.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-058 REV A	NI-900 NETWORK INTERFACE MODULE ASSEMBLY (NIM) P/N 7517964-912 MOD AH	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-060	TAIL ROTOR DRIVESHAFT N.2 AND N.3	-	-	-/NOT APPLICABLE	DIFFERENT PART NUMBER INSTALLED. (SEE HELICOPTER LOGBOOK) REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-084	POWER C/A (B1A18) P/N 3G9B11A01804.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-023	ENGINE PARTICLE SEPARATOR KIT P/N 3G7160F00114 INSTALLATION	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-085	FIRE EXTINGUISHER BOTTLE ASSY P/N 3G2620V00131.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-039	INSTALLATION OF SEARCH LIGHT SX16 KIT P/N 3G3340F00111.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	87
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-075	KIT ICS PASSENGER CABIN (12/16 Pax) P/N 4G2350F00411.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-080 REV A	PART I: REPLACEMENT OF TRANSPONDER TOP ANTENNA COAXIAL CABLES. PART II: REPLACEMENT OF TRANSPONDER P/N 7517400-885 PRE-MOD Y.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-086	CIRCUIT BREAKERS ENGINE IGNITER 1&2 (CB107 AND CB108).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-071	DC GENERATOR MAX LOADING PLACARD P/N 3G1130L00551, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-012	P/NI-8486-3 SMART LINEAR ACTUATOR (LATERAL). P/N 2-8486-3 SMART LINEAR ACTUATOR (TAIL ROTOR). P/N 8486-3 SMART LINEAR ACTUATOR (LONGITUDINAL).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-076	KIT BAGGAGE COMPARTMENT ANCHOR SYSTEM P/N 3G2550F00113.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER
Standard SBs	BT 139-078	REAR FUSELAGE LONGERONS RETRO MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-015	REAR FUSELAGE AND TAILBOOM RETROMODIFICATIONS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-054 REV A	PART I:FLIGHT DATA RECORDER POWER SUPPLY MODIFICATION PART II: DC BATTERY AND EXTERNAL POWER STARTER MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-073	RAPPELING KIT P/N 4G2590F00111.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-069 REV B	TAILPIPE ASSY LH P/N 3G7800L00131 AND TAILPIPE ASSY RH P/N 3G7800L00231 INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT PART NUMBER INSTALLED

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	88
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-006	NEW PITCH & ROLL TRIM ACTUATOR P/N 3G2220V00137, YAW TRIM ACTUATOR P/N 3G2220V00136 AND COLLECTIVE TRIM ACTUATOR P/N 3G2220V00234, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-042	2ND TRANSPONDER KIT P/N 3G3450F00512 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-055	FISHER PILOT SEATS KIT P/N 3G2510F00211 INSTALLATION.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-052	KIT ACRYLIC WINDSHIELDS P/N 3G5610F00211	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-032 REV B	RETROFIT FUEL DISTRIBUTION, INSTALLATION NEW MANIFOLD P/N 3G2820V00731.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-021 REV B	EMERGENCY FLOATS AND LIFE RAFTS P/N 3G9560F00111 INSTALLATION OF.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-045	ALTERNATIVE 27Ah AUXILIARY BATTERY INSTALLATION KIT P/N 4G2430F00112.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-059 REV A	PART I: REPLACEMENT OF DEFECTIVE PRESSURE SWITCH P/N 70797-85 OF THE NUMBER 1 HYDRAULIC POWER SYSTEM. PART II: REPLACEMENT OF DEFECTIVE PRESSURE SWITCHES P/N 70797-85 OF THE NUMBER 2 HYDRAULIC POWER SYSTEM.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-014 REV B	"PRIMUS EPIC" FLIGHT SOFTWARE RELEASE 3.3.0 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-013 REV B	WIRING DIAGRAM DC EXTERNAL POWER P/N 3G240W00101.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-007 REV A	ICS TROUBLESHOOTING DRAWING P/N 3G2350W00102.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-031 REV A	KIT EXTERNAL HOIST (FEET FOUR WAY) P/N 3G2591F00111 INSTALLATION OF.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST.
Standard SBs	BT 139-016 REV B	REPLACEMENT OF THE PEDAL ASSY P/N P/N 3E6721A00135 WITH THE NEW ASSY P/N 3E6721A00136.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	89
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-011 REV C	FAIRING ASSY LH P/N 3G5306P02233 OR 3P5330A31131.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-047 REV A	MGB COOLING FAN P/N 3G6320V03853 REPLACEMENT.	-	-	-/NOT APPLICABLE	COMPONENT NOT AFFECTED. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-008 REV A	OVERHEAD CB PANEL ASSY DRAWING P/N 3G2490A00233, REPLACEMENT OF THE AUTO BREAKER TRIM P/N MS3320-5 CON P/N MS3320-7-1/2.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-036 REV A	EXTERNAL AND INTERNAL PUBLIC ADDRESS SYSTEM P/N 3G2350F00211 INSTALLATION.	-	-	-/OPTIONAL	APPLICABLE.COMPLY UPON CUSTOMER REQUEST
Standard SBs	BT 139-049 REV A	WATER ACTIVATED SWITCH P/N 503-23 REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-010 REV A	REPLACEMENT OF THE VNE PLACARD ILLUMINATED P/N 3G1130L00152 WITH NEW VNE PLACARD ILLUMINATED P/N 3G1130L00155.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. REF: ANNEX 2 - BOLLETTINI TECNICI STATUS LIST
Standard SBs	BT 139-005 REV A	OPERATIONAL ENVELOPE EXPANSION PART.I: REPLACEMENT OF THE SLIDING RING ASSY P/N 3G6220A00432 PART.II: REPLACEMENT OF THE MAIN BRAKE ASSY P/N 3G3240V00332	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE AIRCRAFT BY MANUFACTURER
Standard SBs	BT 139-070	"PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 3.6.0 NVG KIT INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO "LONG NOSE" CONFIGURATION
Standard SBs	BT 139-056	RADIO NAT NTX VHF/FM KIT P/N 4G2310F00111 INSTALLATION.	-	-	-/OPTIONAL	APPLICABLE. COMPLY UPON CUSTOMER REQUEST
ENGINE TECHNICAL BULLETIN						
ENGINE #1						
Standard SBs	NO.1 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0255 APPLICABLE DUE TO ENGINE TYPE AFFECTED: CATEGORY 5- P&WC RECOMMENDS TO DO THIS SERVICE BULLETIN WHEN THE ENGINE IS DISASSEMBLED AND ACCESS IS AVAILABLE TO THE NECESSARY SUBASSEMBLY

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	90
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0248 (REV.0) TIC-AW139-21-0270 (REV.1) CATEGORY 8 - NOT APPLICABLE DUE TO ENGINE S/N NOT AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41119, REVISION 5	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0233 CATEGORY 7 - APPLICABLE DUE TO ENGINE S/N AFFECTED. TO BE COMPLIED ONCE SUPERSEDED IGNITION EXCITER PN CH92106-2 (3043937-07) IS FULLY USED TIC-AW139-21-0249 APPLICABLE DUE TO ENGINE BUILD SPEC AND S/N AFFECTED.
Standard SBs	NO. 1 ENGINE - P&WC S.B. No. 41119	TURBOSHAFT ENGINE IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	APPLICABILITY: APPLICABLE DUE TO ENGINE BUILD SPEC AND S/N AFFECTED. COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SB WHEN THE SUPPLY OF THE SUPERSEDED PARTS IS FULLY USED. REFER TIC-AW139-21-0249
Standard SBs	NO. 1. ENGINE ~ SB NO. 41119, REVISION 1	PT6C-67C SERVICE BULLETIN IGNITION EXCITEER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0227 CATEGORY 7 - APPLICABLE DUE TO ENGENE S/N AFFECTED. TO BE COMPLIED ONCE SUPERSEDED IGNITION EXCITER PN CH92106-2 IS FULLY USED.
Standard SBs	NO. 1 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO NO. 1 ENG S/N (PCE-KB2361) NOT AFFECTED
Standard SBs	NO. 1 ENGINE - SB NO. 41118, REVISION 3	PT6C-67C SERVICE BULLETIN TURBOSHAFT ENGINE CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0157 COMPLIANCE: CATEGORY 7 NOT APPLICABLE BY ESN
Standard SBs	NO. 1 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-205 CAT 7, APPLICABILITY: NOT APPLICABLE ENGINE SN NOT AFFECTED.
Standard SBs	P&WC SB NO. 41118 REV. 3 - ENG #1	CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	P&WC SB NO. 41118 REV. 2 - ENG #1	CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	91
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41118 REV. 1 - ENG #1	CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	P&WC SB NO. 41118 REV. 0 - ENG #1	CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	P&WC SB NO. 41116 REV. 1 - ENG #1	FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION	-	-	-/Category 9	TIC-AW139-21-0156 APPLICABLE. CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	P&WC SB NO. 41116 REV. 0 - ENG #1	FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION	-	-	-/Category 9	TIC-AW139-21-0155 APPLICABLE. CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	P&WC SB NO. 41111 REV. 0 - ENG #1	DIAMETRICAL GROWTH DIMENSION, COMPRESSOR TURBINE DISK	-	-	-/Category 9	TIC-AW139-21-0155 APPLICABLE. CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	P&WC SB NO. 41100 REV. 8 - ENG #1	NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICAT	-	-	-/Category 8	TIC-AW139-21-0154 APPLICABLE. CATEGORY 8 - THIS SERVICE BULLETIN IS OPTIONAL AND CAN BE DONE AT THE DISCRETION OF THE OPERATOR. APPLICABLE TO ENGINE BUILD SPEC. BUILD SPEC ENGINE FITTED 963.
Standard SBs	P&WC SB NO. 41098 REV. 1 - ENG #1	GAS GENERATOR CASE P3 HOLES - INSPECTION/CLEANING OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0153 NOT APPLICABLE. ENGINE SN NOT AFFECTED
Standard SBs	P&WC SB NO. 41095 REV. 1 - ENG #1	POWER TURBINE SHAFT - INSPECTION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0152 NOT APPLICABLE. ENGINE SN NOT AFFECTED NOT APPLICABLE DUE TO ENGINE NOT OVERHAUL PRIOR TO OCTOBER 22/2013.
Standard SBs	P&WC SB NO. 41094 REV. 3 - ENG #1	BLEED VALVE - INSPECTION/MODIFICATION OF	-	-	-/Category 9	TIC-AW139-21-0151 COMPLIANCE: CAT 9 - SPARE PARTS INFORMATION ONLY
Standard SBs	P&WC SB NO. 41093 - ENG #1	ROLLER BEARING OPTION (IC) - REPLACEMENT OF	-	-	-/Category 9	APPLICABLE TO ENGINE TYPE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	92
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41089 REV. 3 - ENG #1	CHECK VALVE PLATE - REPLACEMENT OF	-	-	-/SUPERSEDED	APPLICABLE. THIS SB SUPERSEDED BY 41103 REVISION 0.
Standard SBs	P&WC SB NO. 41079 - ENG #1	X-RAY INSPECTION OF THE NO. 2 BEARING OIL-PRESSURE-TUBE	-	-	-/NOT APPLICABLE	TIC-AW139-21-0149 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED ENGINE SERIAL NUMBER
Standard SBs	P&WC SB NO. 41074 REV. 0 - ENG #1	FUEL-COOLED OIL COOLER - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT AFFECTED. COMPONENT SERIAL NUMBER FITTED WA60058.
Standard SBs	P&WC SB NO. 41073 REV. 1 - ENG #1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE REPLACEMENT/	-	-	-/NOT APPLICABLE	TIC-AW139-21-0147 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER
Standard SBs	P&WC SB NO. 41046 REV. 2 - ENG #1	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	-	-	-/FOR INFO ONLY	TIC-AW139-21-0146 COMPLIANCE: CATEGORY 10 - FOR INFORMATION ONLY REASON THE CONTENT OF SB FOR INFORMATION ONLY AS THIS SB HAS BEEN CANCELLED AS NEW EEC INTRODUCED (SB41047).
Standard SBs	P&WC SB NO. 41061 REV. 0 - ENG #1	FUEL FILTER - INSPECTION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0145 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER
Standard SBs	P&WC SB NO. 41055 REV. 0 - ENG #1	ACCESSORY GEARBOX DIAPHRAGM - REPLACEMENT/MODIFICATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0144 COMPLIANCE: CAT 7 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER
Standard SBs	P&WC SB NO. 41041 REV. 1 - ENG #1	TURBOSHAFT ENGINE - ROTOR AIR SEAL AND TURBINE SPACER -	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	P&WC SB NO. 41036 REV. 0 - ENG #1	TRIPLE FUNCTION FUEL-SWITCH - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO ENGINE BUILD SPEC. BUILD SPEC ENGINE FITTED 1019. TIC-AW139-21-0142 COMPLIANCE: NOT APPLICABLE DUE TO THE UNAFFECTED BUILD SPEC (ENGINE LOG BOOK)

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	93
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41030 REV. 1 - ENG #1	CHECK VALVE ASSEMBLY - INSPECTION OF	-	-	-/Category 9	APPLICABLE. TO BE COMPLIED AFTER ENGINE HOURS REACH 300 FH TIC-AW139-21-0141 COMPLIANCE: CATEGORY 9 - APPLICABLE DUE TO THE AFFECTED BUILD SPEC (BS963)
Standard SBs	P&WC SB NO. 41028 REV. 1 - ENG #1	CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED. TIC-AW139-21-0140 COMPLIANCE: CATEGORY 10 - FOR INFORMATION
Standard SBs	P&WC SB NO. 41030 REV. 0 - ENG #1	CHECK VALVE ASSEMBLY - INSPECTION OF	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	P&WC SB NO. 41113 REV. 1 - ENG #1	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSP	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ENGINE S/N PCE-KB2361 MODEL PWC PT6C-67C NOT AFFECTED.
Standard SBs	P&WC SB NO. 41108 REV. 0 - ENG #1	T5 TERMINAL NUTS - INSPECTION OF	-	-	-/NOT APPLICABLE	ONLY APPLICABLE TO ENGINE ENTERED IN SERVICE BEFORE 31.12.2017
Standard SBs	P&WC SB NO. 41101 REV. 3 - ENG #1	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING	-	-	-/NOT APPLICABLE	NOT APPLICABLE. FUEL MANAGEMNET MODULE (FMM) NOT AFFECTED.
Standard SBs	P&WC SB NO. 41088 REV. 1 - ENG#1	TURBOSHAFT ENGINE TORQUE (Q/NPT) SENSORS -	-	-	-/NOT APPLICABLE	NOT APPLICABLE ON NEW ENGINES.
Standard SBs	P&WC SB NO. 41086 REV. 0 - ENG #1	TURBOSHAFT ENGINE FUEL MANIFOLD - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE NEW ENGINE MOUNTING ROD ASSY P/N 3G7120V00132 ALREADY INSTALLED.
Standard SBs	P&WC SB NO. 41081 REV. 4 - ENG #1	ELECTRONIC ENGINE CONTROL - REPROGRAMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	P&WC SB NO. 41064 REV. 2 - ENG #1	FUEL HEATER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	P&WC SB NO. A41060 REV. 5 - ENG #1	RETAINING RING POWER TURBINE BAFFLE - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE AS PER ENGINE POST SB1056
Standard SBs	P&WC SB NO. A41059 REV. 1 - ENG #1	POWER TURBINE BAFFLE - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE AS PER ENGINE SERIAL NUMBER.
Standard SBs	P&WC SB NO. A41053 REV. 0 - ENG #1	FUEL FILTER INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ENGINE S/N PCE-KB2361 MODEL PWC PT6C-67C NOT AFFECTED.
Standard SBs	P&WC SB NO. 41048 REV. 0 - ENG #1	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ENGINE PRE SB41046.
Standard SBs	P&WC SB NO. 41035 REV. 4 - ENG #1	THERMOCOUPLE WIRING HARNESS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	94
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41021 REV. 1 - ENG #1	FUEL SYSTEM - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO MODIFICATION FOLLOWING SB41069 (SEE PWC SB LIST)
Standard SBs	P&WC SB NO. 41018 REV. 1 - ENG #1	BLOWDOWN VALVE HOUSING - INSPECTION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	P&WC SB NO. 41016 REV. 0 - ENG #1	INCREASED COMPRESSOR TURBINE TIP CLEARANCE - INTRODUCTI	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	P&WC SB NO. 41006 REV. 0 - ENG #1	AIR LIMITATION RESTRICTION LIFTED	-	-	-/NOT APPLICABLE	NOT APPLICABLE AS PER ENGINE S/N.
Standard SBs	P&WC SB NO. 41114 REV. 1 - ENG #1	INSULATION BLANKET - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	P&WC SB NO. 41114 REV. 0 - ENG #1	TURBOSHAFT ENGINE INSULATION BLANKET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41112 (NEW ISSUE) ENG#1	TURBO SHAFT ENGINE FUEL MANAGEMENT MODULE (FMM) REPLAC	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER.
Standard SBs	P&WC SB NO. 41110 REV. 1 - ENG #1	TURBOSHAFT ENGINE PERMANENT-MAGNETIC-ALTERNATOR GEARSHAFT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41110 REV. 0 - ENG #1	TURBOSHAFT ENGINE PERMANENT-MAGNETIC-ALTERNATOR GEARSHAFT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41109 REV. 0 - ENG #1	IGNITION EXCITER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41107 REV. 0 - ENG #1	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41105 REV. 0 - ENG #1	OIL NOZZLE ASSEMBLY ACCESSORY DRIVE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41104 REV. 1 - ENG #1	FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER SUPERSEDED BY SB 41103 REVISION 1 DATED 27.10.2020
Standard SBs	P&WC SB NO. 41103 REV. 1 - ENG #1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED. THIS SB SUPERSEDED PREVIOUS REVISION AND SB 41089 DATED 31.03.2016
Standard SBs	P&WC SB NO. 41103 REV. 0 - ENG #1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41102 REV. 0 - ENG #1	INSULATION BLANKET ASSEMBLY POWER SECTION - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41099 REV. 0 - ENG #1	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLIES - R	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	95
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41097 REV. 0 - ENG #1	SUPPORT BRACKET FUEL ACCUMULATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41096 REV. 0 - ENG #1	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41092 REV. 1 - ENG #1	GASKET DATA COLLECTION UNIT (DCU) - INTRODUCTION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41091 REV. 0 - ENG #1	FUEL MANIFOLD - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41090 REV. 0 - ENG #1	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLY - REP	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41087 REV. 0 - ENG #1	ROTOR COMPRESSOR TIE RODS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41085 REV. 0 - ENG #1	FUEL HEATER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41084 REV. 0 - ENG #1	OIL PRESSURE SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41083 REV. 0 - ENG #1	SEALS OIL TANK FILLER CAP AND OIL LEVEL INDICATOR - REP	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41082 REV. 0 - ENG #1	CLPING RING TURBINE-VANE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41077 REV. 0 - ENG #1	ENGINE SHIPPING CONTAINER ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41076 REV. 0 - ENG #1	SPEED SENSOR NG - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41075 REV. 0 - ENG #1	NPT TORQUE SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41069 REV. 0 - ENG #1	FUEL MANAGEMENT MODULE AND CHIP DETECTOR VALVE AND PLUG	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41068 REV. 0 - ENG #1	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41067 REV. 1 - ENG #1	INTERSTAGE AIR-SEAL HOUSING ASSY AND PT VANE RING - REP	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41066 REV. 5 - ENG #1	TURBOSHAFT ENGINE POWER TURBINE SHAFT AND STATOR ASSEMB	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41066 REV. 4 - ENG #1	TURBOSHAFT ENGINE POWER TURBINE SHAFT AND STATOR ASSEMB	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41066 REV. 3 - ENG #1	POWER TURBINE SHAFT AND STATOR ASSEMBLIES - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41065 REV. 3 - ENG #1	TURBOSHAFT ENGINE POWER TURBINE VANE RING - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	96
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41065 REV. 2 - ENG #1	POWER TURBINE VANE RING - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41063 REV. 0 - ENG #1	HOSE NON-METALLIC - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41062 REV. 0 - ENG #1	HOSE NON-METALLIC - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41057 REV. 5 - ENG #1	TURBOSHIFT ENGINE - SHROUD HOUSING, COMPRESSOR TURBINE	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41057 REV. 4 - ENG #1	SHROUD HOUSING COMPRESSOR TURBINE - REPLACEMENT/MODIFIC	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41057 REV. 3 - ENG #1	SHROUD HOUSING COMPRESSOR TURBINE - REPLACEMENT/MODIFIC	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41056 REV. 6 - ENG #1	POWER TURBINE SHAFT HOUSING ASSEMBLY NO.3 BEARING SEAL	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41056 REV. 5 - ENG #1	POWER TURBINE SHAFT HOUSING ASSEMBLY NO.3 BEARING SEAL	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41054 REV. 1 - ENG #1	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41052 REV. 1 - ENG #1	OIL TRAY ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION O	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	P&WC SB NO. 41052 REV. 0 - ENG #1	OIL TRAY ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION O	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41051 REV. 1 - ENG #1	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41050 REV. 1 - ENG #1	FUEL NOZZLE CONFIGURATION AND ECOLOGY SYSTEM ACCUMULATOR	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41049 REV. 2 - ENG #1	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41049 REV. 1 - ENG #1	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41047 REV. 3 - ENG #1	ELECTRONIC ENGINE CONTROL - REPROGRMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41045 REV. 1 - ENG #1	NO. 5 BEARING HOUSING SUPPORT AND PT ROTOR BALANCING AS	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41044 REV. 0 - ENG #1	IGNITION EXCITER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41043 REV. 0 - ENG #1	CHIP DETECTOR VALVE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41042 REV. 0 - ENG #1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	97
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41040 REV. 0 - ENG #1	ROTOR AIR SEAL AND TURBINE SPACER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41039 REV. 0 - ENG #1	IGNITERS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41038 REV. 0 - ENG #1	AIR SEAL COMPRESSOR TURBINE STATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41037 REV. 0 - ENG #1	COMPRESSOR INLET CASE ASSEMBLY AND RETAINING PLATE FOR	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41034 REV. 0 - ENG #1	FUEL SWITCH IMPENDING BYPASS AND TEMPERATURE - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41033 REV. 0 - ENG #1	SCREEN ASSEMBLY AIR INLET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41032 REV. 0 - ENG #1	WIRING HARNESS T1 SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41031 REV. 1 - ENG #1	PREFORMED PACKING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41027 REV. 0 - ENG #1	PT HOUSING SEALING-RING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41026 REV. 0 - ENG #1	FUEL MANAGEMENT MODULE - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41025 REV. 0 - ENG #1	COLD START VALVE HOUSING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41024 REV. 0 - ENG #1	TURBINE EXHAUST DUCT ASSEMBLY SINGLE PORT - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41023 REV. 0 - ENG #1	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41020 REV. 2 - ENG #1	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT O	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41019 REV. 0 - ENG #1	OIL SWITCH (LOP) - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41017 REV. 0 - ENG #1	COMPRESSOR TURBINE BAFFLE RETAINING BOLT - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41015 REV. 0 - ENG #1	OIL TANK DRAIN ADAPTER AND FIREWALL BRACKET - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41014 REV. 0 - ENG #1	FUEL LINES FROM FUEL MANAGEMENT MODULE TO FUEL HEATER -	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41013 REV. 0 - ENG #1	OIL SYSTEM PREFORMED PACKING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41012 REV. 1 - ENG #1	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODI	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	98
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41011 REV. 0 - ENG #1	IMPROVED HEAT TRANSFER REDUCTION CONFIGURATION AT NO. 3	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41010 REV. 0 - ENG #1	POWER TURBINE OUTPUT SHAFT - INSPECTION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41009 REV. 1 - ENG #1	FUEL HEATER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41008 REV. 1 - ENG #1	WIRING HARNESS SUPPORT BRACKET AND FUEL HEATER COVER AT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41008 REV. 0 - ENG #1	WIRING HARNESS SUPPORT BRACKET AND FUEL HEATER COVER AT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41007 REV. 0 - ENG #1	POWER TURBINE SHAFT SPACER - MODIFICATION/REPLACEMENT O	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41005 REV. 0 - ENG #1	OIL FEED ADAPTER ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	P&WC SB NO. 41004 REV. 0 - ENG #1	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER.
Standard SBs	P&WC SB NO. 41003 REV. 0 - ENG #1	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER.
Standard SBs	P&WC SB NO. 41002 REV. 0 - ENG #1	FUEL MANIFOLD - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER
Standard SBs	P&WC SB NO. 41001 REV. 0 - ENG #1	EXHAUST DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER
Standard SBs	SB 41101 REV 2	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING MSS CAVITY WITH RTV	-	-	-/FOR INFO ONLY	FUEL MANAGEMENT MODULE NOT AFFECTED. REFER PW PT6C-67C SERVICE BULLETINS STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 41093, REV. 1	ROLLER BEARING OPTION (IC) - REPLACEMENT OF	-	-	-/Category 9	REFER TO TIC-AW139-22-0208. APPLICABLE TO THE AIRCRAFT ENGINE TYPE. CATEGORY 9 - SPARE PART INFORMATION. TO DISTRIBUTE AS INFORMATION ONLY.

ENGINE #2

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	99
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0255 APPLICABLE DUE TO ENGINE TYPE AFFECTED: CATEGORY 5- P&WC RECOMMENDS TO DO THIS SERVICE BULLETIN WHEN THE ENGINE IS DISASSEMBLED AND ACCESS IS AVAILABLE TO THE NECESSARY SUBASSEMBLY
Standard SBs	NO. 2 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0248 (REV.0) TIC-AW139-21-0270 (REV.1) CATEGORY 8 - NOT APPLICABLE DUE TO ENGINE S/N NOT AFFECTED.
Standard SBs	NO. 2 ENGINE - P&WC S.B. No. 41119	TURBOSHAFT ENGINE IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	APPLICABILITY: APPLICABLE DUE TO ENGINE BUILD SPEC AND S/N AFFECTED. COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SB WHEN THE SUPPLY OF THE SUPERSEDED PARTS IS FULLY USED. REFER TIC-AW139-21-0249
Standard SBs	NO. 2 ENGINE ~ SB NO. 41119, REVISION 5	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0233 CATEGORY 7 - APPLICABLE DUE TO ENGINE S/N AFFECTED. TO BE COMPLIED ONCE SUPERSEDED IGNITION EXCITER PN CH92106-2 (3043937-07) IS FULLY USED TIC-AW139-21-0249 APPLICABLE DUE TO ENGINE BUILD SPEC AND S/N AFFECTED.
Standard SBs	NO. 2. ENGINE ~ SB NO. 41119, REVISION 1	PT6C-67C SERVICE BULLETIN IGNITION EXCITEER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0227 CATEGORY 7 - APPLICABLE DUE TO ENGENE S/N AFFECTED. TO BE COMPLIED ONCE SUPERSEDED IGNITION EXCITER PN CH92106-2 IS FULLY USED.
Standard SBs	NO. 2 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO NO. 2 ENGINE S/N (PCE-KB2359) NOT AFFECTED
Standard SBs	NO. 2 ENGINE - SB NO. 41118, REVISION 3	PT6C-67C SERVICE BULLETIN TURBOSHAFT ENGINE CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0157 COMPLIANCE: CATEGORY 7 NOT APPLICABLE BY ESN

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	100
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	CENTRIFUGAL IMPELLER - REPLACEMENT OF	P&WC SB NO. 41118 REV. 3 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	CAT 7, APPLICABILITY: NOT APPLICABLE ENGINE SN NOT AFFECTED.
Standard SBs	CENTRIFUGAL IMPELLER - REPLACEMENT OF	P&WC SB NO. 41118 REV. 2 - ENG #2	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	CENTRIFUGAL IMPELLER - REPLACEMENT OF	P&WC SB NO. 41118 REV. 1 - ENG #2	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	CENTRIFUGAL IMPELLER - REPLACEMENT OF	P&WC SB NO. 41118 REV. 0 - ENG #2	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION	P&WC SB NO. 41116 REV. 1 - ENG #2	-	-	-/Category 9	TIC-AW139-21-0156 APPLICABLE. CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION	P&WC SB NO. 41116 REV. 0 - ENG #2	-	-	-/FOR INFO ONLY	CATEGORY 9 - SPARE PARTS INFORMATION. APPLICABLE TO ENGINE SERIAL NUMBER.
Standard SBs	DIAMETRICAL GROWTH DIMENSION, COMPRESSOR TURBINE DISK -	P&WC SB NO. 41111 REV. 0 - ENG #2	-	-	-/Category 9	TIC-AW139-21-0155 APPLICABLE. CATEGORY 9 - SPARE PARTS INFORMATION
Standard SBs	NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICAT	P&WC SB NO. 41100 REV. 8 - ENG #2	-	-	-/Category 8	TIC-AW139-21-0154 APPLICABLE. CATEGORY 8 - THIS SERVICE BULLETIN IS OPTIONAL AND CAN BE DONE AT THE DISCRETION OF THE OPERATOR. APPLICABLE TO ENGINE BUILD SPEC. BUILD SPEC ENGINE FITTED 1019.
Standard SBs	GAS GENERATOR CASE P3 HOLES - INSPECTION/CLEANING OF	P&WC SB NO. 41098 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0153 NOT APPLICABLE. ENGINE SN NOT AFFECTED
Standard SBs	POWER TURBINE SHAFT - INSPECTION OF	P&WC SB NO. 41095 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0152 NOT APPLICABLE. ENGINE SN NOT AFFECTED NOT APPLICABLE DUE TO ENGINE NOT OVERHAUL PRIOR TO OCTOBER 22/2013.
Standard SBs	BLEED VALVE - INSPECTION/MODIFICATION OF	P&WC SB NO. 41094 REV. 3 - ENG #2	-	-	-/Category 9	TIC-AW139-21-0151 COMPLIANCE: CAT 9 - SPARE PARTS INFORMATION ONLY

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	101
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ROLLER BEARING OPTION (IC) - REPLACEMENT OF	P&WC SB NO. 41093 - ENG #2	-	-	-/Category 9	TIC-AW139-21-0150 COMPLIANCE: CAT 9 - SPARE PARTS INFORMATION ONLY
Standard SBs	CHECK VALVE PLATE - REPLACEMENT OF	P&WC SB NO. 41089 REV. 3 - ENG #2	-	-	-/SUPERSEDED	APPLICABLE. THIS SB SUPERSEDED BY 41103 REVISION 0.
Standard SBs	X-RAY INSPECTION OF THE NO. 2 BEARING OIL-PRESSURE-TUBE	P&WC SB NO. 41079 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0149 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED ENGINE SERIAL NUMBER
Standard SBs	FUEL-COOLED OIL COOLER - INSPECTION OF	P&WC SB NO. 41074 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0148 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED ENGINE SERIAL NUMBER (REFER ENGINE COMPONENT SUMMARY ENGINE LOG BOOK) COMPONENT SERIAL NUMBER FITTED WA60058.
Standard SBs	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE REPLACEMENT/	P&WC SB NO. 41073 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0147 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER
Standard SBs	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	P&WC SB NO. 41046 REV. 2 - ENG #2	-	-	-/FOR INFO ONLY	TIC-AW139-21-0146 COMPLIANCE: CATEGORY 10 - FOR INFORMATION ONLY REASON THE CONTENT OF SB FOR INFORMATION ONLY AS THIS SB HAS BEEN CANCELLED AS NEW EEC INTRODUCED (SB41047).
Standard SBs	FUEL FILTER - INSPECTION OF	P&WC SB NO. 41061 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0145 COMPLIANCE: CAT 6 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER
Standard SBs	ACCESSORY GEARBOX DIAPHRAGM - REPLACEMENT/MODIFICATION	P&WC SB NO. 41055 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0144 COMPLIANCE: CAT 7 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	102
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	TURBOSHAFT ENGINE - ROTOR AIR SEAL AND TURBINE SPACER -	P&WC SB NO. 41041 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	TIC-AW139-21-0143 COMPLIANCE: CAT 10 - NOT APPLICABLE DUE TO THE UNAFFECTED SERIAL NUMBER
Standard SBs	TRIPLE FUNCTION FUEL-SWITCH - REPLACEMENT OF	P&WC SB NO. 41036 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO ENGINE BUILD SPEC. BUILD SPEC ENGINE FITTED 1019. TIC-AW139-21-0142 COMPLIANCE: NOT APPLICABLE DUE TO THE UNAFFECTED BUILD SPEC (ENGINE LOG BOOK)
Standard SBs	CHECK VALVE ASSEMBLY - INSPECTION OF	P&WC SB NO. 41030 REV. 1 - ENG #2	-	-	-/Category 9	APPLICABLE. TO BE COMPLIED AFTER ENGINE HOURS REACH 300 FH TIC-AW139-21-0141 COMPLIANCE: CATEGORY 9 - APPLICABLE DUE TO THE AFFECTED BUILD SPEC (BS963)
Standard SBs	CENTRIFUGAL IMPELLER - REPLACEMENT OF	P&WC SB NO. 41028 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED. TIC-AW139-21-0140 COMPLIANCE: CATEGORY 10 - NOT APPLICABLE DUE TO ENGINE S/N NOT AFFECT
Standard SBs	CHECK VALVE ASSEMBLY - INSPECTION OF	P&WC SB NO. 41030 REV. 0 - ENG #2	-	-	-/SUPERSEDED	SUPERSEDED BY LATEST REVISION.
Standard SBs	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSP	P&WC SB NO. 41113 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ENGINE S/N PCE-KB2359 MODEL PWC PT6C-67C NOT AFFECTED.
Standard SBs	T5 TERMINAL NUTS - INSPECTION OF	P&WC SB NO. 41108 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	ONLY APPLICABLE TO ENGINE ENTERED IN SERVICE BEFORE 31.12.2017
Standard SBs	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING	P&WC SB NO. 41101 REV. 3 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE. FUEL MANAGEMNET MODULE (FMM) NOT AFFECTED.
Standard SBs	TURBOSHAFT ENGINE TORQUE (Q/NPT) SENSORS -	P&WC SB NO. 41088 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE ON NEW ENGINES.
Standard SBs	TURBOSHAFT ENGINE FUEL MANIFOLD - INSPECTION OF	P&WC SB NO. 41086 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE NEW ENGINE MOUNTING ROD ASSY P/N 3G7120V00132 ALREADY INSTALLED.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	103
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT OF	P&WC SB NO. 41081 REV. 4 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	FUEL HEATER - MODIFICATION/REPLACEMENT OF	P&WC SB NO. 41064 REV. 2 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	RETAINING RING POWER TURBINE BAFFLE - INSPECTION OF	P&WC SB NO. A41060 REV. 5 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE AS PER ENGINE POST SB1056
Standard SBs	POWER TURBINE BAFFLE - INSPECTION OF	P&WC SB NO. A41059 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE AS PER ENGINE SERIAL NUMBER.
Standard SBs	FUEL FILTER INSPECTION OF	P&WC SB NO. A41053 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ENGINE S/N PCE-KB2359 MODEL PWC PT6C-67C NOT AFFECTED.
Standard SBs	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	P&WC SB NO. 41048 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE. ENGINE PRE SB41046
Standard SBs	THERMOCOUPLE WIRING HARNESS - REPLACEMENT OF	P&WC SB NO. 41035 REV. 4 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	FUEL SYSTEM - INSPECTION OF	P&WC SB NO. 41021 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO MODIFICATION FOLLOWING SB41069 (SEE PWC SB LIST)
Standard SBs	BLOWDOWN VALVE HOUSING - INSPECTION/REPLACEMENT OF	P&WC SB NO. 41018 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	INCREASED COMPRESSOR TURBINE TIP CLEARANCE - INTRODUCTI	P&WC SB NO. 41016 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER.
Standard SBs	AIR LIMITATION RESTRICTION LIFTED	P&WC SB NO. 41006 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE AS PER ENGINE S/N.
Standard SBs	INSULATION BLANKET - REPLACEMENT OF	P&WC SB NO. 41114 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	TURBOSHAFT ENGINE INSULATION BLANKET - REPLACEMENT OF	P&WC SB NO. 41114 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	TURBO SHAFT ENGINE FUEL MANAGEMENT MODULE (FMM) REPLAC	P&WC SB NO. 41112 (NEW ISSUE) ENG#2	-	-	-/NOT APPLICABLE	APPLICABILITY: NOT APPLICABLE DUE TO ENGINE S/N NOT AFFECTED. (SB COMPLIED BY OEM, REFER ATTACHMENT) COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED. REFER TIC-AW139-21-0240
Standard SBs	TURBOSHAFT ENGINE PERMANENT-MAGNETIC-ALTERNATOR GEARSHA	P&WC SB NO. 41110 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	104
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	TURBOSHAFT ENGINE PERMANENT-MAGNETIC-ALTERNATOR GEARSHA	P&WC SB NO. 41110 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	IGNITION EXCITER - REPLACEMENT OF	P&WC SB NO. 41109 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	DATA COLLECTION UNIT - REPLACEMENT OF	P&WC SB NO. 41107 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL NOZZLE ASSEMBLY ACCESSORY DRIVE - REPLACEMENT OF	P&WC SB NO. 41105 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	P&WC SB NO. 41104 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER SUPERSEDED BY SB 41103 REVISION 1 DATED 27.10.2020
Standard SBs	CHECK VALVE ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41103 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED. THIS SB SUPERSEDED PREVIOUS REVISION AND SB 41089 DATED 31.03.2016
Standard SBs	CHECK VALVE ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41103 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	INSULATION BLANKET ASSEMBLY POWER SECTION - REPLACEMENT	P&WC SB NO. 41102 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLIES - R	P&WC SB NO. 41099 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SUPPORT BRACKET FUEL ACCUMULATOR - REPLACEMENT OF	P&WC SB NO. 41097 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41096 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	GASKET DATA COLLECTION UNIT (DCU) - INTRODUCTION OF	P&WC SB NO. 41092 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL MANIFOLD - REPLACEMENT OF	P&WC SB NO. 41091 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLY - REP	P&WC SB NO. 41090 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ROTOR COMPRESSOR TIE RODS - REPLACEMENT OF	P&WC SB NO. 41087 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	105
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	FUEL HEATER - REPLACEMENT OF	P&WC SB NO. 41085 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL PRESSURE SENSOR - REPLACEMENT OF	P&WC SB NO. 41084 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SEALS OIL TANK FILLER CAP AND OIL LEVEL INDICATOR - REP	P&WC SB NO. 41083 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	CLPING RING TURBINE-VANE - REPLACEMENT OF	P&WC SB NO. 41082 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ENGINE SHIPPING CONTAINER ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41077 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SPEED SENSOR NG - REPLACEMENT OF	P&WC SB NO. 41076 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	NPT TORQUE SENSOR - REPLACEMENT OF	P&WC SB NO. 41075 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL MANAGEMENT MODULE AND CHIP DETECTOR VALVE AND PLUG	P&WC SB NO. 41069 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	DATA COLLECTION UNIT - REPLACEMENT OF	P&WC SB NO. 41068 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	INTERSTAGE AIR-SEAL HOUSING ASSY AND PT VANE RING - REP	P&WC SB NO. 41067 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	TURBOSHAFT ENGINE POWER TURBINE SHAFT AND STATOR ASSEMB	P&WC SB NO. 41066 REV. 5 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	TURBOSHAFT ENGINE POWER TURBINE SHAFT AND STATOR ASSEMB	P&WC SB NO. 41066 REV. 4 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	POWER TURBINE SHAFT AND STATOR ASSEMBLIES - REPLACEMENT	P&WC SB NO. 41066 REV. 3 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	TURBOSHAFT ENGINE POWER TURBINE VANE RING - REPLACEMENT	P&WC SB NO. 41065 REV. 3 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	POWER TURBINE VANE RING - REPLACEMENT/MODIFICATION OF	P&WC SB NO. 41065 REV. 2 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	HOSE NON-METALLIC - REPLACEMENT OF	P&WC SB NO. 41063 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	HOSE NON-METALLIC - REPLACEMENT OF	P&WC SB NO. 41062 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	TURBOSHAFT ENGINE - SHROUD HOUSING, COMPRESSOR TURBINE	P&WC SB NO. 41057 REV. 5 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	106
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SHROUD HOUSING COMPRESSOR TURBINE - REPLACEMENT/MODIFIC	P&WC SB NO. 41057 REV. 4 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SHROUD HOUSING COMPRESSOR TURBINE - REPLACEMENT/MODIFIC	P&WC SB NO. 41057 REV. 3 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	POWER TURBINE SHAFT HOUSING ASSEMBLY NO.3 BEARING SEAL	P&WC SB NO. 41056 REV. 6 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	POWER TURBINE SHAFT HOUSING ASSEMBLY NO.3 BEARING SEAL	P&WC SB NO. 41056 REV. 5 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41054 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL TRAY ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION O	P&WC SB NO. 41052 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER NOT AFFECTED.
Standard SBs	OIL TRAY ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION O	P&WC SB NO. 41052 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	P&WC SB NO. 41051 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL NOZZLE CONFIGURATION AND ECOLOGY SYSTEM ACCUMULATO	P&WC SB NO. 41050 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41049 REV. 2 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41049 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ELECTRONIC ENGINE CONTROL - REPROGRMING/REPLACEMENT OF	P&WC SB NO. 41047 REV. 3 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	NO. 5 BEARING HOUSING SUPPORT AND PT ROTOR BALANCING AS	P&WC SB NO. 41045 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	IGNITION EXCITER - REPLACEMENT OF	P&WC SB NO. 41044 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	CHIP DETECTOR VALVE - REPLACEMENT OF	P&WC SB NO. 41043 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	CHECK VALVE ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41042 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ROTOR AIR SEAL AND TURBINE SPACER - REPLACEMENT OF	P&WC SB NO. 41040 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	IGNITERS - REPLACEMENT OF	P&WC SB NO. 41039 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	AIR SEAL COMPRESSOR TURBINE STATOR - REPLACEMENT OF	P&WC SB NO. 41038 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	107
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	COMPRESSOR INLET CASE ASSEMBLY AND RETAINING PLATE FOR	P&WC SB NO. 41037 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL SWITCH IMPENDING BYPASS AND TEMPERATURE - REPLACEM	P&WC SB NO. 41034 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	SCREEN ASSEMBLY AIR INLET - REPLACEMENT OF	P&WC SB NO. 41033 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	WIRING HARNESS T1 SENSOR - REPLACEMENT OF	P&WC SB NO. 41032 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	PREFORMED PACKING - REPLACEMENT OF	P&WC SB NO. 41031 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	PT HOUSING SEALING-RING - REPLACEMENT OF	P&WC SB NO. 41027 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL MANAGEMENT MODULE - REPLACEMENT	P&WC SB NO. 41026 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	COLD START VALVE HOUSING - REPLACEMENT OF	P&WC SB NO. 41025 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	TURBINE EXHAUST DUCT ASSEMBLY SINGLE PORT - REPLACEMENT	P&WC SB NO. 41024 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	DATA COLLECTION UNIT - REPLACEMENT OF	P&WC SB NO. 41023 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT O	P&WC SB NO. 41020 REV. 2 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL SWITCH (LOP) - REPLACEMENT OF	P&WC SB NO. 41019 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	COMPRESSOR TURBINE BAFFLE RETAINING BOLT - REPLACEMENT	P&WC SB NO. 41017 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL TANK DRAIN ADAPTER AND FIREWALL BRACKET - REPLACEME	P&WC SB NO. 41015 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL LINES FROM FUEL MANAGEMENT MODULE TO FUEL HEATER -	P&WC SB NO. 41014 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL SYSTEM PREFORMED PACKING - REPLACEMENT OF	P&WC SB NO. 41013 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODI	P&WC SB NO. 41012 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	IMPROVED HEAT TRANSFER REDUCTION CONFIGURATION AT NO. 3	P&WC SB NO. 41011 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	108
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	POWER TURBINE OUTPUT SHAFT - INSPECTION/REPLACEMENT OF	P&WC SB NO. 41010 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	FUEL HEATER - MODIFICATION/REPLACEMENT OF	P&WC SB NO. 41009 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	WIRING HARNESS SUPPORT BRACKET AND FUEL HEATER COVER AT	P&WC SB NO. 41008 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	WIRING HARNESS SUPPORT BRACKET AND FUEL HEATER COVER AT	P&WC SB NO. 41008 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	POWER TURBINE SHAFT SPACER - MODIFICATION/REPLACEMENT O	P&WC SB NO. 41007 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	OIL FEED ADAPTER ASSEMBLY - REPLACEMENT OF	P&WC SB NO. 41005 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURE.
Standard SBs	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	P&WC SB NO. 41004 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER
Standard SBs	DATA COLLECTION UNIT - REPLACEMENT OF	P&WC SB NO. 41003 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER
Standard SBs	FUEL MANIFOLD - REPLACEMENT OF	P&WC SB NO. 41002 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER
Standard SBs	EXHAUST DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF	P&WC SB NO. 41001 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER
COMPONENT SB						
Standard SBs	BT 139-64-002 REV B	PART I: INSPECTION OF SLIDER ASSY P/N 3G6430A00131 AND OF THE SPIDER & SLIDER ASSY P/N 3G6430A01931. PART II: SOSTITUZIONE DELLO SLIDER BUSHING P/N 3G6430V00251,	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	BT 139-46-001	PART I: "PRIMUS EPIC" FLIGHT SW RELEASE 2.4.0. INSTALLATION. PART II: ANTENNA GPS P/N 567-1575-132 INSTALLATION OF. PART III: PILOT AND COPILOT MASTER CAUTION/ WARNING P/N 3G3150V00353 / -453 AND DIMMING SYSTEM CONTROL PANEL P/N 3G3320V00353. PART IV: MAIN ROTOR BLADES COLLECTIVE MINIMUM PITCH SETTING.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. REFER ANNEX 2 BOLLETTINI TECNICI STATUS LIST DATED 18.02.2021
Standard SBs	SB NO. 41114 REV. 0	TURBOSHAFT ENGINE INSULATION BLANKET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED DURING MANUFACTURER.

Aircraft Registration:	9M-JPM	Serial No:	31899	Date:	28/08/2023	Page No:	109
Aircraft Hours:	254:02	Landings:	413.00	Engine 1:	254:02	Engine 2:	254:02

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 3HRL4-HOIST-ATF-01 REV 2	EQUIPMENT/FURNISHINGS - RESCUE HOIST LUBRICATION UPDATE - PRODUCT IMPROVEMENT	-	-	-/FOR INFO ONLY	FOR INFO ONLY
Standard SBs	3HRL4-HOIST-ATF-01R2	EQUIPMENT/FURNISHINGS - RESCUE HOIST LUBRICATION UPDATE - PRODUCT IMPROVEMENT	-	-	-/FOR INFO ONLY	FOR INFO ONLY
Standard SBs	SB NO. 41100 REVISION 7	NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	OPTIONAL. UPON REVIEWED WITH OPERATOR REFER TIC-AW139-21-0154
Standard SBs	SB 206C	REPLACEMENT OF BETA ROD ASSY.	-	-	-/OPTIONAL	
Standard SBs	SB 42325-213-01 REV. 2	EQUIPMENT/FURNISHINGS - CABLE KICKER REPLACEMENT - PRODUCT IMPROVEMENT	-	-	-/CANCELLED	
Standard SBs	SB 49900-889-101-01 REV 1	EQUIPMENT/FURNISHINGS - GROUND SUPPORT EQUIPMENT - REMOVAL FROM SERVICE	-	-	-/FOR INFO ONLY	
Standard SBs	SB 212	C-5291 COUNTERWEIGHT INSPECTION AND REPAIR	-	-	-/FOR INFO ONLY	FOR INFO ONLY
Standard SBs	41101 REV 1	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING MSS CAVITY WITH RTV	-	-	-/NOT APPLICABLE	FUEL MANAGEMENT MODULE NOT AFFECTED. REFER PW PT6C-67C SERVICE BULLETINS STATUS LIST DATED 18.02.2021