



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2022-66R1	2024-08-02	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fire Protection - Inspection and Replacement of Defective Cargo Fire Extinguisher Containers
CF-2024-28	2024-08-02	AIRBUS CANADA LP	BD-500 (A220 Series)	Wings - Left Hand Main Landing Gear Fuse Pin Missing
2024-0154	2024-08-02	DEUTSCHE AIRCRAFT GmbH	Dornier 328	Fuel - Fuel Tank / Bonding Straps - Inspection
2024-0152	2024-08-01	TECNAM, Costruzioni Aeronautiche	P2008 JC	Ignition - Advanced Start System - Deactivation
2024-0151	2024-07-31	AIRBUS S.A.S.	A321	Aircraft Flight Manual / Complementary Performance Data File - Amendment
2024-0148	2024-07-30	SAFRAN HELICOPTER ENGINES	ARRIUS 1	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0147	2024-07-30	AIRBUS S.A.S.	A318, A319, A320, A321	Fuselage - Centre Fuselage Forward Pressure Bulkhead - Inspection
2024-0150	2024-07-30	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0149	2024-07-30	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2019-0069R2	2024-07-29	AIRBUS S.A.S.	A318, A319, A320, A321	Equipment / Furnishings - Overhead Stowage Compartments - Modification
BR-2020-04-01R2	2024-07-29	EMBRAER	EMB-545/-550 (Legacy 500)	[Correction] Windows - Cockpit Side Windows - Inspection / Replacement
2024-0118R1	2024-07-29	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - High Pressure Turbine Blades - Inspection / Limitation
2024-0146	2024-07-29	AIRBUS HELICOPTERS	EC175	Fuel - Fuel Tanks - Mounting Plates of Fuel Tank Bleed Valves - Inspection / Repair / Replacement / Modification
BR-2024-07-01	2024-07-29	EMBRAER S.A.	ERJ 190	Kidde Aerospace & Defense - Overheat Detection System Sensing Elements - Inspection
US-2024-12-10	2024-07-29	CENTERPOINTE AEROSPACE, INC	S-58	Main Rotor Drive - Angle Gearbox Mount - Repetitive Inspections
CF-2024-27	2024-07-29	BOMBARDIER	BD-700	Flight Controls - Incorrect Airplane Flight Manual Approach Speed Adder and Landing Distance Factors for SLAT-FLAP FAIL Caution Crew Alerting System Message and Jammed or Inoperative Slat/Flap Control Lever



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0145	2024-07-23	AIRBUS S.A.S.	A300, A300-600, A300-600ST (Beluga)	Wings - Main Landing Gear Support Rib 5 - Inspection
CF-2024-26	2024-07-22	AIRBUS CANADA LP	BD-500 (A220 Series)	Wing - Slat Track Corrosion and Wear
US-2024-14-03	2024-07-22	COMMANDER (CPAC, INC.), DAHER AEROSPACE, GARMIN INTERNATIONAL INC., MOONEY INTERNATIONAL CORPORATION, PIPER AIRCRAFT INC., TEXTRON AVIATION INC.	112, 114, TB, EASA STC 10069439, FAA STC SA01866WI, M20, PA-24 (Comanche), PA-28 (Archer), PA-28 (Cadet), PA-28 (Cherokee), PA-28 (Dakota), PA-28 (Warrior), PA-28R (Arrow), PA-30 (Twin Comanche), PA-32 (Cherokee Six), PA-32 (Piper 6X), PA-32 (Saratoga), PA-32R (Lance), PA-39 (Twin Comanche), 172 (Skyhawk), 172RG, 177 (Cardinal), 177RG (Cardinal RG), 182 (Skylane), 19, 206/U206 (Super Skywagon), 206H (Stationair), 210 (Centurion), 23 (Musketeer), 24 (Sierra), 35 (Bonanza), 36 (Bonanza), F172, F177RG, F182, FR172 (Reims Rocket), P172D, P206/TP206 (Super Skylane), R172 (Hawk XP)	Auto Flight - Garmin GFC 500 Autopilot System - Software Update