



| Publ. number  | Issue Date | TC Holder                      | Type                     | Subject   |
|---------------|------------|--------------------------------|--------------------------|---|
| US-2023-19-09 | 2023-10-13 | BOEING                         | 787                      | Auto Flight - Airplane Flight Manual Revision - Flight Control Module Software Update   |
| US-2023-19-02 | 2023-10-13 | PRATT & WHITNEY                | PW4070, PW4080, PW4090   | Low Pressure Compressor Fan Hub - Inspection / Replacement  |
| US-2023-20-08 | 2023-10-13 | GENERAL ELECTRIC               | CF6-80C                  | Magnetic Chip Detector Probe Tip - Inspection   |
| US-2023-18-04 | 2023-10-13 | GENERAL ELECTRIC               | CF6-80E1                 | Forward Outer Seals, High Pressure Turbine Rotor Stage 1 Discs and Rotating Seals - Replacement   |
| CF-2023-65    | 2023-10-13 | BOMBARDIER                     | BD-700                   | Time Limits / Maintenance Checks (TLMC) - TLMC Manual Revision to Introduce New or Revised Tasks Affecting the Main Landing Gear (MLG), Nose Landing Gear (NLG) and Pitch Trim Actuator |
| 2023-0181     | 2023-10-13 | ATR                            | ATR42, ATR72             | Electrical Power - Direct Current Emergency Electrical Network Contactor 1PA - Operational Test   |
| 2023-0179     | 2023-10-11 | AIRBUS S.A.S.                  | A320, A321               | Fuselage - Cargo Door Frame Attachment Drillings - Inspection   |
| CF-2023-68    | 2023-10-10 | AIRBUS CANADA LP               | BD-500 (A220 Series)     | Stabilizer - Horizontal Stabilizer - Jamming of the Horizontal Stabilizer Trim Actuator   |
| CF-2023-48R1  | 2023-10-10 | BOMBARDIER                     | BD-100                   | Indicating / Recording System - Misleading Pitch Trim Indication and Alerting for Take-off  |
| CF-2023-66    | 2023-10-10 | AIRBUS CANADA LP               | BD-500 (A220 Series)     | Landing Gear - Main Landing Gear Lower Spindle Pin Corrosion - Inspections  |
| CF-2023-67    | 2023-10-10 | AIRBUS CANADA LP               | BD-500 (A220 Series)     | Electrical Cabin Systems - Lug - Improper Terminal Lug Selection  |
| 2023-0177-E   | 2023-10-09 | EVEKTOR, SPOL. S R.O.          | SportStar RTC            | Engine - Propeller Gearbox Magnetic Plug - Inspection / Propeller Shaft - Replacement   |
| 2023-0176     | 2023-10-06 | AIRBUS S.A.S.                  | A350                     | Fuselage - Cargo Compartment Panels Sealing Tape - Inspection   |
| 2023-0175     | 2023-10-05 | AIRBUS HELICOPTERS DEUTSCHLAND | MBB-BK 117               | ATA - Rotorcraft Flight Manual - Altitude Correction - Amendment ATA 21 - Air Conditioning - Cooling System - Modification  |
| 2023-0174-E   | 2023-10-02 | AIRBUS HELICOPTERS             | SA 330 / AS 332 / EC 225 | Main Rotor - Swashplate Retaining Bushes / Ball Joint Seating - Inspection  |