

Release Notification Date: 12/27/2022

SPM 70-00-99 S0011 - CONSUMABLE MATERIALS - STRIPPING SOLUTION FOR EPOXY RESIN

DISCLAIMER

The Incremental Changes published by GE Aviation are considered Instructions for Continued Airworthiness. These Incremental Changes, along with the current Manual revision and published Temporary Revisions, constitute the latest Instructions for Continued Airworthiness.

GE Designated: -CONFIDENTIAL-

The information contained in this document is GE proprietary information and is disclosed in confidence. It is the property of GE and shall not be used, disclosed to others or reproduced without the express written consent of GE, including, but without limitation, it is not to be used in the creation, manufacture, development, or derivation of any repairs, modifications, spare parts, designs, or configuration changes or to obtain FAA or any other government or regulatory approval to do so. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document shall appear in any such reproduction in whole or part.

This technical data is considered subject to the Export Administration Regulations (EAR) pursuant to 15 CFR Parts 730-774. Transfer of this data by any means to a Non-U.S. Person, whether in the United States or abroad, without the proper U.S. Government authorization (e.g., License, exemption, NLR, etc.), is strictly prohibited.

Copyright (2022) General Electric Company, U.S.A.

HIGHLIGHTS

HIGHLIGHT REFERENCE DESCRIPTION OF CHANGE

tk70-00-99-800-011 Technical Change: Added NOTE for Turco 5351.

TASK 70-00-99-800-011

1. Composition.

Consumable Product	No.	Concentration (Initial Mix)
Cee-Bee A-202	C04-022	Full strength Ambient Temperature
or		
Turco 5351 Thick *	C04-034	Full strength Ambient Temperature

NOTE: * Turco 5351 Thick C04-034 contains hexavalent chromium.

2. <u>Preparation.</u>

Subtask 70-00-99-809-423

WARNING: ACID STRIPPER SOLUTIONS ARE VERY ACTIVE AND CAUSE SERIOUS BURNS. SOLUTION IS TOXIC. AVOID CONTACT WITH SKIN, EYES, AND CLOTHING. AVOID BREATHING OF VAPORS. USE VAPOR/FUME CONTROL OR A RESPIRATOR. IF CONTACT OCCURS, WASH IMMEDIATELY WITH ABUNDANT QUANTITY OF WATER.

WARNING: OPERATOR SHOULD WEAR FACE SHIELD, GLOVES, PROTECTIVE CLOTHING, AND PROTECTIVE SHOES.

- A. No preparation is required.
- 3. Check.

Subtask 70-00-99-809-424

- A. Not applicable.
- 4. <u>Regeneration</u>.

Subtask 70-00-99-809-425

A. Not applicable.

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media