



INCREMENTAL CHANGE

Release Notification Date: 08/03/2023

SPM 70-47-04 ROTARY FLAP PEENING

DISCLAIMER

The Incremental Changes published by GE Aviation are considered Instructions for Continued Airworthiness. These Incremental Changes, along with the current Manual revision and published Temporary Revisions, constitute the latest Instructions for Continued Airworthiness.

GE Designated: -CONFIDENTIAL-

The information contained in this document is GE proprietary information and is disclosed in confidence. It is the property of GE and shall not be used, disclosed to others or reproduced without the express written consent of GE, including, but without limitation, it is not to be used in the creation, manufacture, development, or derivation of any repairs, modifications, spare parts, designs, or configuration changes or to obtain FAA or any other government or regulatory approval to do so. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document shall appear in any such reproduction in whole or part.

This technical data is considered subject to the Export Administration Regulations (EAR) pursuant to 15 CFR Parts 730-774. Transfer of this data by any means to a Non-U.S. Person, whether in the United States or abroad, without the proper U.S. Government authorization (e.g., License, exemption, NLR, etc.), is strictly prohibited.

Copyright (2023) General Electric Company, U.S.A.

HIGHLIGHTS

<u>HIGHLIGHT REFERENCE</u>	<u>DESCRIPTION OF CHANGE</u>
----------------------------	------------------------------

tk70-47-04-380-019	Technical Change: Changed General information section of the Rotary Flap Peening procedure.
--------------------	---

TASK 70-47-04-380-019

1. General.

CAUTION: THIS IS A MANUAL PROCESS. USE THIS PROCESS ONLY WHEN SPECIFICALLY APPROVED BY THE PROCESS DOCUMENT AND ONLY IN AUTHORIZED LOCATIONS ON THE PART.

A. Many engine components are shot peened at time of manufacture as a method to achieve improved cyclic life. Repair of these parts often requires local blending to remove surface imperfections. Blending may partially or completely remove the compressive surface layer induced by shot peening. An acceptable method of restoring the compressive layer in noncritical areas, as an alternate to standard shop peening procedure per TASK 70-47-01-380-016, Shot Peening, is rotary flap peening. This procedure is to be used only when specifically directed by the Engine/Shop Manual.

B. Unless specified differently, TASK 70-47-06-380-801, Needle Peening, can be used as alternative to TASK 70-47-04-380-019, Rotary Flap Peening.

2. Equipment.

Subtask 70-47-04-380-191

A. The following equipment is required and may be obtained as shown:

- (1) No. 2 Almen Gage. (SAE J442 compliant with type 2 Almen Gage)
- (2) Timing Device (Commercial).
- (3) Magnetic Almen Strip Holder, 3M No. 9016, or equivalent. 3M Company. Refer to the List of Suppliers in Step 4 of 70-80-00.
- (4) Hand operated grinder or flexible shaft driven by an electric or compressed air motor with adjustable shaft speed control (Commercial). Equivalent alternative tools and equipment may be used.

NOTE: Once the operational speed is established the rotary tool must be capable of maintaining a constant speed within plus or minus 100 revolutions for each minute (RPM) on the two test strips and work piece. Never dwell on a work piece or component to verify RPM.

Tool	Supplier
(a) Flexible Shaft Grinder Series 6-1/4HP (Low Speed) Model 6-411	DUMORE Corp. Refer to the List of Suppliers in Step 4 of 70-80-00.
(b) Table-Top Speed Control Model 1-310	DUMORE Corp. Refer to the List of Suppliers in Step 4 of 70-80-00.
(5) Mandrel, Rotopeen, 3M No. 7212, or equivalent. 3M Company. Refer to the List of Suppliers in Step 4 of 70-80-00.	
(6) A hand-held tachometer used to determine shaft rpm. Tachometer is not necessary if the system has calibrated closed-loop speed control.	

Tool	Supplier
Tachometer	Shimpo. Refer to the List of Suppliers in Step 4 of 70-80-00.

3. Materials.

Subtask 70-47-04-380-192

Consumable Product	No.
A. Almen Test Strips, Type A, 0.050-0.052 inch (1.27-1.32 mm) thick.	C10-110
B. Almen Test Strips, Type N, 0.030-0.032 inch (0.76-0.81 mm) thick.	C10-205
C. Rotary Peen Flap Assembly, 1 1/4 x 9/16 inch (32 x 14 mm), 3M No. TC330	C10-111
D. Rotary Peen Flap Assembly, 1 x 9/16 inch (25 x 14 mm), 3M No. TC330	C10-111
E. Rotary Peen Flap Assembly, 1 x 2 inch (25 x 50 mm), 3M No. TC330	C10-111

4. Procedure.

Subtask 70-47-04-380-193

A. Preparation of Part and Flap for Rotary Flap Shot Peening.

- (1) Part to be peened must be repaired and blended to remove burrs and sharp corners from area to be peened.
- (2) Magnetic-particle inspection or fluorescent-penetrant inspection (preceded by appropriate etching) when required must be completed before shot peening.
- (3) Areas not to be peened, adjacent to areas being peened, shall be masked to avoid contact with rotary flap.
- (4) Area of part to be peened must be clean and free of all dirt, grease or oil.
- (5) New flaps must be examined to confirm that no resin coating exists over the shot prior to use. If a coating exists, the flap must be conditioned by operation against an abrasive paper or a hard surface to remove the coating. The resin coating, if not removed, will cushion the impacts against the test strip and will effect delivered intensity until resin has worn off.

Subtask 70-47-04-380-195

B. Determination of Peening Requirements.

- (1) Convert the required arc height in the Engine/Shop Manual. Use the conversion graphs/tables that follow:
 - (a) For type A Almen test strips use Figure 7 or Figure 8.
 - (b) For type N Almen test strips use Figure 9 or Figure 10.

NOTE: Conversion of strip arc heights is necessary since the Almen strip bends more when using the magnetic Almen strip holder than with the SAE J442 strip holder.

NOTE: Peening intensity is measured as curvature (arc height) of the standard test specimen in thousandths of an inch. For example, intensity10 A2 indicates an arc height of 0.010 inch (0.3 mm) on an Almen A test strip, measured on a No. 2 gage.

NOTE: Make sure that the intensity by peening one Almen test strip for the intensity time "T" of the saturation curve accepted at the intensity determination, with the same parameters, operator and equipment. Intensity verification is acceptable if the converted Almen test strip arc height is within plus or minus 0.0015 inch (plus or minus 0.038 mm) of the original intensity arc height and within the necessary intensity range.
- (2) Position an Almen test strip in the Almen gage and set the indicator to zero. Reverse the strip so that opposite surface is up and check for out-of-flatness. If out-of-flatness exceeds 0.001 inch (0.03 mm), select a new strip and repeat the check.
- (3) Position strip in magnetic Almen strip holder. See Subtask 70-47-04-380-191, Equipment.
- (4) Install and center flap assembly in mandrel with mandrel firmly attached in chuck of flexible shaft or hand operated grinder. Select an initial tool speed. Refer to Figure 6. Set tool speed under load and peen test strip along its entire length for a period of 2 minutes. Mandrel will be positioned parallel to and recommended flap deflection (standoff distance from the bottom of mandrel to part surface) must be between 0.050 - 0.150 inch (1.27 - 3.81 mm) of surface being peened. Refer to Figure 5. The tool or shaft must be moved continuously in an overlapping circular motion to maximize uniformity of coverage. Refer to Figure 4.

NOTE: Refer to Figure 3 for reference. However, because of inherent variables of manually controlled mandrel position, each operator must establish a saturation curve that will assure the intensity required for each job.

- (5) Determine Almen strip arc height by placing test strip on Almen gage and record reading.
- (6) Repeat steps 4.B.(4) and 4.B.(5) with the same test strip and generate a saturation curve plotting the converted arc heights. A minimum of four arc heights are necessary. Refer to Figure 2.

NOTE: Unlike conventional peening, a single Almen strip may be used for creation of the saturation curve when using a magnetic fixture.

- (7) If saturation point thus determined is not within intensity limits of part to be peened, set tool speed to a new setting (increase tool speed to increase intensity and vice-versa) and determine the new saturation curve. Repeat this procedure until adequate peening intensity, within limits specified by Engine/Shop Manual repair procedure is achieved. Refer to Figure 1.
- (8) Check for uniformity of coverage with a minimum of 10x power magnification.
- (9) Calculate peening time for repair parts by multiplying saturation time by 1.25 (125 percent) unless otherwise directed by applicable instructions for the parts.

NOTE: The area to be peened must be peened in increments of time and visually inspected for coverage until full coverage is achieved. Coverage time is a function of part material hardness. For coverage requirements more than 100 percent, the time to reach full coverage of a peened area must be determined and then multiplied by the greater coverage percentage for total peening time.


Subtask 70-47-04-380-196

C. Peening Parts.

The following is intended for peening areas no larger than 2 sq inches (12.9 sq cm). If the area to be peened is larger than 2 sq inches (12.9 sq cm), it must be divided into sections, less than 2 sq inches (12.9 sq cm). Each section must be completely peened before proceeding to next section. Overlap at section boundaries is required.

- (1) If area to be peened is flat, position this area in a horizontal plane. If area is on a curved surface, position with approximate center of area uppermost for maximum accessibility.
- (2) Peen designated area on part with the same tool speed and technique used to establish saturation curve. Peening of part must be done by same operator who established peening parameters with test strips.
- (3) Periodically check rotary flap for missing balls. The loss of shot will affect coverage time, but not intensity. Replace flap if more than 2 balls are missing from either on one side.

* * * FOR ALL




NOTE:
 ALL DIMENSIONS GIVEN IN INCHES WITH
 METRIC UNITS IN PARENTHESES.

5059918-00

Figure 1 RPM Relationship and Intensity


* * * FOR ALL



1017075-02-C

Figure 2 Test Strip - Saturation Intensity


* * * FOR ALL



1017074-01-A

Figure 3 Typical Saturation Curves


* * * FOR ALL



1017073-01-C

Figure 4 Typical Overlapping - Circular Motion Pattern for Peening


* * * FOR ALL



5059994-00

Figure 5 Mandrel/Positioning

* * * FOR ALL




1017072-01-A

Figure 6 Peening Intensity/Tool Speed RPM

* * * FOR ALL

"A" TEST STRIP ARC HEIGHT CONVERSION



NOTE:
UNITS SHOWN ABOVE ARE
MULTIPLES OF 0.001 INCH.

1362098-00

Figure 7 "A" Test Strip Magnetic to Stripholder Arc Height Conversion Graph

* * * FOR ALL


MAGNETIC ARC HGT	CONVERTED ARC HGT	MAGNETIC ARC HGT	CONVERTED ARC HGT	MAGNETIC ARC HGT	CONVERTED ARC HGT	MAGNETIC ARC HGT	CONVERTED ARC HGT
5.0	5.0	9.0	7.4	13.0	9.8	17.0	12.2
5.1	5.1	9.1	7.5	13.1	9.9	17.1	12.3
5.2	5.1	9.2	7.5	13.2	9.9	17.2	12.3
5.3	5.2	9.3	7.6	13.3	10.0	17.3	12.4
5.4	5.2	9.4	7.6	13.4	10.0	17.4	12.4
5.5	5.3	9.5	7.7	13.5	10.1	17.5	12.5
5.6	5.4	9.6	7.8	13.6	10.2	17.6	12.6
5.7	5.4	9.7	7.8	13.7	10.2	17.7	12.6
5.8	5.5	9.8	7.9	13.8	10.3	17.8	12.7
5.9	5.6	9.9	7.9	13.9	10.3	17.9	12.7
6.0	5.6	10.0	8.0	14.0	10.4	18.0	12.8
6.1	5.7	10.1	8.1	14.1	10.5	18.1	12.9
6.2	5.7	10.2	8.1	14.2	10.5	18.2	12.9
6.3	5.8	10.3	8.2	14.3	10.6	18.3	13.0
6.4	5.8	10.4	8.2	14.4	10.6	18.4	13.0
6.5	5.9	10.5	8.3	14.5	10.7	18.5	13.1
6.6	6.0	10.6	8.4	14.6	10.8	18.6	13.2
6.7	6.0	10.7	8.4	14.7	10.8	18.7	13.2
6.8	6.1	10.8	8.5	14.8	10.9	18.8	13.3
6.9	6.2	10.9	8.5	14.9	10.9	18.9	13.3
7.0	6.2	11.0	8.6	15.0	11.0	19.0	13.4
7.1	6.3	11.1	8.7	15.1	11.1	19.1	13.5
7.2	6.3	11.2	8.7	15.2	11.1	19.2	13.5
7.3	6.4	11.3	8.8	15.3	11.2	19.3	13.6
7.4	6.4	11.4	8.8	15.4	11.2	19.4	13.6
7.5	6.5	11.5	8.9	15.5	11.3	19.5	13.7
7.6	6.6	11.6	9.0	15.6	11.4	19.6	13.8
7.7	6.6	11.7	9.0	15.7	11.4	19.7	13.8
7.8	6.7	11.8	9.1	15.8	11.5	19.8	13.9
7.9	6.7	11.9	9.1	15.9	11.5	19.9	13.9
8.0	6.8	12.0	9.2	16.0	11.6	20.0	14.0
8.1	6.9	12.1	9.3	16.1	11.7	20.1	14.1
8.2	6.9	12.2	9.3	16.2	11.7	20.2	14.1
8.3	7.0	12.3	9.4	16.3	11.8	20.3	14.2
8.4	7.0	12.4	9.4	16.4	11.8	20.4	14.2
8.5	7.1	12.5	9.5	16.5	11.9	20.5	14.3
8.6	7.2	12.6	9.6	16.6	12.0	20.6	14.4
8.7	7.2	12.7	9.6	16.7	12.0	20.7	14.4
8.8	7.3	12.8	9.7	16.8	12.1	20.8	14.5
8.9	7.3	12.9	9.7	16.9	12.1	20.9	14.5

NOTE:
 UNITS SHOWN ABOVE ARE
 MULTIPLES OF 0.001 INCH.

1362099-00

Figure 8 "A" Test Strip Arc Height Magnetic Stripholder Conversion Chart

* * * FOR ALL



NOTE:
UNITS SHOWN ABOVE ARE
MULTIPLES OF 0.001 INCH.

1362100-00

Figure 9 "N" Test Strip Arc Height Magnetic Stripholder Conversion Graph

* * * FOR ALL

MAGNETIC ARC HGT	CONVERTED ARC HGT	MAGNETIC ARC HGT	CONVERTED ARC HGT	MAGNETIC ARC HGT	CONVERTED ARC HGT	MAGNETIC ARC HGT	CONVERTED ARC HGT
3.0	2.7	7.0	6.3	11.0	9.9	15.0	13.5
3.1	2.8	7.1	6.4	11.1	10.0	15.1	13.6
3.2	2.9	7.2	6.5	11.2	10.1	15.2	13.7
3.3	3.0	7.3	6.6	11.3	10.2	15.3	13.8
3.4	3.1	7.4	6.7	11.4	10.3	15.4	13.9
3.5	3.2	7.5	6.7	11.5	10.4	15.5	14.0
3.6	3.2	7.6	6.8	11.6	10.4	15.6	14.0
3.7	3.3	7.7	6.9	11.7	10.5	15.7	14.1
3.8	3.4	7.8	7.0	11.8	10.6	15.8	14.2
3.9	3.5	7.9	7.1	11.9	10.7	15.9	14.3
4.0	3.6	8.0	7.2	12.0	10.8	16.0	14.4
4.1	3.7	8.1	7.3	12.1	10.9	16.1	14.5
4.2	3.8	8.2	7.4	12.2	11.0	16.2	14.6
4.3	3.9	8.3	7.5	12.3	11.1	16.3	14.7
4.4	4.0	8.4	7.6	12.4	11.2	16.4	14.8
4.5	4.1	8.5	7.6	12.5	11.3	16.5	14.9
4.6	4.1	8.6	7.7	12.6	11.3	16.6	14.9
4.7	4.2	8.7	7.8	12.7	11.4	16.7	15.0
4.8	4.3	8.8	7.9	12.8	11.5	16.8	15.1
4.9	4.4	8.9	8.0	12.9	11.6	16.9	15.2
5.0	4.5	9.0	8.1	13.0	11.7	17.0	15.3
5.1	4.6	9.1	8.2	13.1	11.8	17.1	15.4
5.2	4.7	9.2	8.3	13.2	11.9	17.2	15.5
5.3	4.8	9.3	8.4	13.3	12.0	17.3	15.6
5.4	4.9	9.4	8.5	13.4	12.1	17.4	15.7
5.5	5.0	9.5	8.5	13.5	12.2	17.5	15.8
5.6	5.0	9.6	8.6	13.6	12.2	17.6	15.8
5.7	5.1	9.7	8.7	13.7	12.3	17.7	15.9
5.8	5.2	9.8	8.8	13.8	12.4	17.8	16.0
5.9	5.3	9.9	8.9	13.9	12.5	17.9	16.1
6.0	5.4	10.0	9.0	14.0	12.6	18.0	16.2
6.1	5.5	10.1	9.1	14.1	12.7	18.1	16.3
6.2	5.6	10.2	9.2	14.2	12.8	18.2	16.4
6.3	5.7	10.3	9.3	14.3	12.9	18.3	16.5
6.4	5.8	10.4	9.4	14.4	13.0	18.4	16.6
6.5	5.8	10.5	9.5	14.5	13.1	18.5	16.7
6.6	5.9	10.6	9.5	14.6	13.1	18.6	16.7
6.7	6.0	10.7	9.6	14.7	13.2	18.7	16.8
6.8	6.1	10.8	9.7	14.8	13.3	18.8	16.9
6.9	6.2	10.9	9.8	14.9	13.4	18.9	17.0

NOTE:
 UNITS SHOWN ABOVE ARE
 MULTIPLES OF 0.001 INCH.

1362101-00

Figure 10 "N" Test Strip Arc Height Magnetic Stripholder Conversion Chart

5. Quality Assurance.

Subtask 70-47-04-380-194

- A. Establish peening requirements for intensity required each time a lot of similar parts is to be peened. Determine the peening requirements per Subtask 70-47-04-380-193, Procedure.
- B. Establish parameters each time operator is changed, such as shift change or job reassignment.
- C. At least one intensity determination or verification as defined in Subtask 70-47-04-380-195, Determination of Peening Requirements must be made prior to peening of part(s) to represent each tool and its equipment for each 30 minutes of continuous operation or fraction thereof, and for each change in intensity/RPM/Flap. Refer to Subtask 70-47-04-380-193, Procedure.
- D. Check peened area with a minimum of 10x power magnification to make sure that the coverage is complete. If coverage is not complete of individual indentations do not overlap, repeat the peening operation, refer to Subtask 70-47-04-380-196, Peening Parts. Holes must be inspected with a suitable optical instrument. Refer to Subtask 70-47-04-380-193, Procedure.

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media