

DISCLAIMER

The Incremental Changes published by GE Aviation are considered Instructions for Continued Airworthiness. These Incremental Changes, along with the current Manual revision and published Temporary Revisions, constitute the latest Instructions for Continued Airworthiness.

GE Designated: -CONFIDENTIAL-

The information contained in this document is GE proprietary information and is disclosed in confidence. It is the property of GE and shall not be used, disclosed to others or reproduced without the express written consent of GE, including, but without limitation, it is not to be used in the creation, manufacture, development, or derivation of any repairs, modifications, spare parts, designs, or configuration changes or to obtain FAA or any other government or regulatory approval to do so. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document shall appear in any such reproduction in whole or part.

This technical data is considered subject to the Export Administration Regulations (EAR) pursuant to 15 CFR Parts 730-774. Transfer of this data by any means to a Non-U.S. Person, whether in the United States or abroad, without the proper U.S. Government authorization (e.g., License, exemption, NLR, etc.), is strictly prohibited.

Copyright (2021) General Electric Company, U.S.A.

HIGHLIGHTS

HIGHLIGHT REFERENCE DESCRIPTION OF CHANGE

tk70-80-05-800-802 Technical Change: Added consumable material C05-130 to the Consumable Products table.

TASK 70-80-05-800-802

1. General.

Ref No.	Consumable Name / Remarks	Supplier
C05-001	Compound, Gear Marking Compound, Gear Marking, No. 10 Yellow Obsolete: Supplier Unavailable Compound, Gear Marking, No. 10 Yellow	Chemsol Inc.
C05-002	Ink, Marking Dykem (Steel Blue Layout Fluid, Transparent Blue Staining Color)	ITW Dykem/Dymon/Mark-tex
C05-003	Marking Pens NOTE: Remove all silver pencil marking before processing parts above 500 degrees F or placing parts into service. Carter's Marks-A-Lot (Black or Blue) Deleted LN9051 Red P/N 33404, Black D50TF8, Action Marker Nuclear Grade Fine Tip NOTE: No. 44 Medium Tip P/N 33729, White D50TF8, Action Marker Nuclear	Ratioplast GmbH ITW Dykem/Dymon/Mark-tex ITW Dykem/Dymon/Mark-tex

	Grade Fine Tip	
	NOTE: No. 44 Medium Tip	
	P/N 44404, Black D50TF8, Action Marker Nuclear Grade Medium Tip	ITW Dykem/Dymon/Mark-tex
	NOTE: No. 44 Medium Tip	
	P/N 44729, White D50TF8, Action Marker Nuclear Grade Medium Tip	ITW Dykem/Dymon/Mark-tex
	NOTE: No. 44 Medium Tip	
	P/N 55608, # 55 Valve Action Marker, # Y-608 Black Washout, High Purity	
	Obsolete: Replaced by P/N 91608, Valve Action Marker, Black Washout, High Purity	
	P/N 91608, Valve Action Marker, Black Washout, High Purity	
	Obsolete: Repair requirement no longer exists	
	Prismacolor Verithin Silver Pencil	Sanford Corp.
	T.E.C. Marker (Black)	Sanford Corp.
C05-004	Ink, Stamp Pad	
	Marco S-1141 (Black)	
	Deleted	
	P/N 82404, Q-404 High Purity Ink, Nuclear Grade	ITW Dykem/Dymon/Mark-tex
	NOTE: When using a rubber stamp with Q-404 ink, use a linen or cloth pad (Do Not use a foam Pad). Rubber stamp must be Buna-N (Black) not natural rubber (red).	
C05-005	Liquid, Leak (Bubble) Test (ASTM E515)	
	Leak-Tec 16-OX	American Gas and Chemical Company, Ltd.
C05-006	Fluid, Calibrating (MIL-PRF-7024)	
	Fluid, Calibrating, MIL-PRF-7024	Local Purchase
C05-007	Fluorescent Penetrant Kit	
	Kit ZA-HR	
	Obsolete: Repair requirement no longer exists	
C05-008	Phosphor Thermographic	
	No. 1807	
	Deleted: Contains Cadmium	
C05-009	Polyvinyl Alcohol	
	Partial Film No. 10	Rexco Chemical Co.
C05-010	Ink Marking Epoxy (White) (GE Spec. F50TF6 Class A)	
	No. 6893 Liquid Epoxy Ink (White)	Markem Corp.
	No. 6896, Stamp Pad Ink, (White)	Markem Corp.
C05-011	Tape, Teflon	
	0.0035 in. (0.089 mm) Max Thick Part No. 011200	
	Obsolete: Repair requirement no longer exists	
C05-012	Temperature Marking	
	Tempilstik 1100 deg. F.	Tempil Inc. / Division of ITW
	Tempilstik 1150 deg. F.	Tempil Inc. / Division of ITW
	Tempilstik 1200 deg. F.	Tempil Inc. / Division of ITW
	Tempilstik 1250 deg. F.	Tempil Inc. / Division of ITW
	Tempilstik 400 deg. F.	Tempil Inc. / Division of ITW
	Tempilstik 600 deg. F.	Tempil Inc. / Division of ITW
C05-013	Solutions, Electroetch	
	250A	Lectroetch Co.
C05-014	Solutions, Electroetch	
	250A Nuclear Grade	Lectroetch Co.
C05-015	Marking, Electrolyte	
	Monode MSC-1	Monode Marking Products Inc.
C05-016	Electrolytic Cleaners	

Formula 3 Cleaner	Lectroetch Co.	
C05-017 Electrolytic Cleaners		
Formula 3 Cleaner, Nuclear Grade	Lectroetch Co.	
C05-018 Marking, Electrolyte		
Monode MSC-3	Monode Marking Products Inc.	
C05-019 Stencils		
Blue (Long Life)	Monode Marking Products Inc.	LSG
Obsolete: Replaced by 5009-RS		
5009-RS	Lectroetch Co.	
C05-020 Marking Ink		
Dykem Hi Spot Blue (No. 107)	ITW Dykem/Dymon/Mark-tex	
C05-021 Solvent		
Dykem Remover and Thinner (No. 138)	ITW Dykem/Dymon/Mark-tex	
C05-022 Penetrant		
ZL-2C		
Deleted		
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual		
ZL2A		
Obsolete: Replaced by ZL-2C		
C05-023 Penetrant		
ZL-22A		
Obsolete: Replaced by ZL-27A		
ZL-27A		
Deleted		
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual		
C05-024 Penetrant		
ZL-30A		
Obsolete: Replaced by ZL-37		
ZL-37		
Deleted		
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual		
C05-025 Penetrant		
ZL-54		
Obsolete: Replaced by ZL-60D		
ZL-60D		
Deleted		
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual		
C05-026 Penetrant		
ZL-60B		
Deleted: Repair requirement no longer exists		
NOTE: Contains EPA Banned Compound		
C05-027 Penetrant		
P21		
Deleted: Repair requirement no longer exists		
NOTE: Contains EPA Banned Compound		
C05-028 Penetrant		
P40BGE		

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-029 Penetrant

P41

Obsolete: Replaced by P41H1

P41H1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-030 Penetrant

WP-100

Obsolete: Replaced by WP-100 LSBSD or WP-100H

WP-100 LSBSD

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

WP-100H

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-031 Penetrant

WP169

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-032 Penetrant

WP-1B

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-033 Penetrant

WP-170

Obsolete: Replaced by WP-170LSBD

WP-170LSBD

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-034 Penetrant

P148A

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-035 Penetrant

P149

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-036 Penetrant

P134

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-037 Penetrant

P136

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-038 Penetrant

FP-22B

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-039 Penetrant

FP30A

Obsolete: Replaced by RC-65

RC-65

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-040 Penetrant

HM440

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-041 Penetrant

P5TF4

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-042 Penetrant

Ardrox 985P1

Obsolete: Replaced by Ardrox 985P12

Ardrox 985P12

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-043 Penetrant

Ardrox 985P14

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

Ardrox 985P3

Obsolete: Replaced by Ardrox 985P14

C05-044 Penetrant

Ardrox 970-P24

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

Ardrox 970P10

Obsolete: Replaced by Ardrox P134D

Ardrox P134D

Obsolete: Replaced by Ardrox 970-P24

NOTE: Product ID Numbering Change by Vendor

C05-045 Penetrant

Ardrox 970P5

Obsolete: Replaced by Ardrox P133D

Ardrox P133D

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-046 Penetrant

Ardrox 985P13

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

Ardrox 985P2

Obsolete: Replaced by Ardrox 985P13

C05-047 Penetrant

OD-1700A Penetrant

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-048 Penetrant

OD-2800-II Penetrant

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-050 Penetrant

OD-2800-I Penetrant

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-051 Emulsifier and Solvent

ZE4B

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-052 Emulsifier and Solvent

ZE4A

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-053 Emulsifier and Solvent

ZR-10A

Deleted: Replaced by ZR-10B

NOTE: Contains EPA Banned Compound

ZR-10B

NOTE: Prohibited in EU, contains nonyl-phenol and nonyl-phenol ethoxylate equal or higher than 0.1 percent

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

ZR-10C

NOTE: Not available in the USA

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-054 Emulsifier and Solvent

E4

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-055 Emulsifier and Solvent

E41

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-056 Emulsifier

E157A

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-057 Emulsifier

ER-83A

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

ER82

Obsolete: Replaced by ER-83A

C05-058 Emulsifier

Ardrox 9PR3

Deleted: Repair requirement no longer exists

C05-059 Emulsifier

Ardrox 9PR12

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

Ardrox 9PR4

Obsolete: Replaced by Ardrox 9PR12

C05-060 Emulsifier

OD-1700B

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-061 Developer

ZP-14A

ITW Magnaflux

ZP-4A

Obsolete: Replaced by ZP-4B or ZP-14A

ZP-4B

ITW Magnaflux

C05-062 Developer

ZP-13A

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-063 Developer

ZP-5

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

- C05-064 Developer
SKD-S
Deleted: Repair requirement no longer exists
NOTE: Contains EPA Banned Compound
- C05-065 Developer
SKD-NF
Deleted: Repair requirement no longer exists
NOTE: Contains EPA Banned Compound
- C05-066 Developer
ZP-9
Deleted: Replaced by ZP-9F
NOTE: Contains EPA Banned Compound
ZP-9F
Deleted
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual
- C05-067 Developer
DD2A
Deleted
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual
- C05-068 Developer
WD
Deleted: Repair requirement no longer exists
NOTE: Contains EPA Banned Compound
- C05-069 Developer
NAD-NF
Deleted: Replaced by NAD-SB
NAD-SB
Deleted
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual
- C05-070 Developer
NAD
Deleted
NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual
- C05-071 Developer
D493A
Deleted: Repair requirement no longer exists
NOTE: Contains EPA Banned Compound
- C05-072 Developer
D492A
Deleted: Repair requirement no longer exists
NOTE: Contains EPA Banned Compound
- C05-073 Developer
D495A
Deleted: Repair requirement no longer exists
NOTE: Contains EPA Banned Compound
- C05-074 Developer

D499A

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-075 Developer

D499C

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-076 Developer

D-90G

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

D90

Obsolete: Replaced by D-90G

C05-077 Developer

D110

Deleted: Repair requirement no longer exists

NOTE: Contains EPA Banned Compound

C05-078 Developer

D-100

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-079 Developer

D-104

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

D-106

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

D101-NF

Obsolete: Replaced by D-104 or D-106

C05-080 Developer

D-1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-081 Developer

Ardrox 9D3

Obsolete: Replaced by Ardrox 9D4A

Ardrox 9D4A

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-082 Developer

Ardrox 9D1B

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

Ardrox 9D6

Obsolete: Replaced by Ardrox 9D1B

C05-083 Developer

Ardrox 9D71

Obsolete: Replaced by Ardrox 9D76

Ardrox 9D76

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-084 Developer

DN-600P

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-085 Developer

DN-900D

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-086 Oil-Base, red magnetic particles, Magnaflux Powder

No. 9C

Deleted: Replaced by C05-088

C05-087 Solvent, Petroleum (AMS 3160)

AMS 3160

Dynamation Research, Inc.

ES-6

Eldorado Chemical Co., Inc.

Facto Pure No. 30, or equivalent

Obsolete: Replaced by AMS 3160

Oil, AMS 3160 Suspension Fluid

Local Purchase

C05-088 Fluorescent Magnetic Particles

Magnaglo 14A Powder

ITW Magnaflux

Ardrox 8800

Chemetall Oakite / Division of Chemetall GmbH

No. 853-40 Powder

Obsolete: Replaced by Ardrox 8800

SY8000 A/1 Powder

Eishin Kagaku Co., Ltd.

Met-L-Chek 1400

Met-L-Chek Company

Met-L-Chek 1400A

Met-L-Chek Company

C05-089 Suspension Fluid

Suspension Fluid

Obsolete: Replaced by C05-087

C05-090 Liquid Water Conditioner

WA-4

Obsolete: Replaced by WC-1

WC-1

Obsolete: Replaced by WA-2B

WA-2B

Magnaflux

C05-091 Glycerin

O-G-491

Local Purchase

C05-092 Penetrant

ZL22C

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-093 Penetrant

F-6A-SP/1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-094 Emulsifier

F-6E-W/1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-095 Developer

F-5D/1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-096 Developer

F-4S (NT) /1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-097 Penetrant

F-6A/1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-098 Emulsifier

F-5E-SP/1

Deleted: Repair requirement no longer exists

C05-099 Penetrant

F-4A-C/1

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-100 Developer

ZL7

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-101 Penetrant

P60H

Deleted

NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual

C05-102 Aircraft Marker	Aircraft Marker	
	Obsolete: Replaced by C05-003	
C05-103 Tape, Reflective	No. 580-10	3M Company
C05-104 Ink Marker	Ink Marker	
	Deleted: Replaced by C05-003	
C05-105 Ink Marker	Ink Marker	
	Deleted: Replaced by C05-003	
C05-106 Electrolyte	Monode C-10, Electrolyte	Monode Marking Products Inc.
C05-107 Electrolyte	Monode A-10, Electrolyte	Monode Marking Products Inc.
C05-108 Electrolyte	Monode T-10 (NC), Electrolyte	Monode Marking Products Inc.
C05-109 Neutralizer	Monode APC, Neutralizer	Monode Marking Products Inc.
C05-110 Wetting Agent	Photo-Flo 200, Catalog No. 146 4502-4 Fl oz.	Eastman Kodak Co.
	NOTE: Photo-Flo 600 or 2100 may be substituted for Photo-Flo 200 for large tank applications with proper adjustments for concentration (see S1169)	
	Photo-Flo 200, Catalog No. 146 4510-16 Fl oz.	Eastman Kodak Co.
	NOTE: Photo-Flo 600 or 2100 may be substituted for Photo-Flo 200 for large tank applications with proper adjustments for concentration (see S1169)	
	Photo-Flo 2100, Catalog No. 141 8904-1 gallon	Eastman Kodak Co.
	Photo-Flo 600, Catalog No. 146 4528-1 gallon	Eastman Kodak Co.
C05-111 Chalk, Marking White (Extruded) A-A-318	Dustless Chalk P/N 31144	Dixon Ticonderoga Co.
C05-112 Pocket Comparator, 6X Magnification		Edmund Optics Inc.
C05-113 Inspection System, Honeycomb	P/N 4013518-290	Noble Tool Corp.
C05-114 Optical Refractor, Honeycomb Inspection System	P/N 4013518-319	Noble Tool Corp.
C05-115 Penetrant	RC-77	
	Deleted	
	NOTE: Refer to TASK 70-32-02-230-001, Fluorescent Penetrant Inspection or TASK 70-32-03-230-002, Spot-Fluorescent-Penetrant Inspection as specified in the Engine/Shop Manual	
C05-116 Wetting Agent	Orvus WA	Proctor & Gamble Co.
C05-117 Inspection Lacquer	F-900 Torque Seal	
	Obsolete: Replaced by Dykem Cross Check	
	Dykem Cross Check	ITW Dykem/Dymon/Mark-tex
C05-118 Marking, Electrolyte	2611A	Lectroetch Co.

C05-119 Marking, Electrolyte LNC-3, Nuclear Grade	Lectroetch Co.
C05-120 Electrolytic Cleaners Formula 2 Cleaner, Nuclear Grade	Lectroetch Co.
C05-121 Fluorescent Tracer Material, Shot Peen (GE Specification: D50TF9 Class A or Class B) 220-2 (Class A) 220-6 (Class B) 220 (Class A) FluoroFinder Type 3 (Class A)	Metal Improvement Co. Metal Improvement Co. Shannon Luminous Materials Co. American Gas & Chemical Company Ltd.
C05-122 Inspection Seal Lacquer F-925 Skydrol Resistant Torque Seal	Organic Products Co.
C05-123 Compound, White Gear Marking Cadco O4C-106 Brush	Cadillac Oil Company
C05-124 Facom Briancon Chalk Natural "Briancon" Chalk Sticks	Facom
C05-125 Water-Based Fluorescent Magnetic Particle Concentrate 14A Redi-Bath	Magnaflux
C05-126 Glass Reticle VIP S-7484M 1X Magnification	Visual Inspection Products, LLC
C05-127 Isopropyl Alcohol Specification: D5B57 at full strength	Local Purchase
C05-128 Couplant Soundsafe	Magnaflux Sonotech
C05-129 Probe Tape Polyimide Number 1205	3M Company
C05-130 Remover and Cleaner Dykem Remover Deleted: See C04-307	ITW Proband

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media