

Engine Model(s): PT6A

HIGHLIGHTS

Revision	CH/SE/SU	Pageblock Title	Description of Change
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13518R0 to SB13518R1.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13202R6 to SB13202R7.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13002R18 to SB13002R19.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13001R21 to SB13001R22.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to add SB13515R3.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to add SB13516.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13240R1 to SB13240R2.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to add SB13523R3.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13244R10 to SB13244R11.
57.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13503 to SB13503R1.
57.0	70.00.00 Standard Practices	70-00-00 STANDARD PRACTICES - MAINTENANCE PRACTICES	The procedure for safe handling of engine parts with suspected hexavalent chromium residue has been added.