

Engine Model(s): PT6A

**HIGHLIGHTS**

<b>Revision</b>	<b>CH/SE/SU</b>	<b>Pageblock Title</b>	<b>Description of Change</b>
58.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13490R1 to SB13490R2.
58.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB13206R5 to SB13206R6.
58.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to add SB13519.
58.0	Front	SPECIAL TOOLS/FIXTURES AND EQUIPMENT	The special tools list has been updated to correct tool number for alignment pin from (PWC64241) to (PWC64241-5).
58.0	72.00.00 Engine	72-00-00 ENGINE, TURBOPROP - FAULT ISOLATION	The graphic for engine operating fault isolation chart has been revised to add check for Np tachometer - power section and overspeed governor per AMM before replacing the propeller governor.
58.0	72.00.00 Engine	72-00-00 ENGINE, TURBOPROP - SERVICING	The oil analysis technology sampling procedure has been added.
58.0	72.50.01 Compressor Turbine Stator	72-50-01 COMPRESSOR TURBINE STATOR - MAINTENANCE PRACTICES	The special tools list has been updated to correct tool number for alignment pin from (PWC64241) to (PWC64241-5).
58.0	72.50.01 Compressor Turbine Stator	72-50-01 COMPRESSOR TURBINE STATOR - MAINTENANCE PRACTICES	The removal procedure of CT stator has been revised to delete the note and to add instruction to discard gasket and the installation procedure of CT stator has been revised to add instructions to install guidepins and the new gasket.