GADING AIR SDN. BHD. DOCUMENT TITLE: AIRCRAFT MAINTENANCE PROGRAMME AIRCRAFT TYPE: LEONARDO S.P.A HELICOPTERS AW139 PAGE TITLE: CAAM AND AD REQUIREMENTS REFERENCE: GASB/CAMO/AMP/AW139 ISSUE: 2 REVISION: 0 CHAPTER: 18.0 PAGE: 2 of 2 DATE: 7 FEBRUARY 2023 VIII SUE: VIII SUE: VIII SUE: VIII SUE: VIII SUE: 0

AD REQUIREMENTS

NO.	AD REFERENCE	DESCRIPTION	SB REFERENCE	TASK	RECURRING INTERVAL
1	EASA AD NO 2020- 0271 *OR LATER APPROVED REVISION	ATA 62 - MAIN ROTOR - SWASHPLATE BOOT - INSPECTION	LEONARDO HELICOPTER S.p.A. ASB NO. 139-654 NEW ISSUE (Part II) (or later approved revision)	Recurrent inspection of the boot rings for cracks and corrosion and of the adhesive for condition and restore the correct installation in case of damage (Part II)	Every 50 FH
2	EASA AD NO 2021- 0044 *OR LATER APPROVED REVISION	ATA 24 - ELECTRICAL POWER - OVERHEAD PANEL - INSPECTION	LEONARDO HELICOPTER S.p.A. ASB NO. 139-661 NEW ISSUE (Part II) (or later approved revision)	Recurrent inspection inside the overhead panel in order to check the tape condition and the absence of chafing (Part II)	(Every 300 FH / 12) Months
3	EASA AD 2022-0205 *OR LATER APPROVED REVISION	ATA 64 – TAIL ROTOR – TAIL ROTOR - DAMPER BRACKET - INSPECTION	LEONARDO HELICOPTER S.p.A. SBEA NO. 139-724 REV B (or later approved revision)	Recurrent inspection of the TR damper bracket P/N 3G6420A06131 for cracks and corrosion. If cracks present, perform replacement of the component.	Every 50 FH / 6 Months