

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-1034R1

Service Tool: PWC32069 Rev. B

Description: Puller

Effectivity: PT6A-38, PT6A-41, PT6A-42, PT6A-42A, PT6A-45A, PT6A-45B, PT6A-45R, PT6A-50, PT6A-52, PT6A-60A, PT6A-60AG, PT6A-61, PT6A-62, PT6A-64, PT6A-65AG, PT6A-65AR, PT6A-65B, PT6A-65R, PT6A-66A, PT6A-66, PT6A-66B, PT6A-66D, PT6A-67, PT6A-67A, PT6A-67AF, PT6A-67AG, PT6A-67B, PT6A-67D, PT6A-67F, PT6A-67P, PT6A-67R, PT6A-67T, PT6A-68, PT6A-68B, PT6A-68C, PT6A-68D, PT6A-68T, PT6B-67A, PT6C-67C, PT6C-67C1, PT6C-67D

Subject: Tool Introduction

Reason:

Problem: Difficulty using PWC32069 when removing coupling from shaft.

Cause: Pulling lips are flexing due to the higher torque required to remove.

Solution: Tool PWC77851 introduced to replace PWC32069.

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to:
VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Issued: Mar 25/2024
Revised: Apr 12/2024

PWC32069
Page 1 of 3

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-1034R1

Instruction: Replace existing tool PWC32069 with new tool PWC77851.

Compliance: Required

Tool Usage: Overhaul

Tool Disposition: Discard PWC32069 and replace with tool PWC77851. You can order a new tool from Pratt & Whitney Canada accredited suppliers.

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Mar 25/2024
Revised: Apr 12/2024

PWC32069
Page 2 of 3

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-1034R1

TSB REVISION NOTES			
TSB	DATE	Tool Rev No.	Changes
PT-1034	04/2024	1	TSB issued date corrected

ICN-00198-G000139679-001-01

Figure 1

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Mar 25/2024
Revised: Apr 12/2024

PWC32069
Page 3 of 3