PRATT & WHITNEY CANADA TOOL SERVICE BULLETIN

NO: PT-775R1

Service Tool:	PWC34522 Rev. E
Description:	Puller
Effectivity:	PT6A-38, PT6A-41, PT6A-42, PT6A-42A, PT6A-45A, PT6A-45B, PT6A-45R, PT6A-50, PT6A-52, PT6A-60A, PT6A-60AG, PT6A-61, PT6A-62, PT6A-64, PT6A-65B, PT6A-65R, PT6A-65AG, PT6A-65AR, PT6A-66, PT6A-66A, PT6A-66B, PT6A-66D, PT6A-67, PT6A-67A, PT6A-67AF, PT6A-67AG, PT6A-67B, PT6A-67D, PT6A-67F, PT6A-67P, PT6A-67R, PT6A-67T, PT6A-68, PT6A-68B, PT6A-68C, PT6A-68D, PT6A-68T, PT6A-140, PT6B-37A, PT6B-67A, PT6C-67A, PT6C-67C, PT6C-67C1, PT6C-67D, PT6T-3D, PT6T-3DE, PT6T-3DF
Subject:	Obsolete

Reason:

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to: VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Issued: Jan 05/2012 Revised: Oct 19/2023

PRATT & WHITNEY CANADA TOOL SERVICE BULLETIN

NO: PT-775R1

Problem:	blem: Ease of tool use.	
Cause:	Knocker puller changed to threaded puller.	
Solution:	Obselete and replaced by PWC71823.	
Instruction:	Not applicable.	
Compliance:	Optional	
Tool Usage:	e: Overhaul, Heavy Maintenance	
Tool Disposition:	Usable but no longer supported or procurable.	

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Jan 05/2012 Revised: Oct 19/2023

TOOL SERVICE BULLETIN

NO: PT-775R1

TSB Revision Notes				
TSB	DATE	Tool Rev No.	CHANGES	
PT-775	10/2023	1	Effectivity Revised to Include PT6A-50, PT6A-66B, PT6A-67P, PT6A-68, PT6A-68B PT6A-68C, PT6A-68D, PT6A-68T, PT6A-140, PT6C-67A PT6C-67C1	

ICN-00198-G000134672-001-01

Figure 1

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Jan 05/2012 Revised: Oct 19/2023 **PWC34522** Page 3 of 3