

TIC-AW139-24-0056

APPLICABLE TO M72-02 AND M72-03 ONLY.

PART I

AD/SB ID: 4779 Close Update

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND REPAIR

Title/Subject: SB NO. 139-616 NEW ISSUE - PART I

Version No:

Reason For Raising:

URL:

Date: 19 06 2024

AD/SB ID: 4780 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02	Date (Months)	-	Days	90	19/06/2024	18/12/2024	TO BE COMPLIED	
	M72-03	Date (Months)	-	Days	90	19/06/2024	18/12/2024	TO BE COMPLIED	

PART II

AD/SB ID: 4779

Close Update Save

- General
- Config List
- Aircraft List
- Task/Check List
- Linked To
- BOM

Type : SBS Repetitive

Reference/Number: ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND REPAIR

Title/Subject: SB NO. 139-616 NEW ISSUE - PART II

Version No:

Reason For Raising:

URL:

Date: 19 06 2024

AD/SB ID: 4779

Close Update Save & Close

- General
- Config List
- Aircraft List
- Task/Check List
- Linked To
- BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	OPEN	
	M72-03		-		0	-	-	OPEN	