LEONARDO

REPAIR QUOTATION

Leonardo Malaysia Sdn Bhd
Lot 1 & 2 , Helicopter Center,
Sultan Abdul Aziz Shah Airport
47200 Subang,
Selangor Darul Ehsan, Malaysia

Leonardo Malaysia - Warehouse
Lot 10, Jalan Teknologi, Taman Sains Selangor 1
Kota Damansara, 47810 Petalin Jaya
Selangor Darul Ehsan

CUSTOMER GALAXY (SUPERLYNX)	REPAIR QUOTATION FOR MATERIAL RELATED TO YOUR ORDER RMN-21-99	AW RMA 20418417	DATE 26.07.2022
	ON DATE 15.10.2021	ISSUE N 400500740	OUR QUOTATION N. LM-0358
SHIP TO GALAXY (SUPERLYNX)	CONTACT	TYPE OF CERTIFICATION	DATE 26.07.2022
	OFFER VALIDITY	CUSTOMER CODE 50009236	CURRENCY GBP
	Incoterms **Ex Works**	SHIPPING METHOD	PAYMENT TERMS FDM2

ITEM	SUPPLIABLE P/N - DESCRIPTION	UM	QUANTITY	S/N	UNIT PRICE	DISC %	TOTAL	ESTIMATED TAT DAY (*)
10	Part Number Received WK3039-0147-047 TAIL ROTOR HUB		N	AFP7479	34,556.56			210
	Part Number to be Despatched WK3039-0147-047 TAIL ROTOR HUB			AFP7479				
	WORK DETAIL : REPAIR							
	ACTIVITIES PRICE						34,556.56	

(*) TAT calculation starts when the returned components is received, eveluated and considered eligible for repair, or from the acceptance of Leonardo Helicopter proposal by the Customer whichever occurs last.
The above is not applicable if regulated by prior agreements executed between the Customer and Leonardo Helicopters .

Shipping Methods :
Payment Terms : FDM2 - 60days Billing Date

This quotation is definitive , a revised repair quotation will be issued in case :
- during the repair activity it is nessasary to perform additional work or to replace other components not estimated at this stage

Note : WE ARE WAITING FOR YOUR APPROVAL

WORK REQUIRED : REPAIR