PRECISION HELIPARTS SINGAPORE PTE LTD
690 WEST CAMP ROAD SINGAPORE 797523
JTC AVIATION 2 BUILDING #09-07 SINGAPORE
SELETAR AEROSPACE PARK www.precisionaviationgroup.com
65-6817-3370 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD
Attn: MUZDALIFAH
SUITE 11-14, HELICOPTER CENTRE,
MALAYSIA INTERNATIONAL AEROSPACE CENTRE
SULTAN ABDUL AZIZ SHAH AIRPORT
SUBANG 47200
MALAYSIA
Tel. : +60377347226

No. 5608239 Pg:1/1

Our Ref : SO# 5604918
Your Ref : RMN-24-1517
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : May-12-2024
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : Apr-12-2024

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	**418-00529-102** MAGNETIC BRAKE **Serial No(s).:** 2004 **ECCN:** 9A991.d Reported By Customer: Unit is INOP. Inspect and Advise Preliminary Inspection: Unit received in bad condition Motor ratcheting failed speed test, found with excessive play, requires replacement - USD 6,750.00 Gear found worn, requires replacement - USD 2,540.00 Shaft found worn, requires replacement - USD 995.00 Unit requires standard repair - USD 2,750.00 Unit requires replacement of parts and standard repair Total - USD 13,035.00 Corrective Action: Unit is to be Repaired per CMM and tested and recertified. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature:_____ Date:_____	RP	**1 EA**	**60 Days**	**$ 13,035.00 EA**	**$ 13,035.00**

Sub Total:	$ 13,035.00
Total: [USD]	$ 13,035.00

RIDZUAN BIN YA'AKOB,

Copyright (c) PENTAGON *2000* Software, Inc.
Ser #:[2000.21267] Ver 2019.01.01 Build 14

ORIGINAL