Nampa Valley Helicopters, Inc.

NAMPA VALLEY HELICOPTERS

1870 W. Franklin Rd.
Meridian, ID 83642
USA
Ph: 208-362-0851, Fax: 208-362-9726
customer_support@nvhelicopters.com

Work Order Quote

Quote #: 18961-RP
Version #: 1
Work Order #: 18961
Serial #: MA1329
Printed: 7/10/2024   **Page:** 1

To:	Ship To:
AIRWORTHINESS EXPERT **Galaxy Aerospace (M)** **Sdn Bhd, Sultan Abdul** **Aziz Shah Airport** **Subang, Selangor 47200** **Malaysia**	**Galaxy Aerospace** **Lot 11-14, MRO Centre, Malaysai** **International Aerospace Centre, SAA** **Airport** **Subang - Selangor - 47200** **Malaysia**

Ref #: RMN-24-1686   **Code:** AE3   **Site:**   **Terms:** PREPAYMENT

Description	Qty	Unit Price	Ext. Price
WO 18961 PN 350A33-0200-07 -			
Labor			
List	1	$2,160.00	$2,160.00
Labor Total:			**$2,160.00**
Parts			
350A33-1061-20 SPACER	1	$399.80	$399.80
Note:			
Items below are systematic			
77044-1 SEAL,MAGNETIC (VITON)	1	$1,269.30	$1,269.30
ECS2334BE060M NUT, HEXAGON	6	$2.68	$16.08
23111CA060 WASHER	6	$1.83	$10.98
AS3209-145 O RING	1	$8.41	$8.41
AS3209-036 Packing Preformed	1	$6.66	$6.66
ECS2033.62 PLATE,INDIC	1	$3.48	$3.48
704A39-821-036 SEAL	1	$119.21	$119.21
350A00-0120-73 LABEL	1	$8.39	$8.39
DHS812-419.00 PLATE,NAME	1	$6.69	$6.69
AS3209-013 O-Ring	2	$6.76	$13.52
Parts Total:			**$1,862.52**
Charges			
Bench Stock/Material -	1	$216.00	$216.00
Test Bench Run In: -	1	$430.00	$430.00
Charges Total:			**$646.00**

WQ Note: Only signs of leaking was minor wear on the spacer & wear lines on the magnet contact surface

Authorized Signature:

WO Total: $4,668.52

THIS IS NOT AN INVOICE. YOU WILL RECEIVE AN INVOICE WITHIN 48 HOURS OF APPROVAL   Payable in USD