TIC-AW139-22-0233

Edit Limitation (A/C: 9M-YTL)

Edit Limitation SBEA 139-731 REV./ PART I (EASA AD 2022-0209-E)-ATA 00 FORW...

Cancel | Save

Based On: Airframe Hours

Warning: 5

Warning Unit: Hours

Completed:

Due At:

Status: COMPLIED WITH

Limitation Notes:

```
REFER TIC-AW139-22-0233

LAST DONE - WP NO. 9M-YTL-13059 AT 348:40FH ON 12-OCT-22 (AJL 1569)

APPLICABILITY: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED.

PART I: WITHIN AND NOT LATER THAN 10FH FROM THE ISSUE DATE OF THIS SERVICE BULLETIN.
```

Aeronet Galaxy Aerospace > Modifications >Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

AD/SB ID: 10129

Close | Update | Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS — Repetitive

Reference/Number: ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION

Title/Subject: SBEA 139-731 REV./ PART I (EASA AD 2022-0209-E)

Edit Limitation (A/C: 9M-YTL)

Based On: Airframe Hours

Warning: 10

Warning Unit: Hours

Completed:

Due At:

Status: COMPLIED WITH

Limitation Notes:

```
REFER TIC-AW139-22-0233

LAST DONE - WP NO. 9M-YTL-13062 AT 348:40FH ON 12-OCT-22 (AJL 1569)

APPLICABILITY: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED.

PART I: WITHIN AND NOT LATER THAN 10FH FROM THE ISSUE DATE OF THIS SERVICE BULLETIN.
PART II: WITHIN AND NOT LATER THAN 25FH FROM THE ISSUE DATE OF THIS SERVICE BULLETIN.
```

Aeronet Galaxy Aerospace > Modifications >Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

AD/SB ID: 10130

Close | Update | Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS — Repetitive

Reference/Number: ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION

Title/Subject: SBEA 139-731 REV./ PART II (EASA AD 2022-0209-E)