

Aircraft Type: AW 139
Date: 21/Apr/2024



Tail No	Task / Defect Description	Duration	Job No.	Remarks
9M-PMA s/n: 31807	1 NO.2 PUMP LIP SEAL REPLACEMENT DUE TO LEAK	2 DAYS	UMC-PMA-24-011	AWAITING PTF
	2 1W CCP	TBN	9M-PMA-18979	AWAITING EGR
	3			
	4			
	5			
	6			
	7			
	8			
	9			
	10			
9M-PMB s/n: 31726	1 2Y INSP + 2Y CCP + 1200FH//2Y INSP + 1500FH//2Y INSP + FRAME INSP STA 3120 REPAIR AREA	TBN	9M-PMB-17936	IN PROGRESS
	2 1Y INSP + 400FH//1Y INSP + 500FH//1Y INSP + 600FH//1Y + 900FH//1Y + 1Y CCP + 1200 FH INSP	TBN	9M-PMB-17896	IN PROGRESS
	3 **8 YEARS INSPECTION	TBN	9M-PMB-18183	IN PROGRESS
	4 4Y INSP + 2400FH//4Y + 2400FH//4Y INSP	TBN	9M-PMB-18184	IN PROGRESS
	5			
	6			
	7			
	8			
	9			
	10			
9M-PMD s/n: 31809	1 NIL			
	2			
	3			
	4			
	5			
	6			
	7			
	8			
	9			
	10			
9M-PME s/n: 31855	1 DISPLAY UNIT FOUND INOPERATIVE	TBN	TBN	IN PROGRESS
	2			
	3			
	4			
	5			
	6			
	7			
	8			
	9			
	10			
9M-PMF s/n: 31913	1 NIL			
	2			
	3			
	4			
	5			
	6			
	7			
	8			
	9			
	10			
9M-JPM s/n: 31899	1 NIL			
	2			
	3			
	4			
	5			
	6			
	7			
	8			
	9			
	10			

Abbreviation

F	Flying
Tf	Test flight
FMC	Full Mission Capability
PMC	Partial Mission Capability

S	Serviceable
Ms	Maintenance schedule
Mr	Maintenance repair
L	Awaiting Maintenance
A	Awaiting Spare

Ao	Operation Availability
ALDT	Aircraft on ground / Maintenance down time
MOD	Modification / Service Bulletin

Prepared by:

Sign: _____

Name: AMIRUL ASYRAF BIN SAM

Verified by:

Sign: _____

Name: _____