

GALAXY AEROSPACE (M) SDN BHD
SUITE 11-14, HELICOPTER CENTRE
MALAYSIA INTERNATIONAL AEROSPACE CENTRE
SULTAN ABDUL AZIZ SHAH AIRPORT
47200 SUBANG. SELANGOR.
MALAYSIA.

QUOTATION

Your Ref	: GB60/20 GPU PMC & DEFECT	Ref No	: GALAXY/SZB/10597/2021
Attn	: EN. MUHAMMAD	Date	: 22 JANUARY 2021
Designation	: LEAD ENGINEER	Contact	: Nizuyir Buyong
E-mail	: muhammad@galaxyaerospace.my	Mobile	: 019-288 3155
Telephone	: +6013-905-4556		

REF: TO CARRY OUT PREVENTIVE MAINTENANCE – GUINAULT GPU MODEL: GB60/20V04.

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
1.	MODEL: GB60/20V04D1100; S/N: 17026. OPTG HOURS: 185.5 HOURS. TO CARRY OUT PREVENTIVE MAINTENANCE CHECK IN ACCORDANCE WITH GUINAULT TECHNICAL MANUAL.	01 EA.		
1.1.	TO REPLACE OIL FILTER P/N: MTFH10210.	01 EA	75.00	75.00
1.2.	TO REPLACE LUBRICATING OIL. SAE 15W-40.	14L.	20.00	280.00
1.3.	TO REPLACE FUEL FILTER P/N: MTFG00550.	01 EA	65.00	65.00
2.	MODEL: GB60/20V04D1100; S/N: 17454. OPTG HOURS: 163.5 HOURS. TO CARRY OUT PREVENTIVE MAINTENANCE CHECK IN ACCORDANCE WITH GUINAULT TECHNICAL MANUAL.	01 EA.		
2.1.	TO REPLACE OIL FILTER P/N: MTFH10210.	01 EA	75.00	75.00
2.2.	TO REPLACE LUBRICATING OIL. SAE 15W-40.	14L.	20.00	280.00
2.3.	TO REPLACE FUEL FILTER P/N: MTFG00550.	01 EA	65.00	65.00
3.	LABOUR TO CARRY OUT PREVENTIVE MAINTENANCE, INSPECTION, AND FUNCTIONAL TEST.	16 MHRS.	50.00	800.00
4.	MODEL: GB60/20V04D1100; S/N: 17454. OPTG HOURS: 163.5 HOURS. ENGINE EMITTED WHITE SMOKE AFTER START. TO CARRY OUT DEFECT TROUBLE SHOOTING & RECTIFICATION.	8 MHRS.	50.00	400.00
4.1.	FUEL SUPPLY CONTAMINATED. TO DRAIN FUEL FROM FUEL TANK.			
4.2.	TO REMOVE FUEL TANK, FLUSH AND RE-INSTALL FUEL TANK.			
TOTAL				2,040.00


Terms & Conditions:

Terms & Conditions : The above work scope is for the PMC and defect rectification. Any additional work for defect rectification, spare parts and labour will be charged separately.
Price validity : 30 days from date of this offer.
Delivery : ASAP.
Payment Terms : CASH ON DELIVERY.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.





Thank you.

For NN IDAMAN SDN BHD



Nizuyir Buyong
Managing Director



1.	<p style="text-align: center;">GB60/20; S/N: 17454</p>  <p>OPPO F9</p>
2.	<p style="text-align: center;">GENERAL VIEW OF GPU</p>  <p>OPPO F9</p>
3.	<p style="text-align: center;">RUNNING @ OPTIMUM SPEED</p>  <p>OPPO F9</p>
4.	<p style="text-align: center;">FUEL STRAINER/FILTER BASE</p>  <p>OPPO F9</p> <p style="text-align: center;">FUEL STRAINER CLOGGED.</p>