

GALAXY AEROSPACE (M) SDN BHD
SUITE 11-14, HELICOPTER CENTRE
MALAYSIA INTERNATIONAL AEROSPACE CENTRE
SULTAN ABDUL AZIZ SHAH AIRPORT
47200 SUBANG. SELANGOR.

QUOTATION

Your Ref	: YOUR REQUEST 13/5/22.	Ref No	: GALAXY/SZB/10896/2022
Attn	: EN. FADZLIE ADAM	Date	: 13 MAY 2022
Designation	: HPM PLANNER	Contact	: Nizuyir Buyong
E-mail	: fadlieadam@galaxyaerospace.my	Mobile	: 019-288 3155
Telephone	: +6017-398-9835		

REF: 400HZ UNABLE TO COME ON-LINE – GUINAULT MODEL: GB60/20V04D1100; S/N: 17026.

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
	TYPE: GUINAULT GPU MODEL: GB60/20V04D1100; S/N: 17026. REPORTED AC OUTPUT UNABLE TO COME ON-LINE. OPTG HOUR: 271 HOURS. TO CARRY OUT TROUBLE SHOOTING & RECTIFICATION OF THE DEFECT.			
1.	CARRIED OUT TROUBLE SHOOTING, FOUND PHASE C NIL OUTPUT. CABLE AT AIRCRAFT PLUG OPEN CIRCUIT. TO REPLACE PLUG ASSEMBLY. P/N: CXPA00020.	01 EA.	2,650.00	2,650.00
2..	LABOUR TO CARRY OUT TROUBLE SHOOTING, REPLACEMENT OF AIRCRAFT PLUG AND FUNCTIONAL TEST OF THE GPU.	LUM SUM	600.00	600.00
TOTA3,250.00				3,250.00

Terms & Conditions : The above quotation is based on the conditions of the GPU during inspection & trouble shooting. Any additional defects found will be charged in addition to the above work scope.

Price validity : 30 days from date of this offer.


Delivery : 1 week.

Payment Terms : 100% IN ADVANCE.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD


Nizuyir Buyong
Managing Director

