

NN IDAMAN SDN BHD (860809W) LOT 12971 A, JALAN BBN 1/7E, PUTRA NILAI, 71800 NILAI. NEGERI SEMBILAN. MALAYSIA. TEL : +606-856 9155; H/P : +6019-288 3155 / +6012-400 4132 EMAIL : nizuyir.nnidaman@yahoo.com / nora.nnidaman@yahoo.com

## GALAXY AEROSPACE (M) SDN BHD

SUITE 11-14, HELICOPTER CENTRE MALAYSIA INTERNATIONAL AEROSPACE CENTRE SULTAN ABDUL AZIZ SHAH AIRPORT 47200 SUBANG, SELANGOR,

## QUOTATION

| Your Ref    | : YOUR REQUEST 24/7/23.         |
|-------------|---------------------------------|
| Attn        | : EN. FADZLIE ADAM              |
| Designation | : HPM PLANNER                   |
| E-mail      | : fadlieadam@galaxyaerospace.my |
| Telephone   | : +6017-398-9835                |

Ref No : GALAXY/SZB/11185/2023 : 15 SEPTEMBER 2023 Contact : Nizuyir Buyong Mobile : 019-288 3155

Date

## REF: 400HZ UNABLE TO START - GUINAULT MODEL: GB60/20V04D1100; S/N: 17026.

| NO.  | DESCRIPTION  | QTY    | U. PRICE<br>(RM) | TTL PRICE<br>(RM) |
|------|--|--------|------------------|-------------------|
|      | TYPE: GUINAULT GPU MODEL: GB60/20V04D1100; S/N: 17026.   |        | (11141)          | (((())))          |
|      | OPTG HOUR: <b>322.1 HOURS</b> .                          |        |                  |                   |
|      | REPORTED HIGH TEMPERATURE & ALTERNATOR FAULT MESSAGE.    |        |                  |                   |
|      | GPU UNABLE TO START.                                     |        |                  |                   |
| 1.   | DURING INSPECTION FOUND ENGINE OIL LEVEL LOW AND DIRTY.  |        |                  |                   |
|      | ENGINE SERVICE OVERDUE. TO CARRY OUT PMC SERVICING.      |        |                  |                   |
| 1.1. | TO REPLACE ENGINE OIL. SAE 15-40W.                       | 12L    | 20.00            | 240.00            |
| 1.2. | TO REPLACE OIL FILTER. P/N: MTFH10210.                   | 01 EA. | 85.00            | 85.00             |
| 1.3. | TO REPLACE FUEL FILTER. P/N: MTFG00550.                  | 01 EA. | 75.00            | 75.00             |
| 1.4. | TO REPLACE AIR SAFETY FILTER. P/N: MTFA10393             | 01 EA. | 315.00           | 315.00            |
| 1.5. | TO REPLACE AIR FILTER. P/N: MTFA10392.                   | 01 EA. | 225.00           | 225.00            |
| 2.   | ALTERNATOR FAULT MESSAGE: TO INSPECT ALTERNATOR V-BELT   | 01 EA. | 1,600.00         | 1,600.00          |
|      | FOR CONDITION & SECURITY.                                |        |                  |                   |
| 3.   | HIGH TEMPERATURE MESSAGE CAME ON. TO CARRY OUT TROUBLE   | 01 EA. |                  |                   |
|      | SHOOTING AND CHECKED OPERATION.                          | OI LA. |                  |                   |
| 4.   | LABOUR TO CARRY OUT TROUBLE SHOOTING, RECTIFICATION, PMC | LUM    |                  |                   |
|      | AND FUNCTIONAL TEST OF THE GPU.                          | SUM    |                  |                   |
|      | TOTAL  |        |                  | 2,540.00          |

Terms & : The above quotation is based on the conditions of the GPU during inspection & trouble Conditions shooting. Any additional defects found will be charged in addition to the above work scope. Price validity : 30 days from date of this offer. Delivery : 1 week. Payment Terms : 100% IN ADVANCE.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD

Nizuyir Buyong





NN IDAMAN SDN BHD (860809W) LOT 12971 A, JALAN BBN 1/7E, PUTRA NILAI, 71800 NILAI. NEGERI SEMBILAN. MALAYSIA. TEL : +606-856 9155; H/P : +6019-288 3155 / +6012-400 4132 EMAIL : nizuyir.nnidaman@yahoo.com / nora.nnidaman@yahoo.com

Managing Director