

**AVP-AERO VOO DE PORTUGAL**

Avionics MRO Repair Facility / EASA Repair Station PT.145.039  
 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal  
 Tel: +351 219 411 208 Fax: +351 219 411 210  
**www.avp.com.pt** email: [avp@avp.com.pt](mailto:avp@avp.com.pt)  
 VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

**COTAÇÃO Nº**

Quotation Nº

20223990R2-2

Page 1-2

<b>V. Ref./ Your Ref:</b>	PL/CTS/AERO/2022/026	<b>Data/Date:</b>	27-Jul-22		
<b>Para/To:</b>	CTS-CHOPPERTECH SERVIÇOS SDN BHD				
<b>Ao Cuidado/ Attn of:</b>	Robin Chin	<b>Assunto/ Subject</b>	Repair Quote		
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	0202HRA/1	RADAR ALTIMETER TRANSCIEVER (RADALT)	5841-99-717-8209	138/03	Repair


<b>A. Avaria Reportada pelo Cliente/</b> Description of Discrepancy Reported by Client	A.1- PAGE 2
<b>B. Descrição da Avaria feita pela AVP/</b> Description of Discrepancy found by AVP	B.1- PAGE 2
<b>C. Teste de inspeção e de bancada/</b> Bench test of unit (em caso de rejeição do orçamento este é o valor até à data presente) * Broker and Customs Fee (In case of rejection this is the value at the present date)	3500.00 €
<b>D. Abertura e desmontagem da unidade/</b> Open and dismount Instrument	0.00 €
<b>E. Reparação e revisão da unidade/</b> Repair and Revision to Latest Configuration	11500.00 €
<b>F. Montagem, pintura, teste final e calibração/</b> Assemble, retest, paint and calibrate to T.O Standards	0.00 €
<b>G. Material substituído/</b> Material Replaced:	
	Description
	G.1 Material in page 2
	0.00 €
	Broker and Custom Fees
	Included in point C
	<b>Valor Final</b>
	Final Value
	15000.00 €
	<b>Discount</b>
	0.00 €
	<b>IVA 23%</b>
	Taxes
	0.00 €
	<b>Valor Final Com Iva</b>
	Final Value With Taxes
	15000.00 €
<b>H.Garantia/</b> Warranty:	O valor monetário usado é o Euros.
<b>1 Year warranty against work done and parts replaced from date of Certificate</b>	<b>Currency quoted in euros.</b>
<b>I. Entrega/</b> Delivery:	
10 working days after quote approval	
<b>J. Observações/</b> Observations:	
Payment <b>Proforma Invoice before delivery</b>	
The quote is valid for <b>180 days</b> .	
The unit is sent with <b>Certificate of Conformance and Component Condition Report</b> .	

Aprova/ Approved \_\_\_\_\_

Assinatura:  
Signature

Não Aprova/ Disapproved \_\_\_\_\_

Entregar Como Está/ Return As Is \_\_\_\_\_

	<b>AVP-AERO VOO DE PORTUGAL</b> Avionics MRO Repair Facility / EASA Repair Station PT.145.039 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal Tel: +351 219 411 208 Fax: +351 219 411 210 <b>www.avp.com.pt</b> email: <a href="mailto:avp@avp.com.pt">avp@avp.com.pt</a> <small>VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082</small>		<b>COTAÇÃO Nº</b> Quotation Nº 20223990R2-2 Page 2-2		
	<b>V. Ref./ Your Ref:</b> PL/CTS/AERO/2022/026	<b>Data/Date:</b> 27-Jul-22			
<b>Para/To:</b>	CTS-CHOPPERTECH SERVIÇOS SDN BHD				
<b>Ao Cuidado/ Attn of:</b> Robin Chin	<b>Assunto/ Subject:</b>	Repair Quote			
<b>#</b>	<b>Peça número Part Number</b>	<b>Descrição Description</b>	<b>NNA/NSN</b>	<b>NS/SN</b>	<b>Condição Condition</b>
01	0202HRA/1	RADAR ALTIMETER TRANSCEIVER (RADALT)	5841-99-717-8209	138/03	Repair

#### A.1 Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Customer

01-ITEM WRAPPING AND STORAGE AT STORE.

#### B.1 Avaria detectada pela AVP/ Description of defects found by AVP

1. Power supply INOP

#### C.1 Teste de inspeção e de bancada/ Bench test of unit

01- Unit requires to be open, cleaned, repaired, lubricated, closed and tested to go back to work.

#### G.1 Material – Details

Part Number	Description	Qty	Unit Price	Total Price
2N3497	Transistor	1	Included in repair price	Included in repair price
M39062/21-0139	Capacitor	1	Included in repair price	Included in repair price
2N3716	Transistor	1	Included in repair price	Included in repair price
			<b>Total</b>	<b>0.00 €</b>