



|             |                  |
|-------------|------------------|
| Date        | February 7, 2024 |
| Valid Until | March 9, 2024    |
| Quote #     | 24QSA02018       |
| Currency    | MYR              |

**Sunaero Asia Sdn Bhd**

Julian Francis  
 Phone: +60 12 644 8821  
 @: jfrancis@sunaero.com

**Galaxy Aerospace (M) Sdn Bhd**

Che Wan Muhammad Luqman  
 Phone: 603-7455 0555  
 @: cwluqman.galaxy@gmail.com

| Item                       | Non Contractual Pictures | P/N             | Description   | Unit Price | Qty | Total         |
|----------------------------|--------------------------|-----------------|---|------------|-----|---------------|
| <b>Fuel Bladder Repair</b> |                          |                 |   |            |     |               |
| 1                          | n/a                      | WG1357-0005-103 | <b>Fuel Bladder Repair</b><br>Aircraft type: AW SuperLynx MK100<br>Operator: Royal Malaysian Navy<br>S/N: FPT/368905<br>Aircraft registration: M501-4   | 20,592     | 1   | <b>20,592</b> |
| 2                          | n/a                      | n/a             | <b>Transportation cost</b><br>Iskandar Puteri - Subang  | 1,749      | 1   | <b>1,749</b>  |
| 3                          | n/a                      | n/a             | <b>Term &amp; Condition</b><br>a) Price inclusive tear down inspection & repair cost.<br>b) Repair will be carried out in accordance with Design Repair Approval GAM308/DRAS provided by Galaxy Aerospace.<br>c) All repair materials listed in accordance with Design Repair Approval GAM308/DRAS shall be provided by Galaxy Aerospace.<br>d) Additional charges and lead time shall apply should Sunaero found additional damage during repair process.<br>e) For the specific repair tasks undertaken, Sunaero explicitly disclaims any warranty associated with the repair work. This exclusion applies to, but is not limited to, the replacement of components, adjustments, or any other repair-related services performed.<br>f) Customer acknowledges and agrees that any risks associated with the repair services, including the potential for failure or unsatisfactory performance, are assumed by the customer. Sunaero shall not be held responsible for any direct, indirect, incidental, or consequential damages arising from the repair services.<br>g) Repair will commence upon receipt of Purchase Order and receipt of finalised Design Repair Approval GAM308/DRAS by Galaxy Aerospace. The repaired components shall be released upon receipt of full payment.<br>h) Certificate of Conformance (CoC) will be issued under ISO9001-2015. Design Repair Approval GAM308/DRAS | -          | -   | -             |
| <b>Total</b>               |                          |                 |   |            |     | <b>22,341</b> |

**Terms & Conditions :**

|                         |  |
|-------------------------|--|
| Lead Time :             | 10 working days upon receipt repair order (RO) |
| Payment Terms service : | Advanced payment                               |
| Payment means :         | Swift transfer                                 |
| Incoterm CCI 2010 :     | DAP to Johor Bahru, MALAYSIA                   |
| Warranty Conditions :   | Excluded                                       |

CGVS/GT&C available following this link [www.sunaero.com/CGVS/CGVS\\_FR\\_and\\_EN.pdf](http://www.sunaero.com/CGVS/CGVS_FR_and_EN.pdf)