



CRS # 25FR283B EASA.145.6177

3200 Howard Street  
 McClellan CA 95652  
 Ph 916-434-5194  
 Fx 916-434-5637  
[www.FreedomAeroService.Com](http://www.FreedomAeroService.Com)

116799

Quote #: W26025  
 Date Printed: 5/19/2022  
 Time: 3:12:40 PM  
 Page: 1

<b>To:</b> ATTN: Shannon Lyon Prime Industries, Inc. 406 Dividend Drive Peachtree City,GA 30269 United States	<b>Ship To:</b> Prime Industries, Inc. 406 Dividend Drive Peachtree City,GA 30269 United States
---	--

<b>Ref #:</b> 051330	<b>Phone #:</b> 770-632-1851	<b>Fax #:</b> 770-632-1852	<b>Email:</b> slyon@primeindustriesusa.com
<b>Code:</b> 8526	<b>Site:</b> NA	<b>PN:</b> 300SGL146Q-3	<b>Descr:</b> Starter Generator
<b>Quantity:</b> 1			

<b>TSN:</b> 3319.49	<b>TSO:</b> 0	<b>TSR:</b> 0	<b>CSN:</b> 0	<b>CSO:</b> 0	<b>CSR:</b> 0
---------------------	---------------	---------------	---------------	---------------	---------------

**Please Check one:**

\*Approved       \*Return As Is       \*Scrap On-Site       \*Tear-down charges still apply.

**Serial Numbers:** 9039

**Faults:**  
 Pretest and teardown findings  
 Speed sensor failed pretest, replacement required. T-Block divider cracked, repair required. Unit disassembled and cleaned. Evaluated found, Thermal switch non operable, replacement required. Unit passes all additional dimensional and electrical checks for overhaul .

Overhaul

Parts above normal \$925.82  
 Speed sensor MSP3090-2 \$481.25  
 Thermal Switch 300SG1254-2 \$444.57

Labor above normal \$515.00  
 Terminal block repair

WRITTEN AUTHORIZATION REQUIRED BEFORE WE CAN PROCEED.  
 Quote is valid for 30 days, parts are subject to prior sale. Failure to respond within 45 days will result in this item being returned as is or scrapped at our facility and you will be invoiced for the evaluation fee. There will be a reasonable evaluation fee for all declined quotes unless otherwise negotiated. Any unit put on hold will be invoiced for the evaluation fee at that time.

<b>Authorized Signature:</b>	<b>Total Parts:</b> 925.82
	<b>Total Labor:</b> 515.00
<b>Print:</b> _____ <b>Date:</b> _____	<b>Total Misc:</b> _____
<b>Signature:</b> _____	_____
<b>Advise Shipping Instructions:</b>	_____
<b>Method:</b>	_____
<b>Acct:</b>	<b>Total:</b> _____
<b>For Questions or Comments Please Contact Scott Durham</b>	