

LOG CARD

Sezione 1

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°

Part n°

DESCRIPTION (1) Tail Rotor Actuator	P/N (2) 366730V00731	S/N (3) HSC 223536	MANUFACTURER NAME (4) Claverham	ASSEMBLY DATE (5) JULY 2010	RETIREMENT LIFE (6) 3000 FH 01H
	P/N (7) 366730V00732	S/N (8) HSC 223536	MANUFACTURER NAME (9) UTC Aerospace Systems Wroclaw Sp. z o.o.	DATE OF CHANGE (10) 2020-11-27	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

Handwritten: 12/069, LPI 76, Bemah

NOTES (12)

ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL								
DATE (13)	A/C		ASSY		ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)		
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)					TIME SINCE OH (18)	TOTAL TIME (23)				TIME SINCE OH (24)	
202-11-20	VH-542	31155	1019.8	00.00	NEW	CHC POST	[Signature]	25/09/13	2381:12	1361:24	1361:24	NEW	Removed serviceable to service VH-54J (Csn 31114) - ref WP: 152/13 WSP 172A/13	CHC AUS	[H1 (AUS) 04]
23/09/13	VH-54J	31114	2908.49	1361.24	NEW	CHC AUS	[Signature]	10/12/13	3023:50	1476:25	1476:25	NEW	Removed VH-54J Ref WP 35/13 WSP 2278/13	CHC AUS	[H1 (AUS) 14]
12/08/14	PH-EUF	31406	2975:18	1476:25	NEW	CHC HR	[Signature]	17 Dec 2015	4471:15	2974:22	2974:22	Time	Time	Y-2. CHC/HR	[H0 42]

AG GEI 186 I 01

