



REPAIR QUOTATION

Leonardo Malaysia - Warehouse
 Lot 10, Jalan Teknologi, Taman Sains Selangor 1
 Kota Damansara, 47810 Petaling Jaya
 Selangor Darul Ehsan

Leonardo Malaysia Sdn Bhd
 Lot 1 & 2 , Helicopter Center,
 Sultan Abdul Aziz Shah Airport
 47200 Subang,
 Selangor Darul Ehsan, Malaysia

CUSTOMER GALAXY (SUPERLYNX)	REPAIR QUOTATION FOR MATERIAL RELATED TO YOUR ORDER RMN-22-620 ON DATE 22.08.2022	AW RMA 20448912 ISSUE N 400560060 TYPE OF CERTIFICATION COC	DATE 25.07.2023 OUR QUOTATION N. LM-6015 DATE 25.07.2023 CURRENCY GBP PAYMENT TERMS X021
SHIP TO GALAXY (SUPERLYNX)	CONTACT OFFER VALIDITY Incoterms Ex Works	CUSTOMER CODE 50009236 SHIPPING METHOD	

ITEM	SUPPLIABLE P/N - DESCRIPTION	UM	QUANTITY	S/N	UNIT PRICE	DISC %	TOTAL	ESTIMATED TAT DAY (*)
10	Part Number Received 765100-10 SENSOR ELECTRONIC UNIT		N	006	39,002.66		39,002.66	90
	Part Number to be Despatched 765100-10 SENSOR ELECTRONIC UNIT			006				
	WORK DETAIL : Repair							
	ACTIVITIES PRICE						39,002.66	
(*) TAT calculation starts when the returned components is received, evaluated and considered eligible for repair, or from the acceptance of Leonardo Helicopter proposal by the Customer whichever occurs last. The above is not applicable if regulated by prior agreements executed between the Customer and Leonardo Helicopters . Shipping Methods : Payment Terms : X021 - Advance Payment This quotation is definitive , a revised repair quotation will be issued in case : - during the repair activity it is nessasary to perform additional work or to replace other components not estimated at this stage Note : WE ARE WAITING FOR YOUR APPROVAL WORK REQUIRED : AS ABOVE								