

Galaxy Aerospace (M) Sdn. Bhd.
Suite 11-14, Helicopter Centre,
Malaysia International
Aerospace Centre,
Sultan Abdul Aziz Shah Airport
47200 SUBANG, SELANGOR,
MALAYSIA

Karlsruher Strasse 91
D-75179 Pforzheim
Fon: +49 (0)7231 58 678 - 0
Fax: +49 (0)7231 58 678 - 111
email: avionics@hensoldt.net
www.hensoldt-avionics.com

24.07.2024

Quotation 803549

Page 1 of 2

Customer:	11320	Inhouse contact:	Linda Oechsle
Your inquiry:	MMA-24-1052	Phone / -Fax:	+49 (0) 7231 58678 504 / -111
from:	17.06.2024	Email:	linda.oechsle@hensoldt.net
Your VAT reg. no.:		Project:	10/ REP.7158

Item	Product	Revision	Quantity	Unit price EUR	Total price EUR
	<u>Fault Diagnostic and Result Investigation</u>				
	The complete function test as part of the incoming inspection showed, that the PCMCIA slot B does not work. A test with a spare PCMCIA board showed no further errors. An additional 4h endurance test showed no failures or self reboot of the DMG.				
	<u>Result</u>				
	BIOS battery has to be replaced. PCMCIA slot B has to be replaced.				
1	202.002-012		1 pc.	551.58	551.58
	Service - Handling Fee (Hardware)				
	RN6 - EN5 P/N 210.001-001 S/N RN6-00733				
	202.001-008		8 h	202.63	1,621.04
	Repair/Maintenance				
	Processes				
	254.018-007		1 pc.	149.50	149.50
	Platine mit PCMCIA-Laufwerk für RN6				
	268.03-05		1 pc.	50.00	50.00
	3,6V Mignon Lithium-Thionylchlorid				
				Carry over	2,372.12

Item	Product	Revision	Quantity	Unit price EUR	Total price EUR
				Carry over	2,372.12
	Minimum Order Quantity: 10 pc.				
			Total		2,372.12

Validity: To 30.09.2024
Delivery terms: Ex Works
Payment: Upon receipt of invoice within 30 days net.
Reverse Charge

Best regards,

Linda Oechsle
HENSOLDT Avionics GmbH

The effective version of our General Terms and Conditions is applicable.
<https://www.hensoldt-avionics.com/?q=gtc>