

Blade Repair Workshop Inspection Report

<i>Customer:</i>	Galaxy Aerospace
<i>Part Number:</i>	4F6210A00132
<i>Serial Number:</i>	BAT4996
<i>TTSN:</i>	1176.54
<i>Date:</i>	15 March 2023

Discrepancy:


- Trailing edge fairing found damage

Inspection findings:

- **Trailing edge fairing found crack**

Corrective action

- Trailing edge fairing to be replaced





- **Swept tip erosion shield found edge void**
 - Corrective action
 - Edge void to be sealed
- **Trailing edge cover to be replaced to facilitate for static balance**
- **Paint touch up required at all necessity area.**

Name: Peir Ler

Date: 15 March 2023