



Dorfstrasse 8
CH-8311 Brütten
ZH, Switzerland

Tel: +41 52 345 3605
Fax: +41 52 345 3606
E-mail: kevin@alpine.aero

Component Teardown Report and Quotation

Customer Galaxy Aerospace PROCUREMENT TEAM E-mail procurement@galaxyaerospace.my	Customer R.O.# MMA-23-7 Work Order # R230919-21	Nomenclature Module, Pitot Static Part Number 418-00475-550	Date 03-10-2023 Serial # 2380
--	--	--	--

Reported discrepancy: Reason for removal: Reason for removal: Airspeed will not follow Baran 2. Mod status: ABCD . Data plate unclear, please confirm #2380 and repair, issue EASA Form 1 with FAA release.

Inspection Findings: Reason of removal confirmed. Major repair including the replacement of the clutch board and pressure seals.

Tech Notes: The following quote is to return the above unit in **repaired** condition. Please advise.

Normal Labor & Parts	EUR	26'050.00
High cost Parts	EUR	0.00
*Misc. charges	EUR	0.00
Total Euros	EUR	26'050.00

*Miscellaneous charges may include freight, hazardous waste, or any charges outside normal parts and labor and are subject to change.

Please advise us of your decision within 5 working days so that repairs may be completed.

Please sign and date your approval prior to faxing or e-mailing this form back to us.

Approximate lead-time for completion after we receive approval: 4-6 weeks

APPROVAL SIGNATURE: _____

DATE: _____

Please sign the above line and return this fax to: +41 52 345 3606

Thank you, Kevin Amey

