

SAFRAN AEROSYSTEMS SERVICES ASIA PTE LTD
SHOP FINDING REPORT
OVERHAULED



No 0000976635

CUSTOMER: GALAXY AEROSPACE (M) SDN BHD

ORDER No: 1100474 / 0051121242

CUSTOMER ORDER: MMA-23-710

RECEIVED DATE: 17-07-23
(DD-MM-YY)

CUSTOMER INSTRUCTION: EASA FORM 1 / FAA 8130-3

RECEIVING

DESCRIPTION: L/H FORWARD FLOAT ASSY

REF AIRCRAFT MANUFACTURER: 216118-0

RECEIVED PART NUMBER: 216118-0

MANUFACTURER:

ARZ141 SAFRAN AEROSYSTEMS COGNAC DSE

SERIAL NUMBER: N/A

CAGE CODE: F6101

AMENDMENT: N/A

MANUFACTURING DATE: 01-01-06
(DD-MM-YY)

QUANTITY: 1

REMOVAL DATE: 28-06-23
(DD-MM-YY)

LAST OHL DATE MAR 2021

TSN:

TSO:

TSR:

AIRCRAFT:	REGISTRATION NUMBER:	A/C DELIVERY DATE:
AS365N3	M70-03	UNKNOWN

Maintenance Documentation Reference

Amendment: N/A

Documentation: CMM 25-69-35 Rev.1, MPTA SAO.PSE.CML.21-0216 Rev.B

Work Performed: See Attached Repair Report: 1100474

SB/SIL Performed: SIL 025-69-07 Rev.04

AD Compliance: N/A

Including Balloon P/N: 216064-0, S/N: 118 (DOM: 01-2006)

OTL extension

Reason for Removal

Order Type:

OVERHAUL

Findings

Received flotation assy in packed condition.

Balloon requires replacement as balloon has reached maximum life limit.

The composite angle of the container cracked requires repair as per MPTA SAO.PSE.CML.21-0216.

Manifold tube LH corroded requires replacement.

Braid incoming less requires replacement.

Protector incoming less requires replacement.

Manifold tube sealing washer worn requires replacement.

Qty 04 screw and washer worn requires replacement.

Container sealing washer worn requires replacement.

All others sub-components in acceptable condition.

SHIPPING

SHIPPED PART NUMBER: 216118-0

REF AIRCRAFT MANUFACTURER: 216118-0

SERIAL NUMBER: N/A

AMENDMENT : N/A

DATE: 25-07-23
(DD-MM-YY)

WRITER: Gandhi Radhakrishnan

INSPECTOR:

Signature

Signature

SAFRAN AEROSYSTEMS SERVICES ASIA PTE LTD
SHOP FINDING REPORT
OVERHAULED



No 0000976635

CUSTOMER: GALAXY AEROSPACE (M) SDN BHD

ORDER No: 1100474 / 0051121242

CUSTOMER ORDER: MMA-23-710

RECEIVED DATE: 17-07-23
(DD-MM-YY)

CUSTOMER INSTRUCTION: EASA FORM 1 / FAA 8130-3

Work to be performed & parts to be replaces/Travaux à réaliser & pièces à remplacer
Overhauled with balloons replacement, leak test and folding.

Replacement of parts: Manifold tube LH (Qty: 01), Braid (Qty: 01), Protector (Qty: 01), Manifold tube sealing washer (Qty: 01), Screw (Qty: 04), Washer (Qty: 04), Container sealing washer (Qty: 01), Gasket (Qty: 02), O-ring (Qty: 09), Pin (Qty: 03), Plastic shear rivet (Qty: 16) and Lead seal (Qty: 02).

Remarks

Log card received with float assy.

Customer liability Yes

SHIPPING

SHIPPED PART NUMBER: 216118-0

REF AIRCRAFT MANUFACTURER: 216118-0

SERIAL NUMBER: N/A

AMENDMENT : N/A

DATE: 25-07-23
(DD-MM-YY)

WRITER: Gandhi Radhakrishnan

INSPECTOR:

Signature

Signature