

Quote



Date: 04/02/2024
Quote No.: EASB/QUO1447
Salesperson: Yusnita

EPIC AERO SDN. BHD.

1200688 A
No.B29 Jalan Delta U6/18,
Taman Perindustrian Sunway Subang,
Seksyen U6,40150,Shah Alam,Selangor.
Website : <https://www.epicaero.com.my>

Phone (off):+603-7734 1394
Email : yusnita@epicaero.com.my / mmyusnita@gmail.com
No Daftar CP : B16-2403-32000265

Bill To:

GALAXY AEROSPACE (M) Sdn.
Bhd.
Galaxy Aerospace (M) Sdn Bhd,
Suite 11-14,
Helicopter Centre,
Malaysia International Aerospace
Centre,
Sultan Abdul Aziz Shah Airport,
47200, Subang,
Selangor,
Darul Ehsan.
Website :
www.galaxyaerospace.my
Tel : +603 7734 7226
Fax : +603 7734 7526
Email :
admin@galaxyaerospace.my

Attn : Cik Izzati.

Ship To:

Galaxy Aerospace (M) Sdn Bhd,
Suite 11-14,
Helicopter Centre,
Malaysia International Aerospace
Centre,
Sultan Abdul Aziz Shah Airport,
47200, Subang,
Selangor,
Darul Ehsan.
Website :
www.galaxyaerospace.my
Tel : +603 7734 7226
Fax : +603 7734 7526
Email :
admin@galaxyaerospace.my

Attn : Cik Izzati.

Qty	Description	Unit Price	Total
1	To do NDT Eddy current inspection on Forward Tail Rotor Drive Shaft aircraft M70-02.	MYR1,800.00	MYR1,800.00
1	SST 8%.	MYR144.00	MYR144.00

Total MYR1,944.00

Payment schedule as below :

- Notification of work to be carried out via letter 50% down payment.(works to commence after down payment made and cleared into bank account).
- Upon completion of work 50% balance payment (within 1 month).
- This quotation is valid for 90 days.

Best regards,

Authorised Signature
EASB/FIN/007

YUSNITA MOHAMED YUSOFF
FINANCE EXECUTIVE
EPIC AERO SDN BHD