



Customer Repair Services

Elbit Systems of America
7635 Plantation Road
Roanoke, VA 24019
nvwarranty@elbitsystems-us.com
800-360-6054

Quotation

Return
Authorization: **RNI4642**

Date: 6/27/2023

Sold to: B.M.A. S.R.L.
Address: LARGO AMBA ARADAM, 1
00184 ROME
ITALY,

Attn: MOHD SUMAILI BIN SULAIMAN
Phone: +6013-3089494
Email: sumaili@galaxyaerospace.my

Ship To: Galaxy Aerospace (M) Sdn Bhd
Address: Lot 11-14, MRO Centre, Malaysia International
Aerospace Centre, Sultan Abdul Aziz Shah Airport
Subang, Selangor Darul Ehsan

Bill To: Galaxy Aerospace (M) Sdn Bhd
Address: Lot 11-14, MRO Centre, Malaysia International
Aerospace Centre, Sultan Abdul Aziz Shah Airport
Subang, Selangor Darul Ehsan

See attached Terms and Conditions

Quotation valid for 60 days

Check method of payment for repairs and shipping cost:

Payment by: **Credit Card** ___ or **Purchase Order #** _____

Estimated shipping: **Invoice Customer** ___ or **Customer Shipping Account #** _____

Send signed quotation to nvwarranty@elbitsystems-us.com to authorize Night Vision to proceed with repairs listed above. You will be invoiced or contacted to arrange payment at the time of shipment.

Printed Name: _____

Date: _____

Signature: _____

Export of this product requires an export license from the U.S. Department of State, directorate of defense trade controls, in accordance with international traffic in arms (ITAR), Title 22, Code of Federal Regulations.

Number of Items: 2

Quote Total: \$5770.00



Return Authorization #:

RNI4642

Serial # **9037366**

Part # **4949B4M18HP43-2**

Model # **F4949B4M18HP43**

F4949B4M18H2P43 16-1800 FOM 1.0 MAX

Reason for return blemish right side

Repair needed Customer requested new tube.

Part Number	Description	Quantity	Parts	Labor
9800M18H-2	F9800M18H2, 1600-1800 FOM, 1.0 MAX	1	\$2,635.00	\$0.00
286600-CRSLABOR	CRS LABOR	1	\$0.00	\$250.00
		2	\$2635.00	\$250.00

Price for this item: **\$2,885.00**

Serial # **9037368**

Part # **4949B4M18HP43-2**

Model # **F4949B4M18HP43**

F4949B4M18H2P43 16-1800 FOM 1.0 MAX

Reason for return blemish right side

Repair needed Customer requested new tube.

Part Number	Description	Quantity	Parts	Labor
9800M18H-2	F9800M18H2, 1600-1800 FOM, 1.0 MAX	1	\$2,635.00	\$0.00
286600-CRSLABOR	CRS LABOR	1	\$0.00	\$250.00
		2	\$2635.00	\$250.00

Price for this item: **\$2,885.00**

Quote Total: \$5,770.00